MoDO	r.			-	Fransportation	
				Bridge Inspect	-	
	COUNTY: OZARK	DISTRICT: SE		S: STATBR	FED-ID: 10065	BRIDGE: K08
		***GENERAL STRUCT				***BR
	US160E	# SPANS:			CODE: 36548 JASPER	DATE: 10/24
	BULL SHOALS LK	LANES ON: LANES UNDER:			NGTH: 1,817 FT 0 IN	FREQUENCY: 24
LOG MILE:	P-POSTLOAD	COMPASS DIRECTION:			I SPAN: 181 FT 8 IN DWAY: 24 FT 0 IN	TEAM LEADER: TERR
	: 54.00 MILES	DIRECTION OF TRAFFIC:			CURB: 22 FT 0 IN	INSPECTOR 2: BRAN INSPECTOR 3:
NHS:		FUNCTIONAL CLASS:			D OUT: 24 FT 8 IN	** When calculated interv
BUILT:	: 1951	NBI OWNER:	MODOT		AADT: 1453	G
REHAB:		NBI MAINTAINED:			YEAR: 2023	
	S 19 T 22 R 15 W	MAINTENANCE DISTRICT:			RUCK: 7.4%	
	: 36 34 40.05 (DMS)	MAINTENANCE COUNTY:			AADT: 3051	
LONGITUDE:	: 92 38 50.35 (DMS)	SUB AREA:	/H19	FUTURE AADT	YEAR: 2043	
	FRACTURE C	RITICAL INSPECTION INFO	DRMATION			***INDEPTH INSPECT
DATE:		ONSIBILITY: BRIDGEDIV	CATEGORY: THRU	TRUSS	DATE:	RESPONSIBILITY:
FREQUENCY:			NBI: YES	1110.00	FREQUENCY:	CALCULATED INTERVAL**:
-		SPECTOR 3:	METHOD: A62, E	BUCKET TRK	TEAM LEADER:	INSPECTOR 3:
INSPECTOR 2:	BRANDON SMITH (NTLQ) IN	ISPECTOR 4:			INSPECTOR 2:	INSPECTOR 4:
** When calculated	interval exceeds the frequency, a j	ustification comment per BIRM is requi	red.		** When calculated interval exceed	ds the frequency, a justification comm
	FRACTURF	CRITICAL INSPECTION CON				ΙΝΝΕΡΤΗ ΙΝΩΡΕζ
			MMENTS			INDEPTH INSPEC
			<u>MIMEINTS</u>			<u>INDEFIH INSPEC</u>
		AL INSPECTION INFORMATI				***UNDERWATER INSPEC
DATE:	***SPECIA	AL INSPECTION INFORMATI	ION***	NEL CROSS SEC	DATE: 08/09/2022	***UNDERWATER INSPE
DATE: FREQUENCY: TEAM LEADER: INSPECTOR 2:	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN		ION*** Category: Chani NBI: No	NEL CROSS SEC'	DATE: 08/09/2022 FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	<u>***UNDERWATER INSPE</u> RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3:
FREQUENCY: TEAM LEADER: INSPECTOR 2:	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 ISPECTOR 3: TERRY L SHUNAMON	ION*** Category: Chant NBI: No Method: Emd	NEL CROSS SEC	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	<u>***UNDERWATER INSPE</u> RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3:
FREQUENCY: TEAM LEADER: INSPECTOR 2:	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 ISPECTOR 3: TERRY L SHUNAMON ISPECTOR 4:	ION*** CATEGORY: CHANI NBI: NO METHOD: EMD red.	NEL CROSS SEC'	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	***UNDERWATER INSPE RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4:
FREQUENCY: TEAM LEADER: INSPECTOR 2: ** When calculated i	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju SPEC	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 [SPECTOR 3: TERRY L SHUNAMON [SPECTOR 4: ustification comment per BIRM is requir	ION*** CATEGORY: CHANI NBI: NO METHOD: EMD red.	NEL CROSS SEC	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	***UNDERWATER INSPE RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4: eds the frequency, a justification com
FREQUENCY: TEAM LEADER: INSPECTOR 2: ** When calculated i	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju SPEC	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 ISPECTOR 3: TERRY L SHUNAMON ISPECTOR 4: ustification comment per BIRM is requir	ION*** CATEGORY: CHANI NBI: NO METHOD: EMD red.	NEL CROSS SEC'	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	***UNDERWATER INSPE RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4: eds the frequency, a justification com
FREQUENCY: TEAM LEADER: INSPECTOR 2: ** When calculated i	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju SPEC 022)SEE UNDERWATER WOR Descent and the second s	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 ISPECTOR 3: TERRY L SHUNAMON ISPECTOR 4: ustification comment per BIRM is requir	ION*** CATEGORY: CHANI NBI: NO METHOD: EMD red. TS CTIONS	NEL CROSS SEC'	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	***UNDERWATER INSPE RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4: eds the frequency, a justification com
FREQUENCY: TEAM LEADER: INSPECTOR 2: ** When calculated i (ELSEMJ, 08/11/20	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju SPEC 022)SEE UNDERWATER WORI OTH	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 SPECTOR 3: TERRY L SHUNAMON SPECTOR 4: ustification comment per BIRM is requir MAL INSPECTION COMMENT KSHEET FOR CHANNEL CROSS SEC	ION*** CATEGORY: CHAN NBI: NO METHOD: EMD red. TS CTIONS		FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN ** When calculated interval exce	***UNDERWATER INSPE RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4: eds the frequency, a justification con UNDERWATER INSP OTHER UNDERWA
FREQUENCY: TEAM LEADER: INSPECTOR 2: ** When calculated i (ELSEMJ, 08/11/20	***SPECIA 08/09/2022 RESPO 120 CALCULATED II JESSE ELSEMAN IN ADAM ZENTZ IN interval exceeds the frequency, a ju SPEC 022)SEE UNDERWATER WOR Descent and the second s	AL INSPECTION INFORMATI DNSIBILITY: DIVETEAM NTERVAL**: 109 SPECTOR 3: TERRY L SHUNAMON SPECTOR 4: ustification comment per BIRM is requir CIAL INSPECTION COMMENT KSHEET FOR CHANNEL CROSS SEC	ION*** CATEGORY: CHAN NBI: NO METHOD: EMD red. TS CTIONS	NEL CROSS SEC'	FREQUENCY: 60 TEAM LEADER: JESSE ELS INSPECTOR 2: ADAM ZEN	***UNDERWATER INSPECTOR RESPONSIBILITY: CALCULATED INTERVAL**: EMAN INSPECTOR 3: NTZ INSPECTOR 4: eds the frequency, a justification con UNDERWATER INSP

Page 1

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

)817

BRIDGE INSPECTION INFORMATION*** '24/2023 RESPONSIBILITY: BRIDGEDIV CALCULATED INTERVAL**: 24 RRY L SHUNAMON RRY L SHUNAMON ELEMENT: NO CANDON SMITH (NTLQ) INSPECTOR 4:

erval exceeds the frequency, a justification comment per BIRM is required. **GENERAL INSPECTION COMMENTS**

TION INFORMATION***

CATEGORY: NBI: METHOD:

mment per BIRM is required.

ECTION COMMENTS

PECTION INFORMATION***

Y: DIVETEAM **: 49 3: TERRY L SHUNAMON 4: CATEGORY: DIVE NBI: YES METHOD: SCUBA

comment per BIRM is required.

SPECTION COMMENTS

VATER INSPECTIONS ALCULATED INTERVAL RESPONSIBILITY

METHOD

MODOT		Ν	Iissouri Departmen State Bridge Insj	-	
COUNTY: OZARK	DISTRICT: SH	C	CLASS: STATBR	FED-ID: 10065	BRIDGE: K08
			STRU	CTURE POSTING	
APPROVED CATEGORY: S-9	6 AXLE TRUCKS OVER 33 TO	NS 15 MPH ON B	RIDGE.		
Ton 1: 33	Ton 2:		Ton 3:		
COMMENTS: (LYCZAG1,	02/08/2018)EMAIL CORRESPONDEN	CE, 2/2/2018, MC	DOT		
FIELD CATEGORY: S-9 Ton 1: 33	6 AXLE TRUCKS OVER 33 TO	NS 15 MPH ON B		PROBLEM:	PROBLEM DIRECTIO
COMMENTS:	Ton 2:		Ton 3:	r RODLEM;	FRODLENI DIRECTIO
		*	**GENERAL COMM	ENTS/MAJOR RATED ITEMS***	
GENERAL COMMENTS: (MADSEJ, 11/15	5/2019)10 @ (181') THRU TRUSS SMP	SPANS			
	4-POOR CONDITION	COMMENT		MINOR TO MODERATE DECK EDGE DE	
RATING :	10/21/2021		(LISTEDI, 10/21/2021) DETERIORATION	RATING CHANGE DUE TO MANY MAPS	CRACKS THROUGHOUT SPAN
· .	4-POOR CONDITION	COMMENT		MODERATE TO ADVANCED SECTION LO	OSS AT THE BOTTOM OF THE V
RATING :	12/15/2017		MOST OF THE END FLO	JORBEAMS.	
	6-SATISFACTORY CONDITION	COMMENT		MINOR TO MODERATE CRACKING AND	SPALLING THROUGHOUT A F
RATING :	05/18/2001		(2 F I.) ON ROCK AT PI	ER 5 PER DIVETEAM 2018	
	8-PROTECTED DEVICES STBLE	COMMENT		THE STRUCTURE IS OVER BULL SHOAL	
RATING :	05/18/2001		ABUTMENT SETS ON F	ROCK BLUFF AND BOTH ARE IN GOOD	CONDITION.
	8-STABLE FOR CALCULATED	COMMENT	TS: (ELSEMJ, 08/11/2022)N	NO SCOUR OBSERVED	
RATING : EVALUATION TYPE :	05/18/2001				
ITEM 71] WATERWAY ADEQUACY:	DECK ABOVE FLOOD ELEV	COMMENT	`S:		
RATING :					
[ITEM 72] APPRRDWY ALIGNMENT:		COMMENT	'S: (HULBES1, 11/01/2023)-	-MINOR SPEED REDUCTION REQUIRED	O ON EAST END
RATING :	05/18/2001				
		RAILING		VEMENT COMPONENTS AND R	ATINGS
[ITEM 36A] BRIDGE RAILING RATI			RATING: 05/18/2001	COMMENTS:	
<u>MATERIAL</u> REINFORCED CONCRETE	<u>CONSTRUCTION</u> CURB	<u>DIRECTION</u> BOTH	<u>COMMENTS</u>		
STEEL	CHANNEL-DOUBLE	BOTH			
[ITEM 36B] TRANSITION RAILING RATI	NG: MEETS CURRENT STANDARDS-1		RATING: 12/15/2017	COMMENTS:	
MATERIAL	CONSTRUCTION	<u>DIRECTION</u>	<u>COMMENTS</u>		
GALVANIZED STEEL	THRIE BEAM TO W-BEAM	ALL			
[ITEM 36C] APPROACH RAILING RATI	NG: MEETS CURRENT STANDARDS-1		RATING: 12/15/2017	COMMENTS:	
MATERIAL	<u>CONSTRUCTION</u> W-BEAM	<u>DIRECTION</u> All	<u>COMMENTS</u>		
GALVANIZED STEEL					

Page 2

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

0817

ION:

OUTLETS. NS 4-10 W/ HEAVY DECK EDGE AND CURB OUTLET

E WEB, BOTTOM FLANGE, AND TOP FLANGE THROUGHOUT

FEW OF THE PIER BEAMCAPS. TOP OF FOOTING EXPOSED

FILL SLOPES ARE WELL PROTECTED WITH ROCK AND EAST

MODOT		Ν	Iissouri Department State Bridge Insp	-	tion		
COUN	NTY: OZARK	DISTRICT: SE	CLASS: STATBR	-	FED-ID	: 10065	BRIDGE: K08
[ITEM 36D] RAIL END TRI	EATMENT RATING: MEETS CURREN	NT STANDARDS-1	RATING: 12/15/2017	COMMENTS:			
<u>MATERIAL</u> GALVANIZED STE	EL ENERGY ABSORB		<u>COMMENTS</u>				
APPROAC	H PAVEMENT: *Overall condition ass	igned for each approach pavemenet c	omponent is shown below.				
<u>MATERIAL</u> ASPHALT	<u>CONSTRUCTIO</u> BITUMINOUS M	<u>N</u> <u>DIRECTION</u>	<u>CONDITION*</u>	<u>COMMENTS</u>			
ASPHALI	BITOMINOUS M						
		DRAINAGE, EXPANS	SION DEVICES, BANK	K/SLOPE, AND D	ECK PR	ROTECTIVE CO	DMPONENTS
DECK PROTECTIVE COMPO SERIES TYPE-# MAIN SERIES-1	<u>NENIS:</u> <u>COMPONENT</u> WEARING SURFACE	<u>MATERIAL</u> ASPHALT	<u>Construction</u> Bituminous Ma		IN ESS IN	<u>YEAR APPLIED</u> 2017	<u>MANUFACTURE</u>
<u>COMMENT:</u>	WEARING SOM ACE		bii owiitoos wa	11 11	114	2017	
	DECK PROTECTION	NOTAPPLICABLE	NONE				
<u>COMMENT:</u>							
	MEMBRANE	NOTAPPLICABLE	NONE				
<u>COMMENT:</u>							
DRAINAGE COMPONENTS:							
	<u>COMPONENT</u> DRAINAGE	<u>MATERIAL</u> REINFORCED CONCRETE	<u>CONSTRUCTIO</u> CURB OUTLET		<u>ECTION</u>	<u>COMMENTS</u>	
	DRAINAGE	PVC	MODOT PIPE DRA	1IN			

Page 3 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

X0817

OVERALL CONDITION GOOD

COUNTY: COUNTY: COUNTY: COUNTY: COUNTY: COUNTY: COUNTY: COUNTS: SUB UNIT-# SUB LABEL ABUTMENT-1 COMMENT: COVERED WITH PIER-2 COMMENT:	<u>S:</u> CLO	DISTRICT: SE <u>COMPONENT</u> OSED EXPANSION JOINT	State Brid CLASS: STA <u>MATERIAL</u> STEEL		FED-ID: 10065	BRID	GE: K0817		7:02:52
INSION DEVICE COMPONENT SUB UNIT-# SUB LABED ABUTMENT-1 <u>COMMENT:</u> <u>CONDITION</u> COVERED WITH PIER-2	<u>S:</u> CLO	<u>COMPONENT</u>	<u>MATERIAL</u>		FED-ID: 10005	DNIL	GE: KUOI/		
SUB UNIT-# SUB LABER ABUTMENT-1 COMMENT: CONDITION COVERED WITH PIER-2	CLO			CONSTRUCTION					
CONDITION COVERED WITH PIER-2			SILLL	<u>CONSTRUCTION</u> FLAT PLATE	<u>GAP</u>	<u>YEAR APPLIED</u>	<u>MANUFACTURE</u>	<u>OVERALL CONDITION</u> POOR	
COVERED WITH PIER-2									
		<u>LOCATION 1</u> THROUGHOUT	<u>LOCATION 2</u>	<u>SEVERITY</u> NOT APPLICABLE	<u>COMMENT</u>				
COMMENT:	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>CONDITION</u> COVERED WITH		<u>LOCATION 1</u> THROUGHOUT	LOCATION 2	<u>SEVERITY</u> NOT APPLICABLE	<u>COMMENT</u>				
PIER-3	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
COMMENT:									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-4	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-5	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-6	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-7	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-8	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-9	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
PIER-10	CLO	OSED EXPANSION JOINT	STEEL	FLAT PLATE				POOR	
<u>COMMENT:</u>									
COVERED WITH	MAT	THROUGHOUT		NOT APPLICABLE					
ABUTMENT-11 <u>COMMENT:</u>	CLO	OSED EXPANSION JOINT	ASPHALT	FILLED JOINT					

Page 4 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

8	1	7

MODOT			Missouri Departn State Bridge	nent of Transpo Inspection Rep			
COUNTY: OZ	ARK	DISTRICT: SE	CLASS: STATB		FED-ID: 1006	5	BRIDGE: K08
X/SLOPE PROTECTION COMPONE	NTS:						
	<u>IPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUC</u>			<u>OMMENTS</u>	
BANK I	PROTECTION	ROCK	DEFLECT	TOR	EAST		
			DE	ECK COMPONE	NTS		
	<u>OMPONENT</u>	<u>MATERIAL</u>	CONSTRUC		<u>OMMENTS</u>		
MAIN SPANS-1	DECK	REINFORCED CONCRETE	CAST-IN-PL		MEASUDEMENT	COMMENT	
<u>CONDITION</u> DETERIORATION		<u>LOCATION 1</u> AT OUTLETS	LOCATION 2	<u>SEVERITY</u> MINOR	<u>MEASUREMENT</u>	<u>COMMENT</u>	
EFFLORESCENCE		THROUGHOUT		LIGHT			
TRANSVERSE CRACK	S	THROUGHOUT		MANY			
MAIN SPANS-2	DECK	REINFORCED CONCRETE	CAST-IN-P				
<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
DETERIORATION		AT OUTLETS		MINOR			
EFFLORESCENCE	2	THROUGHOUT		LIGHT			
TRANSVERSE CRACK	8	THROUGHOUT		MANY			
MAIN SPANS-3	DECK	REINFORCED CONCRETE	CAST-IN-PL	LACE			
<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
DETERIORATION		AT OUTLETS		MINOR			
EFFLORESCENCE		THROUGHOUT		LIGHT			
SPALLS		BOTTOM	THROUGHOUT	FEW			
TRANSVERSE CRACK	S	THROUGHOUT		MANY			
MAIN SPANS-4	DECK	REINFORCED CONCRETE	CAST-IN-PL	LACE			
<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
DETERIORATION		AT OUTLETS		MINOR			
EFFLORESCENCE		THROUGHOUT		LIGHT			
TRANSVERSE CRACK	S	THROUGHOUT		MANY			
MAIN SPANS-5	DECK	REINFORCED CONCRETE	CAST-IN-PL	LACE			
<u>CONDITION</u>		LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
DELAMINATION			THROUGHOUT	FEW		<u>COMMENTER I I I</u>	
DETERIORATION		AT OUTLETS		MINOR			
EFFLORESCENCE		THROUGHOUT		LIGHT			
TRANSVERSE CRACK	S	THROUGHOUT		MANY			
MAIN SDANS 6	DECV	DEINEADCED CONCDETE	CAST IN D	LACE			
MAIN SPANS-6 CONDITION	DECK	REINFORCED CONCRETE LOCATION 1	CAST-IN-PL LOCATION 2	LACE <u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT	
						<u>COMMENT</u>	
DETERIORATION EFFLORESCENCE		AT OUTLETS THROUGHOUT		MINOR LIGHT			
TRANSVERSE CRACK	S	THROUGHOUT		MANY			
MAIN SPANS-7	DECK	ΒΕΙΛΙΕΛΒΩΕΝ ΟΛΙΟΡΟΤ	CAST-IN-PL	LACE			
MAIN SPANS-7 CONDITION	DEUN	REINFORCED CONCRETE LOCATION 1	LOCATION 2	LACE <u>SEVERITY</u>	MEASUREMENT	COMMENT	
DETERIORATION		AT OUTLETS		MINOR	MEADUREMENT		
				NUMBER			

Page 5 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

10DOT				Department of Transport		
COUNTY:	OZARK	DISTRICT: S		e Bridge Inspection Rep SS: STATBR	oort FED-ID: 10065	5 BRIDGE: K081
EFFLORESCEN TRANSVERSE CR	ICE	THROUGHOUT THROUGHOUT		LIGHT MANY	TED-1D. 1000.	
<i>MAIN SPANS-8</i> <u>CONDITION</u> DETERIORATIO EFFLORESCEN TRANSVERSE CR	ON ICE	<i>REINFORCEI</i> <u>LOCATION 1</u> AT OUTLETS THROUGHOUT THROUGHOUT	D CONCRETE <u>LOCATION 2</u>	<i>CAST-IN-PLACE</i> <u>SEVERITY</u> MINOR LIGHT MANY	<u>MEASUREMENT</u>	<u>COMMENT</u>
<i>MAIN SPANS-9</i> <u>CONDITION</u> DETERIORATIO EFFLORESCEN SPALLS TRANSVERSE CR	ON ICE	<i>REINFORCEI</i> <u>LOCATION 1</u> AT OUTLETS THROUGHOUT BOTTOM THROUGHOUT	D CONCRETE <u>LOCATION 2</u> THROUGHOU	<i>CAST-IN-PLACE</i> <u>SEVERITY</u> MINOR LIGHT Г FEW MANY	<u>MEASUREMENT</u>	<u>COMMENT</u>
<i>MAIN SPANS-10</i> <u>CONDITION</u> DETERIORATIO EFFLORESCEN TRANSVERSE CR	ON ICE	<i>REINFORCEI</i> <u>LOCATION 1</u> AT OUTLETS THROUGHOUT THROUGHOUT	D CONCRETE <u>LOCATION 2</u>	<i>CAST-IN-PLACE</i> <u>SEVERITY</u> MINOR LIGHT MANY	<u>MEASUREMENT</u>	<u>COMMENT</u>
				SUPERSTRUCTURE CON		
<u>SERIES TYPE-#</u> MAIN SERIES-1	<u>SPAN TYPE</u> SIMPLE SPAN	<u>MATI</u> STI		<u>CONSTRUCTION</u> THRU TRUSS	<u>LABEL</u>	<u>COMMENTS</u> (MADSEJ, 11/15/2019)SEE THE FR ACCOUNTING OF ALL TRUSS MEM
						ACCOUNTING OF ALL TROSS MEM
<u>SPAN</u> MAIN SPANS-1 <u>CONDITION</u>	COMPOSITE INDIANON-COMPOSI		<u>WEATHERING STEEL</u> NO <u>LOCATION 2</u>	<u>COMMENTS</u> <u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
MAIN SPANS-1	NON-COMPOS	ITE 181 FT 8 IN <i>Location 1</i>	NO		<u>MEASUREMENT</u> <u>MEASUREMENT</u>	<u>COMMENT</u> <u>COMMENT</u>
MAIN SPANS-1 <i>CONDITION</i> MAIN SPANS-2	NON-COMPOS	ITE 181 FT 8 IN <u>LOCATION 1</u> ITE 181 FT 6 IN <u>LOCATION 1</u>	NO <i>LOCATION 2</i> NO	<u>SEVERITY</u>		
MAIN SPANS-1 <u>CONDITION</u> MAIN SPANS-2 <u>CONDITION</u> MAIN SPANS-3	NON-COMPOSI NON-COMPOSI NON-COMPOSI	ITE 181 FT 8 IN LOCATION 1 ITE 181 FT 6 IN LOCATION 1 ITE 181 FT 6 IN LOCATION 1 ITE 181 FT 6 IN LOCATION 1	NO <u>LOCATION 2</u> NO <u>LOCATION 2</u> NO	<u>SEVERITY</u> <u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
MAIN SPANS-1 <u>CONDITION</u> MAIN SPANS-2 <u>CONDITION</u> MAIN SPANS-3 <u>CONDITION</u> MAIN SPANS-4	NON-COMPOSI NON-COMPOSI NON-COMPOSI NON-COMPOSI	ITE 181 FT 8 IN LOCATION 1 ITE 181 FT 6 IN LOCATION 1	NO <u>LOCATION 2</u> NO <u>LOCATION 2</u> NO <u>LOCATION 2</u> NO	<u>SEVERITY</u> <u>SEVERITY</u> <u>SEVERITY</u>	<u>MEASUREMENT</u> <u>MEASUREMENT</u>	<u>COMMENT</u> <u>COMMENT</u>
MAIN SPANS-1 <u>CONDITION</u> MAIN SPANS-2 <u>CONDITION</u> MAIN SPANS-3 <u>CONDITION</u> MAIN SPANS-4 <u>CONDITION</u> MAIN SPANS-5	NON-COMPOSI NON-COMPOSI NON-COMPOSI NON-COMPOSI NON-COMPOSI	ITE 181 FT 8 IN LOCATION 1 ITE 181 FT 6 IN LOCATION 1	NO <u>LOCATION 2</u> NO <u>LOCATION 2</u> NO <u>LOCATION 2</u> NO <u>LOCATION 2</u>	<u>SEVERITY</u> <u>SEVERITY</u> <u>SEVERITY</u> <u>SEVERITY</u>	<u>MEASUREMENT</u> <u>MEASUREMENT</u> <u>MEASUREMENT</u>	<u>COMMENT</u> <u>COMMENT</u> <u>COMMENT</u>

Page 6 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

0817

FRACTURE CRITICAL ELEMENT TABLE FOR DETAILED EMBER CONDITIONS.

MODOT			Missouri Departmen State Bridge Ins	-	-		
COUNTY:	OZADV	DICTDICT. CF	0	pection Re	-	. 100/5	DDIDCE, VAG
	UZAKK	DISTRICT: SE	CLASS: STATBR		FED-IL	D: 10065	BRIDGE: K08
MAIN SPANS-8	NON-COMPOSITI	E 181 FT 6 IN	NO				
MAIN SPANS-8 CONDITION	NON-COMPOSITI	LOCATION 1	LOCATION 2	SEVERITY	MEASURE	EMENT COMME	NT
			<u></u>	<u>52, 1111</u>			<u></u>
MAIN SPANS-9	NON-COMPOSITI	E 181 FT 6 IN	NO				
<u>CONDITION</u>		LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASURE</u>	EMENT <u>COMME</u>	<u>NT</u>
MAIN SPANS-10	NON-COMPOSITI		NO				
<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASURE</u>	<u>EMENT</u> <u>COMME</u>	<u>NT</u>
			444011D0TD110	TUDE CON		- 4 -	
SUBSTRUCTURE	SKEW LENG	TH MATERIAL	***SUBSTRUC CONSTRUCTION	LABEL	<u>TPONENTS""</u> <u>COMMENTS</u>		
ABUTMENT-1	<u>31 FT</u>			2.1000		<u> </u>	
	<u>CONDITION</u>	LOCATION 1	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED COM	<u>IPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>				
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE		~		~~~~~
<u>(</u>	<u>CONDITION</u>	LOCATION 1	<u>LOCATION 2</u>		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
VED	SEALED	THROUGHOUT THROUGHOUT			EPOXY		
STRAIGHT WINGS	FICAL CRACKS	REINFORCED CONCRETE	CAST-IN-PLACE		FEW		
	CONDITION	LOCATION 1	LOCATION 2		<u>SEVERITY</u>	MEASUREMENT	COMMENT
FOOTING		REINFORCED CONCRETE	SPREAD				
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BACKWALL		REINFORCED CONCRETE	CAST-IN-PLACE				
<u>(</u>	<u>CONDITION</u>	LOCATION 1	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT			EPOXY		
EXPANSION BEAR		STEEL	ROCKER		GEVEDITV		COMMENT
<u>(</u>	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PIER-2	<i>32 FT</i>	0 IN REINFORCED CONCRET	TE MULTIPLE COLUMN				
	CONDITION	LOCATION 1	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED COM	IPONENT	<u>MATERIAL</u>	<u>CONSTRUCTION</u>				
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE				
<u>(</u>	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT			EPOXY		
	FICAL CRACKS	THROUGHOUT	CACT IN DI ACE		FEW		
COLUMN	<u>CONDITION</u>	REINFORCED CONCRETE <i>LOCATION 1</i>	CAST-IN-PLACE <i>LOCATION 2</i>		<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
	LAMINATION	THROUGHOUT	LOCAHON 2		<u>SEVENIII</u> FEW	MEASUREMENT	
	LORESCENCE	THROUGHOUT			MEDIUM		
	FICAL CRACKS	THROUGHOUT			LARGE		
FOOTING		REINFORCED CONCRETE	SPREAD				
<u>(</u>	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM		REINFORCED CONCRETE	CAST-IN-PLACE		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		601 <i>(</i> 1/7)-7
	<u>CONDITION</u>	LOCATION 1	LOCATION 2		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BEAR		STEEL	ROCKER		CEVEDITY	MEACUDEMENT	COMMENT
<u>G</u> FIXED BEARING	<u>CONDITION</u>	<u>LOCATION 1</u> STEEL	<u>LOCATION 2</u> DEDESTAL (DOTAT		<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	<u>CONDITION</u>	STEEL LOCATION 1	PEDESTAL(ROTAT <u>LOCATION 2</u>	,	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
l l l l l l l l l l l l l l l l l l l	· · · · · · · · · · · · · · · · · · ·						C C ITITITITI I

Page 7 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

<u>K0817</u>

DOT			Missouri Department of Tr	-		
			State Bridge Inspection	1 Report		
COUN	ГY: OZARK	DISTRICT: SE	CLASS: STATBR	FED-I	D: 10065	BRIDGE: K08
PIER-3		32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<u>ASSOCIATED</u>	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE	~~~~~~		~~~~~
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT		EPOXY		
	VERTICAL CRACKS	THROUGHOUT		FEW		
COLUMN	<u>CONDITION</u>	REINFORCED CONCRETE <u>LOCATION 1</u>	CAST-IN-PLACE <u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING		REINFORCED CONCRETE	SPREAD	<u>SEVENIII</u>	MEASUKEMENT	COMMENT
roonna	<u>CONDITION</u>	LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM	CONDITION	REINFORCED CONCRETE	CAST-IN-PLACE	<u>SEVERITT</u>	MEASUREMENT	COMMENT
	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARI		STEEL	PEDESTAL(ROTATING)	<u>SEVERITT</u>	MEASUREMENT	COMMENT
TIAED DEAR	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
EXPANSION E		STEEL	ROCKER	<u>SEV ERITT</u>	MENSOREMENT	COMMENT
LAIANGION L	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
				<u>SH</u> , <u>BRITT</u>		
PIER-4		32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
1 11211-7	CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
ASSOCIATED		MATERIAL	CONSTRUCTION			
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE			
	CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
	SEALED	THROUGHOUT		EPOXY		
•	VERTICAL CRACKS	THROUGHOUT		FEW		
COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
	CONDITION	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING		REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SPALLS	COLLISION WALL		FEW		
	VERTICAL CRACKS	COLLISION WALL		OPEN		
FIXED BEARI		STEEL	PEDESTAL(ROTATING)	~		<i>~~~~~</i>
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION E		STEEL	ROCKER	~		<i>~~~~~</i>
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PIER-5		32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN	~		<i>~~~~~</i>
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP	CONDUCTO	REINFORCED CONCRETE	CAST-IN-PLACE			COMPLET
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT		EPOXY		
	VERTICAL CRACKS	THROUGHOUT	CAST IN DI ACE	FEW		
COLUMN	<u>CONDITION</u>	REINFORCED CONCRETE <u>LOCATION 1</u>	CAST-IN-PLACE LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
FOOTING		<u>EUCATION 1</u> REINFORCED CONCRETE	SPREAD	<u>SLVENIII</u>	MLASUREMENT	UIMIMENT
ruuting	CONDITION	LOCATION 1	SPREAD LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
	EXPOSED	TOP	LOCATION 2	<u>SEVERITI</u> MODERATE	MEASUREMENT	
WEB BEAM	LAFUSED	REINFORCED CONCRETE	CAST-IN-PLACE	MODEKALE		
	CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
	CONDITION		LUCATION 2		III ISUNEIVIEIVI	COMMENT

Page 8 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

<u>K0817</u>

MODOT		Missouri Department of Tra	-		
		State Bridge Inspection	Report		
COUNTY: OZARK	DISTRICT: SE	CLASS: STATBR	FED-l	ID: 10065	BRIDGE: K08
DIAGONAL CRACKS	WALL		FEW		
VERTICAL CRACKS	AT WALL		FEW		
FIXED BEARING CONDITION	STEEL <u>LOCATION 1</u>	PEDESTAL(ROTATING) <i>LOCATION 2</i>	<u>SEVERITY</u>	MEASUREMENT	COMMENT
EXPANSION BEARING	STEEL	ROCKER	<u>SEVENITI</u>	MEASOREMENT	
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<i>PIER-6</i> 32 <i>FT</i>	0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED COMPONENT	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			COMUENT
<u>CONDITION</u>	LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
SEALED VERTICAL CRACKS	THROUGHOUT THROUGHOUT		EPOXY FEW		
COLUMN	REINFORCED CONCRETE	CAST-IN-PLACE	L L VV		
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
FOOTING	REINFORCED CONCRETE	SPREAD			
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARING	STEEL	PEDESTAL(ROTATING)			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BEARING	STEEL	ROCKER			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PIER-7 32 FT CONDITION	0 IN REINFORCED CONCRETE LOCATION 1	MULTIPLE COLUMN LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
ASSOCIATED COMPONENT	MATERIAL	CONSTRUCTION	<u>SEV EKITT</u>	MLASUKLMLI	COMMENT
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
SEALED	THROUGHOUT		EPOXY		
VERTICAL CRACKS	THROUGHOUT		LARGE		
COLUMN	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING	REINFORCED CONCRETE	SPREAD			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARING	STEEL	PEDESTAL(ROTATING)	SEVEDITV	MEASUDEMENT	COMMENT
<u>CONDITION</u> EXPANSION BEARING	<u>LOCATION 1</u> STEEL	<u>LOCATION 2</u> ROCKER	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EAFAINSION BEARING CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
condition	<u>Boennoivr</u>	ECCHIICIT 2	<u>SEV EMITI</u>		COMULIVI
PIER-8 32 FT	0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
ASSOCIATED COMPONENT	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
SEALED	THROUGHOUT		EPOXY		
VERTICAL CRACKS	THROUGHOUT		LARGE		
COLUMN	REINFORCED CONCRETE	CAST-IN-PLACE			
Design No = K0817					

Page 9 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

DOT			Missouri Department of Tra	-		
			State Bridge Inspection	ı Report		
COUN	ΓY: OZARK	DISTRICT: SE	CLASS: STATBR	FED-l	D: 10065	BRIDGE: K0
	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING		REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARI		STEEL	PEDESTAL(ROTATING)	~~··~~		
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION B		STEEL	ROCKER			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PIER-9		32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
	CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
ASSOCIATED	COMPONENT	MATERIAL	CONSTRUCTION			
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE			
	CONDITION	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT		EPOXY		
	VERTICAL CRACK			LARGE		
COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING		REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARI		STEEL	PEDESTAL(ROTATING)			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION B		STEEL	ROCKER			COMUENT
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PIER-10		32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
	CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
ASSOCIATED	COMPONENT	MATERIAL	CONSTRUCTION			
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE			
	CONDITION	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	THROUGHOUT		EPOXY		
	VERTICAL CRACK			LARGE		
COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING	CONDUCTON	REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEAM	CONDITION	REINFORCED CONCRETE	CAST-IN-PLACE			COMMENT
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION B		STEEL	ROCKER	<u>CEVEDITV</u>	MEASUDEMENT	COMMENT
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARI	NG <u>CONDITION</u>	STEEL <u>LOCATION 1</u>	PEDESTAL(ROTATING) <u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BUTMENT-11		29 FT 2 IN REINFORCED CONCRETE	NON-INTEGRAL			
	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP	CONTRACTOR -	REINFORCED CONCRETE	CAST-IN-PLACE			COMPUT
	CONDITION	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT

Page 10 This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

K0817

		Missouri Department of Tr	ansportation			
MoDOT		State Bridge Inspection	n Report			
COUNTY: OZAR	RK DISTRICT: SE	CLASS: STATBR	-	D: 10065	BRIDGE: K0817	
VERTICAL C STRAIGHT WINGS <u>CONDIT</u> BACKWALL <u>CONDIT</u>	REINFORCED CONCRETE <u>LOCATION 1</u> REINFORCED CONCRETE	CAST-IN-PLACE <u>LOCATION 2</u> CAST-IN-PLACE <u>LOCATION 2</u>	FEW <u>SEVERITY</u> <u>SEVERITY</u>	<u>MEASUREMENT</u> <u>MEASUREMENT</u>	<u>COMMENT</u> <u>COMMENT</u>	
FIXED BEARING <u>CONDIT</u>	STEEL <u>LOCATION 1</u>	PEDESTAL(ROTATING) <u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
		OVER/UNDER ROUTES CLE	ARANCE INFOR	MATION		
<u>LEARANCES OVER DECK</u> <u>VERTICAL CLEARANCE TYPE**</u> ACTUAL	**NOTE: Vertical clearances for permitting purposes are taken VALUE DIRECTION DATE 15 FT 4 IN 06/27/201	a as 2 inches less than the actual field measured clearance <u>COMMENT</u>				
<u>LEARANCES UNDER BRIDGE</u> RECORD <u>#</u> <u>ROUTE</u>	**NOTE: Vertical clearances for permitting purposes are taken <u># LANES</u> <u>DIRECTION OF TRAFFIC</u>			L CLEARANCE	<u>UR-ID</u>	
VERTICAL CLEARANCE TYPE**	VALUE DIRECTION DATE	<u>COMMENT</u>				
		***STRUCTURE PAINT	- INFORMATION	***		
CONDITION: VERY GOOD	RUST AMOUNT : 9=.03% OF SURF	***STRUCTURE PAINT		***		
CONDITION: VERY GOOD ORIGINAL PAIN	<u>VT</u> <u>CON</u>	FACE RUSTED STEEL TO TRACT REPAINT	NS : 1,122		DEPARTMENT REPAINT	-
	<u>NT</u> <u>CON</u> PAINT TYPI NAMI PAINT COLOI PAINT YEAI	FACE RUSTED STEEL TO TRACT REPAINT E : G SYSTEM E : ZINC/EPOXY/ACRYLIC R : BROWN	NS: 1,122 PAINT TY NA PAINT COL PAINT YI	YPE : ME : .OR :	MANUF	<u>F</u> FACTURE : ACE PREP :
ORIGINAL PAIN PAINT TYPE : NAME : PAINT COLOR : PAINT YEAR :	<u>NT</u> <u>CON</u> PAINT TYPI NAMI PAINT COLOI PAINT YEAI	FACE RUSTED STEEL TO TRACT REPAINT E : G SYSTEM E : ZINC/EPOXY/ACRYLIC R : BROWN R : 2016	NS: 1,122 PAINT TY NA PAINT COI PAINT YI M	YPE : ME : .OR : ZAR :	MANUF	FACTURE :
ORIGINAL PAIN PAINT TYPE : NAME : PAINT COLOR : PAINT YEAR :	<u>NT</u> <u>CON</u> PAINT TYPI NAMI PAINT COLOI PAINT YEAI	FACE RUSTED STEEL TO TRACT REPAINT E : G SYSTEM E : ZINC/EPOXY/ACRYLIC R : BROWN R : 2016 S : 12	NS: 1,122 PAINT TY NA PAINT COI PAINT YI M	YPE : ME : .OR : ZAR :	MANUF	FACTURE :

August 07, 2024 7:02:52AM

0817

·ID

NT REPAINT

MODOT		Missouri Department of Transportation State Bridge Inspection Report						
COUNT	FY: OZARK	DISTRICT: SE	CLASS: STAT	BR	FI	BRIDGE: K08		
<i>RESPONSIBILITY</i> DISTRICT SPECIAL DISTRICT SPECIAL REGIONAL	<i>LOCATION</i> ROADWAY SURFACE SEE COMMENT SUPER-TRUSS	<i>ITEM</i> REPAIR CONCRETE > 50 SF REPLACE JOINTS REPAIR SECT LOSS IN MEMBR	<i>CATEGORY</i> DECK DECK SUPERSTRUCTURE	PRIORITY 2 2 2			15)REPLACE JOINTS OVE 15)REPAIR SECTION LOSS	
			***UT	TILITY ATTA	CHMENTS*	***		
<i>UTILITY</i> ELECTRIC TELEPHONE	OWNER	<i>METHOD M</i> HANGER HANGER	EASUREMENT TYPE	VALUE	NUM. 4 1	(PRINCH, 09/	<i>CACHMENT COMMENT</i> 25/2002)ON SOUTH SIDE 0/15/2003)PHONE LINE AT	
			PROGR	AM NOTES	INFORMAT	ION		
YEAR PROJECT # 2025 9P3728 2016 9P3024	MONTH LET YEAR LE 1 2025 0 0	<u>I</u> <u>ITEMS</u> OTHER REPAINT, SUPERSTRUCTURE F	REPAIR, WEARING SURFAC	E		COMMENT (BRAWLK1, 03/	10/2022)BRIDGE WASHING	
*:	**COMPUTER GENERA	TED RATINGS AND DEFIC	CIENCY ITEMS***				***ADVANCE	
NOTE: The items listed in this s	section are updated whenever con	mputer edits are ran on a structure aft	er the inspection updates hav	ve been entered in	n to TMS.	SIGN #	SIGN TYPE	
<u>Rated Item</u> [Item 67] Structure Evaluation [Item 68] Deck Geometry Ratin [Item 69] Underclearance: Sufficiency Rating: Deficiency:	Rating: 4-MEETS MINI ag: 2-BASICALLY N-NOT A	<u>Rating</u> IMUM TOLERABLE I INTOLRBLE REQ APPLICABLE I7.9% JCTURAL	Rating Date 1/16/2018 3/6/2024 5/18/2001 10/25/2021 1/16/2018			1		
Funding Eligibility:]	FULL					***OUTFALL INS	
Estimated New Structure Leng Estimated Structure Cost: Estimated Total Project Cost: Year of Cost Estimate:	\$17 \$26	49 FT. ,570,970 ,356,455 2024				# OUTFALLS: STATUS: NOTES:	Ι	
generalized to use NBI items to co	ome up with a new structure leng	er generated using algorithims in the oth and width to calculate a new area of the from these numbers once site spe	which is taken times a repres					

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

August 07, 2024 7:02:52AM

0817

VER ALL PIERS TO PROTECT FLOOR BEAMS AND PIER CAPS DSS IN FLOOR BEAMS (WEBS AND/OR FLANGES) AT PIERS 2, 4, 6,

E ATTACHED TO NORTH SIDE & POWER LINES ATTACHED TO

NG

CED SIGN INFORMATION*** PROBLEM

PROBLEM DIRECTION

NSPECTION INFORMATION***

INSPECTOR: DATE:



Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

NBI STATUS : T SUBMITTAL YEAR : 2024 ON INFORMATION JITE CARRIED 'ON' STRUCT INLINE 50 CAPPLICABLE 400 E 30007806 400 F					
ON INFORMATION JTE CARRIED 'ON' STRUCT INLINE 50 F APPLICABLE 160 E					
UTE CARRIED 'ON' STRUCT INLINE 50 Γ APPLICABLE 160 E					
INLINE 50 F APPLICABLE 160 E 5					
50 Γ APPLICABLE 160 E 5					
50 Γ APPLICABLE 160 E 5					
FAPPLICABLE 160 E					
160 E					
0007806					
FREE ROAD					
RURAL MINOR ARTERIAL					
NOT A DEFENSE HWY					
Γ ON NHS					
FAPPLICABLE					
STRUCTURE TRAFFIC INFORMATION					
i i i i i i i i i i i i i i i i i i i					
AY TRAFFIC					
TRIC INFORMATION					
. 6 In.					
miles					
. 11 In.					
Degrees					
. 12 In.					
. 12 In. Ft. 9 In.					
řt. 9 In.					
řt. 9 In. 5 Ft. 11 In.					
řt. 9 In. 5 Ft. 11 In. 0 In.					
řt. 9 In. 5 Ft. 11 In. 0 In. 0 In.					
C					

Design_No = K0817 and Inventory_Appraisal_Submittal_Year = 2024

Page: 1


This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.




Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet


COUNTY: OZARK BRIDGE: K0817 2 RECORD TYPE: ROUTE CARRIED 'ON' STRUCT	REVIEW STATUS :APPROVEDNBI STATUS :TRUN DATE :3/15/2024SUBMITTAL YEAR :2024					
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION					
31Design LoadH 1541Structure StatusPOSTED FOR LOAD63Oper. Rating Meth.LOAD FACTOR64Operating Rating35 Tons.65Inventory Rating MethLOAD FACTOR66Inventory Rating21 Tons.70Bridge Posting Code0.1-9.9% BELOW	43A Main Struc. Mat type STEEL 43B Main struc Constr. Type TRUSS - THRU 45 # of Main Spans 10 44A Appr Struc. Mat type 000 44B Appr Struc. Cnstr. type 000 46 # of Approach Span 0 107 Deck Mat/Constr. 1 CONCRETE CIP					
PROPOSED IMPROVEMENT INFORMATION	108A Wear Surf Mat/Constr. 6 BITUMINOUS 108B Membrane Mat/Constr. 0 NONE					
Sufficiency Rating 17.9 Percent Deficiency Rating STRUCTURAL Funding Eligibility FULL 75A Proposed Work REPLACEMENT SUBSTND LOAD	108C Deck Protect Mat/Constr. 0 NONE CONDITION RATING INFORMATION 58 Deck Cond. Rating 4					
75BWork Done ByContract76New Struc Length1,817 Ft. 7 In.94Struc Improve Cost\$ 17,571,00095Roadway Improve Cost\$ 1,757,000	59Superstructure Cond. Rating460Substructure Cond. Rating661Channel /Channel Protection Cond. Rating862Culvert Cond. RatingN					
96 Total Project Cost \$ 26,356,000						
97 Year of Cost Estimates 2024 APPRAISAL RATING INFORMATION	INSPECTION INFORMATION 90 Gen. Insp Date 10 / 23 91 Gen. Insp. Frequency 24 Months					
36ABr. Rail App. RatingDOES NOT MEET ACCEPT STND36BTransition Rail App. RatingMEETS ACCEPTBLE STND36CApproach Rail App. RatingMEETS ACCEPTBLE STND36DRail End Treat. App. RatingMEETS ACCEPTBLE STND67Struc Eval App. Rating468Deck Geometry App. Rating2	91 Gen. Insp. Frequency 24 Months 92A Frac. Critical Inspection Y Months 24 93A Frac. Critical Insp. Date 10 / 23 10 / 23 92B Underwater Inspection Y Months 60 93B Underwater Insp. Date 8 / 22 92C Special Inspection N Months 93C Special Inspection Date V Months 93C Special Inspection Date					
69 Underclearance App. Rating N	BORDER BRIDGE INFORMATION					
71Waterway Adeq. App. Rating872Approach Road App. Rating6113Scour Assess App. Rating8	98 Neighboring State Code 98B Neighboring State % Respon 99 Neighboring State Struc. No.					
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION					
Approved Posting Category S-9 Ton1 Ton2 Ton3	Field Posting Category S-9 Ton1 Ton2 Ton3					
Tonnage Values for Posting Sign 33	Tonnage Values for Posting Sign 33					
General Text for Posting Sign 6 AXLE TRUCKS OVER 33 TONS 15 MPH ON BRIDGE.	General Text for Posting Sign 6 AXLE TRUCKS OVER 33 TONS 15 MPH ON BRIDGE.					
Design_No = K0817 and Inventory_Appraisal_Submittal_Year = 2024 Page:	2					


This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.




r Forsten, surface In 1997, 2011










m











MISSOUR! STATE HIGHWAY DEPARTMENT





DETAILS OF INTERIOR BENTS NO. 2, 3.4, 5, 6, 7, 8 & 9

ny.									C	CMPLET	ΞB	ILL	OF RE	INF (PRCING	2
.9	NO.	size	Length	Mork	Location	NO.	Size	Length	Mork	Locotion	No.	size	Longin	Morik	location	Ĺ
		SUP	ERSTA	RUCT	URE	5	UPE	R STR.	(00	ntal	END	BE	V75 M	0.1 €	(control)	Į.
	4	2.0	12'-6"	RI	Roil	28	5-6	9'-6'	W5	Web	11	29	31-0	U4	Colismo	Ĺ
	416	2.4	5"	R2.	Roil	8	200	15'- 0"	WG	Web	G	24	30-6-	65	Column	Ĺ
	252	2.4	7-3-	R3	SUD PUSI	9		2:-6"	w9	W65	13	4%	32-0-	06	Coiumn	
	184	2."0	3'-9"	RØ	Post	9	8-4	3'-0"	WIO	Web	7	5.0	31-6-	07	Column	
Í	3200	3.0 p	18"	<i>R5</i>	Bolusters	1152	2"0	7:6"	BI	Girder	G	20	81.61	V8	Column	Ĺ
	1	źź	11'-3*	RG	Roil	.90	1200	29.3	<i>B2</i>	Circler	G	ŹŚ	10-5	Vg	Column	Ĺ
i	2	20	10'-3"	R7	Fioil	:08	12 0	50'-0"	83	Girder	6	2.4	11-00	210	Coiumn	
	8	Ź*\$	8-5-	R8	Roil	72	12"0	45-6	34	Girder	6	270	12:-6-	111	Column	Ĺ
	4	\$-\$	11-6	R9	Roit	.108	15-0	20-0-	35	Girder	ω	\$~¢	6-3-	D!	Fcotina	
i	4	\$°¢	9'-9"	RIO	.90,1	90	1200	29.9	56	Girder						1
	So	2"0	12400	RII	Reil						INTER		<i>BENTS</i> A	02,3	4,5.G,7,889	
	.56	ć~3	121-3"	R/2	Roil						20	\$ 6	81-9-	GI	30000	
	56	ź-¢	10-9-	R/3	Fori		END	BENTS	1.10. 1	8.10	88	2"\$	2.'-6'	G2	Beam	
	50	ž.4	11-0	RIA	2011	16	24	18:0"	1.1	Wing	32	3-0	18:-2	63	Bearn	
ĺ	Δ	±r≠	9'-6"	R15	Ruil	2.	3%	33'-9"	H2	Wing	48	89	10'-9	G4	Beam	İ.
	Δ	Ź"¢	11	RIG	Roil	20	1"\$	26-9	<u>8</u>	Beom	-48	2.0	12:50	65	Beam	
	8	1.0	8'-6"	RM	Roil	8	÷ 9	2.3'-9'	H.2	Beam	48	80	13-6-	66	Beom	
	8	2-6	10'-6'	R18	Roil	16	#"¢	23'-6'	H5	Beam	96	3.	9'-3'	F1	Hounch	
	4	2.0	:0'-9"	R19	Roil	IC	3-4	28'-3'	HG	Beam	32	24	15-6.		Hounch	1
	4	Ź"¢	121-3-	R20	Raii	12	:**	12'-0'	47	Beam	64	2.0	8'-6"	F.S.	Hounch	ł
	12	ź"\$	6'-9"	R21	End Post	3	2"\$	33-0-	нз	Wing	16	8°\$	17-6	PI	Column	
ĺ	12	2"¢	6'-0"	222	Ent Fosi		L				307	450	10-9-	P2	Column	ł
						12	2"0	9'-6'	11	Hing	24	8"0	18-6		Column	ł
						:0	2%	15-6'	12	Col. 5.4	40	89	18'-0"	.20	Coligran	ļ
	6	8 4	26'-3"	CI	CURD	10	<u> z</u> "ø	17:0	1/3	Col. 3:"1	32	8-5	191-0-	.25	Column	ł
	594	3.4	31-9	<u>C2</u>	CURD	10	3.4	18'-0'	<u> </u>	Coi: Bi:#1	48	8 0	19'-4"	PG	Column	i
	28	3-4	2'-0	C3	CUrb	10	3-4	18'-6"	15	Co! at *10	8	30	20-0	27	Column	ł
	6	8 4	23'-3'	CA	CURB	10	2.0	19'-6'		Col. 3± "10	13	8.0	20'-6'	28	Column	ł
	84	2.4	25'-3"	<i>c5</i>	CUrb	10	3%	20.0		Col. B-3;0	<u> </u>	3.0	21.0	,29	Coiumn	ł
	G	81	22'-6"	60	CUrb	16	3.4	9'-3'	.=1	Hounch			-			1
	G	ê'\$	26'-3"	C7	CURD	4	3%	10'-6'	-2	Hounch	128	214	13'-9'	18	Beom	+
				i		2	24	11-0	F3	Hounch	136	20	12-9	119	danm_	ì
	496	80	27'-6"	51	5165	· ·	<u> </u>	i			128	7.0	2-9-	00		1
•	846	8.0	25'-0"	52	5100	6	24	16-6	71	Wing	;92	8"\$	6-9"	02	Footing	┨
	241	8.9	29'-9"	53	5105	4	3%	17-6	72	Wing	<u> ·</u>	1-				ł
	39	8.0	34-9	-	5105	6	1%	16'-6"	73	Wing		! —		<u></u>		ł
	2 8 8	8.0	32 '-6".		5/05	2	34	15'-9'	TΔ	Wing	<u> </u>					ł
	304	3.0	32'-0"	-	5/00	6	34	15'-0"	75	Beam			<u> </u>	i —	<u> </u>	ł
	20	3-0	34'-3"	<u> </u>	5/05	6	3-4	10-0-	76	Beam				<u>i</u> —		1
	52	8-6	7'6"	5/2	5105	6.	5%	12'-6"	77	Beom		<u>ــــــــــــــــــــــــــــــــــــ</u>	<u> </u>		<u>i</u>	1
	96	8.4	6-6	5/3	5/00	3	3%	13'-0"	78	Beam					5-13-0-	
	96	2-0	13.6	wi	neo	3	2.4	14'-9'	79	Beom	Ľ.,	04		_		
	36	2.4	18'-0	W2	WED	32	2.0	12'-9*	11	Beam	. ``	96	F2 -		<u></u>	
	4	8.0	11-6*	W3	Neb	42	2.0	13'-9"	UZ	Beom		10:0	_	3-0	19-7	
	4	5.0	20'-3"	W4	Web	20	2°\$	2'-9"	<u>U</u> 3	Beam	F	F2-			CUT13&	
	9	1.	5:0"	W7	Web								()		ASSHOW	1
	9	8-4	5'-9	₩8	r.ne.5						L					_

č


	DATA FO	A INTERI	OR BENT	s
Bent No.	Dimension	Dimension	No: P2 30-5	Elevation
2	1.15.08	1 2 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1		6
3.	£.15 %		13	6
1	L. 13.40 "-	W/27	14	Le Taxies
5	5 1.00	10 302	14	TUPS.
6	1430 ····	6 24 State	14	1 44.5" 1 44.5"
7	14-16	- C	15	107.00
8	14.50		15	Sertiz
9	14 23 4 /4 23 4 /4 34	4.25 THE	15	1821


WIT June 1841 by J.G Intel June 1941 by C.S TChec Aug. 1941 by RAC


80

Note: This drowing is not to scale. Follow dimensions.


sneet______ನ್ ಎಕ್...









MISSOURI STATE HIGHWAY DEPARTMENT




X


0/







	A second	FED. BOAD STAT DIST. NO. S KO	FED. ANC FISC PICUL NO. TFA AZ SC(SO) 19 Sec. 3-9	K SHEET TOTAL	
	Note: Backwoll at the Structural S has beign installs Backfill beam and wing in place.	tael expension at and floor s	lab has been	poured.	
4-					
n Fac: Face					
24					
m Face Face	Ĩ		• •		
			1 - L	•	
cam face Tace		· .			
	an a				
	RIDGE OVER !				RIVER
ر ا	ABOUT .57 MILES V PROJECT NO. RI SC	(ad) sec. 3-A	AINS STA 375 + 98		
C	ZARK	COUN	AL Y	5	













13


Ta.
























					1.00	
					12.5	
				10		18131
						-
					1.5	- Env
					1	P Parts
					1.1	
					1	1
						1
					1	ie la la
					-	
VER LIT	TLE NORT	H FORK W	HITE R	IVER		
	TLE NORT	H FORK W	HITE R	IVER		
	TLE NORT	h fork w	HITE R	IVER		
)			HITE R	IVER		
)	ST	A	HITE R	IVER		
		A	HITE R	IVER		
)	ST	A				
)	ST	A	HITE R			
WER LIT	ST	a Y	FINIS	НЕD		
D .	ST	A	FINIS			

NF	ORCIN	G STE	EL.	FOR	REV	SION	IS
	Location			ending			
24	Backwill.	New		3=12	1000		
311	Beam	1		205	1113		
112			1		1	-	
13		1	0	12	2		
14	Backwill		1.1	-	Cul 28	3	
25	- 1			UII-UI	3 3	5	
6		Mar Indi	1			- +**	
				184		12 - 4	28
		1	3	1		MIT	-
			1.1.	1 11-3	1	1/3	
	100	2. 32.	1	A St	2	1 3	
3450			14	13-	1	1	÷.,

FED. ROAD STATE FED. AND FISCAL SHEET TOTAL DIST. NO, PROJ. NO, YEAR NO, SHEETS



HALF SECTION NEAR PANEL POINT

HALF SECTION NEAR MID-PANEL POINT

TYPICAL SECTION THRU EXISTING DECK

GENERAL NOTES:

Design Specifications:

2002 AASHTO LFD (17th Ed.) Standard Specifications Bridge Deck Rating = 6

Design Unit Stresses:

Structural Low Alloy Steel (ASTM A709 Grade 50) fy = 50,000 psi

Concrete Protective Coatings:

Protective coating for concrete bents and piers (Epoxy) shall be applied as shown on the bridge plans and in accordance with Sec 711.

Miscellaneous:

Outline of old work is indicated by light dashed lines. Heavy lines indicate new work.

Contractor shall verify all dimensions in field before ordering new material.

High strength bolts, nuts and washers will be sampled for quality assurance as specified in Sec 106.

Fabricated structural steel shall be ASTM A709 Grade 50, except as noted.

Field connections shall be made with $\frac{3}{4}''$ diameter high strength bolts and $\frac{13}{16}''$ diameter holes, except as noted.

Shop-drilled holes in new steel and existing holes in existing steel may be used as a template for field drilling new holes at connection joints with the installation of replacement end portals and sway frames.

Removal and replacement of the end portals and sway frames, as shown in the plans, and any incidental work, complete in place, will be considered completely covered by the contract jump sum price for "Remove and Replace Portals and Sway Frames".

All removed rivets in rehab structure shall be replaced with high strength bolts with flat washer under bolt head and nut (See Special Provisions).

Roadway surfacing adjacent to the bridge ends shall match new bridge wearing surface (Roadway Item).

Traffic Handling:

Traffic to be maintained on structure during construction except structure to be closed during heat straightening and removal and replacement of portals and sway frames. See roadway plans for traffic control.

Detailed	Apr.	2015
Checked	June	2015

Estimated Quantities		
I tem		Total
Removal of Seal Coat	sq. foot	39,981
Ultrathin Bonded Wearing Surface, Type C	sq. yard	4,442
Substructure Repair (Unformed)	sq. foot	70
Repairing Concrete Deck (Half-Soling)	sq. foot	6,000
Full Depth Repair	sq. foot	400
Clean and Epoxy Seal	sq. foot	8,954
Protective Coating-Concrete Bents and Piers (Epoxy)	lump sum	1
Surface Preparation for Recoating Structural Steel	lump sum	1
Field Application of Inorganic Zinc Primer	lump sum	1
Intermediate Field Coat (System G)	lump sum	1
Finish Field Coat (System G)	lump sum	1
Remove and Replace Portals and Sway Frames	lump sum	1
Heat Straightening	lump sum	1

The State estimates there is approximately 98.000 pounds of new steel in the pay item "Remove and Replace Portals and Sway Frames" and that weight is used in preparing the cost estimate for the pay item. Variation may be encountered in the estimated weight but the variation cannot be used for an adjustment in the contract lump sum price.


Structural Steel Protective Coatings:


including curb rails.


for Recoating Structural Steel".


ROUTE 160 FROM ROUTE 5 TO ROUTE 95 ABOUT 2.9 MILES EAST OF ROUTE 95 BEGINNING STATION 375+98.00± (Match Existing)


Sheet No. 1 of 7























HALF SECTION NEAR PANEL POINT

HALF SECTION NEAR MID-PANEL POINT

TYPICAL SECTION THRU EXISTING DECK

GENERAL NOTES:

Design Specifications:

2002 AASHTO LFD (17th Ed.) Standard Specifications Bridge Deck Rating = 6

Design Unit Stresses:

Structural Low Alloy Steel (ASTM A709 Grade 50) fy = 50,000 psi

Concrete Protective Coatings:

Protective coating for concrete bents and piers (Epoxy) shall be applied as shown on the bridge plans and in accordance with Sec 711.

Miscellaneous:

Outline of old work is indicated by light dashed lines. Heavy lines indicate new work.

Contractor shall verify all dimensions in field before ordering new material.

High strength bolts, nuts and washers will be sampled for quality assurance as specified in Sec 106.

Fabricated structural steel shall be ASTM A709 Grade 50, except as noted.

Field connections shall be made with $\frac{3}{4}''$ diameter high strength bolts and $\frac{13}{16}''$ diameter holes, except as noted.

Shop-drilled holes in new steel and existing holes in existing steel may be used as a template for field drilling new holes at connection joints with the installation of replacement end portals and sway frames.

Removal and replacement of the end portals and sway frames, as shown in the plans, and any incidental work, complete in place, will be considered completely covered by the contract jump sum price for "Remove and Replace Portals and Sway Frames".

All removed rivets in rehab structure shall be replaced with high strength bolts with flat washer under bolt head and nut (See Special Provisions).

Roadway surfacing adjacent to the bridge ends shall match new bridge wearing surface (Roadway Item).

Traffic Handling:

Traffic to be maintained on structure during construction except structure to be closed during heat straightening and removal and replacement of portals and sway frames. See roadway plans for traffic control.

Detailed	Apr.	2015
Checked	June	2015

<mark>Final Estimated Quantities</mark>		
Item		Total
Removal of Seal Coat	sq. foot	39,981
Ultrathin Bonded Wearing Surface, Type C	sq. yard	4,686
Substructure Repair (Unformed)	sq. foot	23
Repairing Concrete Deck (Half-Soling)	sq. foot	10,083
Full Depth Repair	sq. foot	29
Clean and Epoxy Seal	sq. foot	8,954
Protective Coating-Concrete Bents and Piers (Epoxy)	lump sum	1
Surface Preparation for Recoating Structural Steel	lump sum	1
Field Application of Inorganic Zinc Primer	lump sum	1
Intermediate Field Coat (System G)	lump sum	1
Finish Field Coat (System G)	lump sum	1
Remove and Replace Portals and Sway Frames	lump sum	1
Heat Straightening	lump sum	1
Misc. Structural Steel Construction	lump sum	1

The State estimates there is approximately 98.000 pounds of new steel in the pay item "Remove and Replace Portals and Sway Frames" and that weight is used in preparing the cost estimate for the pay item. Variation may be encountered in the estimated weight but the variation cannot be used for an adjustment in the contract lump sum price.


Structural Steel Protective Coatings:

including curb rails.

for Recoating Structural Steel".

cleaning of the coating systems as required by the engineer.

ROUTE 160 FROM ROUTE 5 TO ROUTE 95 ABOUT 2.9 MILES EAST OF ROUTE 95 BEGINNING STATION 375+98.00± (Match Existing)



STD. 616.10

