November 26, 2024 6:52:08AM

Missouri Department of Transportation State Bridge Inspection Report

COUNTY: BUTLER DISTRICT: SE CLASS: STATBR FED-ID: 4499 BRIDGE: F0665

GENERAL STRUCTURE INFORMATION ***BRIDGE INSPECTION INFORMATION*** **ROUTE: US67S** # **SPANS**: 1 PLACE CODE: 51392 NEELY **DATE:** 02/21/2023 **RESPONSIBILITY: DISTRICT** LANES ON: 2 FEATURE: HARVIELL DRAIN DTC LENGTH: 54 FT 0 IN FREQUENCY: 24 **CALCULATED INTERVAL**: 24** LANES UNDER: 0 STATUS: A-OPEN **MAXIMUM SPAN: 54 FT 1 IN TEAM LEADER:** STEVE RIGHTNOWAR **ELEMENT: YES LOG MILE:** 189.092 **COMPASS DIRECTION: NORTH to SOUTH** APPROACH ROADWAY: 24 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR: 26.00 MILES DIRECTION OF TRAFFIC: 2-WAY TRAF CURB TO CURB: 26 FT 0 IN INSPECTOR 3:** NHS: YES **FUNCTIONAL CLASS: RL-PRINCIPAL ARTERIAI** OUT TO OUT: 28 FT 10 IN ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1922 **NBI OWNER: MODOT AADT:** 6412 **GENERAL INSPECTION COMMENTS REHAB:** 1941 **NBI MAINTAINED: MODOT AADT YEAR: 2023** MAINTENANCE DISTRICT: SE LOCATION: S 27 T 23 R 5 E **AADT TRUCK: 26.7% LATITUDE:** 36 36 28.55 (DMS) **MAINTENANCE COUNTY: BUTLER FUTURE AADT: 11221 LONGITUDE:** 90 31 13.57 (DMS) SUB AREA: 7H38 **FUTURE AADT YEAR: 2043** ***INDEPTH INSPECTION INFORMATION*** ***FRACTURE CRITICAL INSPECTION INFORMATION*** DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL**: NBI**: **FREQUENCY: CALCULATED INTERVAL**: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** ***SPECIAL INSPECTION INFORMATION*** ***UNDERWATER INSPECTION INFORMATION*** CATEGORY: CHANNEL CROSS SECT **CATEGORY: DRY DATE:** 04/14/2020 **RESPONSIBILITY: DISTRICT DATE:** 02/21/2023 **RESPONSIBILITY: DISTRICT NBI:** NO NBI: NO FREOUENCY: 72 CALCULATED INTERVAL**: 72 FREQUENCY: 60 CALCULATED INTERVAL**: 24 TEAM LEADER: ED HESS **INSPECTOR 3: METHOD:** WT TAPE **TEAM LEADER: INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 2: INSPECTOR 4: INSPECTOR 2:** STEVE RIGHTNOWAR **INSPECTOR 4:** * When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS DATE **FREQUENCY CATEGORY** CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** NO VISUAL 05/09/2017 DAMAGE POST DISTRICT INCIDENT

MoDOT

MoDOT

Missouri Department of Transportation State Bridge Inspection Report

November 26, 2024 6:52:08AM

DISTRICT: SE CLASS: STATBR FED-ID: 4499

COUNTY: BUTLER BRIDGE: F0665 ***STRUCTURE POSTING*** APPROVED CATEGORY: S-1 NO POSTING REQUIRED

COMMENTS:

FIELD CATEGORY: S-1

NO POSTING REQUIRED

Ton 2:

Ton 1: COMMENTS:

Ton 1:

Ton 2:

Ton 3:

Ton 3:

PROBLEM:

PROBLEM DIRECTION:

GENERAL COMMENTS/MAJOR RATED ITEMS GENERAL COMMENTS: (BOWDEJ1, 09/05/2008)--(54') SMP WF GDR SPAN (WIDENED AND REDECKED)

[ITEM 58] DECK: 5-FAIR CONDITION **RATING:** 09/24/2014

COMMENTS: (DENNIB1, 12/11/2012)--DECK IS SHIFTING AT ABUTMENTS

[ITEM 59] SUPER: 5-FAIR CONDITION

COMMENTS: (SHRUBM1, 12/27/2011)--SECTION LOSE AT GIRDER 7

RATING: 12/27/2011

[ITEM 60] SUB: 5-FAIR CONDITION

RATING: 03/15/2017

COMMENTS: (DENNIB1, 03/15/2017)--V & H CRACKS & SCALING

[ITEM 61] BANK/CHANNEL: 5-MAJOR DAMAGE

RATING: 02/20/2019

COMMENTS: (DENNIB1, 02/20/2019)--EROSION ON NORTH SLOPE

[ITEM 113] SCOUR: 8-STABLE FOR CALCULATED

RATING: 05/18/2001

EVALUATION TYPE:

[ITEM 71] WATERWAY ADEQUACY: DECK/APPRCH OVERTOP SLIGT **COMMENTS:**

RATING: 05/18/2001

[ITEM 72] APPRRDWY ALIGNMENT: 8-VERYGOOD

RATING: 05/18/2001

RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS

[ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 01/11/2011 **COMMENTS:**

MATERIAL REINFORCED CONCRETE **CONSTRUCTION CURB**

DIRECTION COMMENTS

BOTH

REINFORCED CONCRETE **BALUSTER**

BOTH

[ITEM 36B] TRANSITION RAILING RATING: DOESN'T MEET CURRN'T STND-0

RATING: 01/11/2011

COMMENTS:

MATERIAL **GALVANIZED STEEL** **CONSTRUCTION** W-BEAM

DIRECTION ALL

COMMENTS:

COMMENTS:

COMMENTS

[ITEM 36C] APPROACH RAILING RATING: MEETS CURRENT STANDARDS-1

RATING: 05/18/2001

COMMENTS:

MATERIAL GALVANIZED STEEL **CONSTRUCTION**

DIRECTION

COMMENTS

W-BEAM ALL

Design No = f0665

November 26, 2024 6:52:08AM

Missouri Department of Transportation State Bridge Inspection Report

COUNTY: BUTLER DISTRICT: SE CLASS: STATBR FED-ID: 4499 BRIDGE: F0665

[ITEM 36D] RAIL END TREATMENT RATING: MEETS CURRENT STANDARDS-1

RATING: 01/11/2007

DIRECTION

COMMENTS

MATERIAL **GALVANIZED STEEL**

MoDOT

CONSTRUCTION BREKAWAY SYSTEM

ALL

APPROACH PAVEMENT: *Overall condition assigned for each approach pavemenet component is shown below.

MATERIAL REINFORCED CONCRETE **CONSTRUCTION SLAB**

DIRECTION BOTH

CONDITION*

COMMENTS

COMMENTS:

DRAINAGE, EXPANSION DEVICES, BANK/SLOPE, AND DECK PROTECTIVE COMPONENTS

DECK PROTECTIVE COMPONENTS:

SERIES TYPE-# **COMPONENT** MAIN SERIES-1 WEARING SURFACE **MATERIAL** ASPHALT

CONSTRUCTION BITUMINOUS MAT **THICKNESS** 2 IN

YEAR APPLIED **MANUFACTURE** **OVERALL CONDITION FAIR**

COMMENT:

DECK PROTECTION

NOTAPPLICABLE

NONE

COMMENT:

MEMBRANE

NOTAPPLICABLE

NONE

COMMENT:

DRAINAGE COMPONENTS:

COMPONENT DRAINAGE

MATERIAL REINFORCED CONCRETE **CONSTRUCTION**

DIRECTION COMMENTS

CURB OUTLET

EXPANSION DEVICE COMPONENTS:

SUB UNIT-#

SUB LABEL

COMPONENT

MATERIAL

CONSTRUCTION

GAP

YEAR APPLIED

MANUFACTURE

OVERALL CONDITION

COMMENT:

BANK/SLOPE PROTECTION COMPONENTS:

COMPONENT

MATERIAL

CONSTRUCTION

DIRECTION

COMMENTS

DECK COMPONENTS

SPAN TYPE-# MAIN SPANS-1 **COMPONENT** DECK

MATERIAL REINFORCED CONCRETE

CONSTRUCTION CAST-IN-PLACE

COMMENTS

CONDITION POP-OUTS

SCALING

SPALLS

TRANSVERSE CRACKS

LOCATION 1 THROUGHOUT THROUGHOUT

RANDOM

THROUGHOUT

LOCATION 2

SEVERITY FEW

MEASUREMENT

MEDIUM SMALL FEW

SUPERSTRUCTURE COMPONENTS

SERIES TYPE-# MAIN SERIES-1

SPAN TYPE SIMPLE SPAN MATERIAL STEEL

CONSTRUCTION WIDE FLANGE GIRDERS LABEL

COMMENTS

COMMENT

<u>SPAN</u>

COMPOSITE INDICATOR

LENGTH

WEATHERING STEEL

COMMENTS

Design No = f0665

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

November 26, 2024 6:52:08AM

Missouri Department of Transportation State Bridge Inspection Report

COUNTY: BUTLER DISTRICT: SE CLASS: STATBR FED-ID: 4499 BRIDGE: F0665

NO

LOCATION 2

MAIN SPANS-1 NON-COMPOSITE 54 FT 1 IN

AT BEARING

(REHAGM, 02/12/2004)--ABUTMENT #1 - MOVING TO EAST 1 1/2 INCHES

ABUTMENT #2 - MOVING TO WEST 1 1/2 INCHES

DECK BOLTED (SOME SHEARED OFF)

CONDITIONLOCATION 1OTHERDIAPHRAGMSRUSTINGBOTTOM FLANGERUSTINGTHROUGHOUT

<u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>

NOT APPLICABLE (DENNIB1, 09/24/2014)--DIAPHRAGM TWISTING MODERATE (DENNIB1, 03/15/2017)--GIRDER 1,2,4 & 7

MODERATE (SHRUBM1, 12/27/2011)--ALL RUSTING AT SOUTH BEARING AREAS

MODERATE (DENNIB1, 03/15/2017)--GIRDER 1,2,4 & 7.

		***SUBSTRUCT	URE COMPONENTS*	**		
<u>SUBSTRUCTURE</u> <u>SKEW</u> <u>LEN</u>		<u>CONSTRUCTION</u>	<u>LABEL</u> <u>COMMENT</u>	<u>S</u>		
ABUTMENT-1 RA-45 DEGREES 39 FT		<i>NON-INTEGRAL</i>				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
ASSOCIATED COMPONENT	<u>MATERIAL</u>	<u>CONSTRUCTION</u>				
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>	
SCALING	THROUGHOUT		MODERATE			
FLARED WINGS	REINFORCED CONCRETE	CAST-IN-PLACE				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>	
HORIZONTAL CRACKS	THROUGHOUT		FEW			
SPALLS	BACKWALL		MINOR			
VERTICAL CRACKS	THROUGHOUT		MODERATE			
WING PILES	TIMBER	OTHER				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>	
DECAYING	THROUGHOUT		MODERATE			
FOOTING	REINFORCED CONCRETE	TIMBER PILE				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>	
EXPOSED	TOP		PARTIAL			
BACKWALL	REINFORCED CONCRETE	CAST-IN-PLACE				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>	
SCALING	THROUGHOUT		MODERATE			
FIXED BEARING	STEEL	FLAT PLATE				
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>	
RUSTING	THROUGHOUT		MODERATE			
ABUTMENT-2 RA-45 DEGREES 39 FT	0 IN REINFORCED CONCRETE	NON-INTEGRAL				
CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT	
ASSOCIATED COMPONENT	MATERIAL	CONSTRUCTION				
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE				
CONDITION	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT	
SCALING	THROUGHOUT		MODERATE			
FLARED WINGS	REINFORCED CONCRETE	CAST-IN-PLACE	WOBERTE			
CONDITION	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT	
EFFLORESCENCE	THROUGHOUT		MODERATE		_ 	
HORIZONTAL CRACKS	THROUGHOUT		FEW			
VERTICAL CRACKS	THROUGHOUT		MODERATE			
WING PILES	TIMBER	OTHER				
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT	
FOOTING	REINFORCED CONCRETE	TIMBER PILE				
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT	
BACKWALL	REINFORCED CONCRETE	CAST-IN-PLACE	<u> </u>			
<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT	
01.211.01.		<u> </u>				

MODOT

SECTION LOSS

Missouri Department of Transportation State Bridge Inspection Report

November 26, 2024 6:52:08AM

COUNTY: BUTLER DISTRICT: SE CLASS: STATBR FED-ID: 4499 BRIDGE: F0665

THROUGHOUT

FIXED BEARING

FLAT PLATE

LOCATION 2

MEASUREMENT COMMENT

CONDITION RUSTING

SCALING

LOCATION 1 THROUGHOUT **SEVERITY** MODERATE

MINOR

(SHRUBM1, 12/27/2011)--ALL RUSTING

OVER/UNDER ROUTES CLEARANCE INFORMATION

CLEARANCES OVER DECK

MODOT

**NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance. DATE

VERTICAL CLEARANCE TYPE**

VALUE

LANES

STEEL

DIRECTION

COMMENT

CLEARANCES UNDER BRIDGE RECORD # ROUTE **NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance. **DIRECTION OF TRAFFIC RIGHT LATERAL CLEARANCE**

LEFT LATERAL CLEARANCE

UR-ID

DEPARTMENT REPAINT

VERTICAL CLEARANCE TYPE**

VALUE

DIRECTION

DATE

COMMENT

STRUCTURE PAINT INFORMATION

CONDITION:

FAIR

RUST AMOUNT: 6=1.0% OF SURFACE RUSTED

STEEL TONS: 22

ORIGINAL PAINT PAINT TYPE:

CONTRACT REPAINT

PAINT TYPE: A SYSTEM

MANUFACTURE: SURFACE PREP:

NAME: **PAINT COLOR:** **PAINT TYPE:** NAME:

NAME: RED LEAD

PAINT YEAR:

MILS:

PAINT COLOR: PAINT YEAR:

MILS:

PAINT COLOR: ALUMINUM PAINT YEAR: 1972

MILS: 9

REOUESTED WORK ITEMS

GENERAL WORK COMMENTS:

RESPONSIBILITY DISTRICT ROUTINE **LOCATION** SLOPE

ITEM PLACE RIP-RAP **CATEGORY** SLOPE

PRIORITY 2

DATE

WORK ITEM COMMENT 02/13/2019 (DENNIB1, 02/19/2019)--RIP RAP ON NORTHWEST CORNER

Design No = f0665

Missouri Department of Transportation State Bridge Inspection Report

November 26, 2024 6:52:08AM

COUNTY: BUTLER

DISTRICT: SE

CLASS: STATBR

FED-ID: 4499

BRIDGE: F0665

UTILITY ATTACHMENTS

UTILITY OWNER METHOD MEASUREMENT TYPE

VALUE

NUMBER

UTILITY ATTACHMENT COMMENT

YEAR PROJECT # MONTH LET YEAR LET ITEMS
2027 SE0140 1 2027 REPLACE BRIDGE

COMPUTER GENERATED RATINGS AND DEFICIENCY ITEMS

NOTE: The items listed in this section are updated whenever computer edits are ran on a structure after the inspection updates have been entered in to TMS.

Rated Item

Rating

Rating

Rating Date

ADVANCED SIGN INFORMATION

SIGN TYPE

PROBLEM DIRECTION

1

[Item 67] Structure Evaluation Rating:4-MEETS MINIMUM TOLERABLE1/14/2004[Item 68] Deck Geometry Rating:2-BASICALLY INTOLRBLE REQ2/23/2015[Item 69] Underclearance:N-NOT APPLICABLE5/18/2001Sufficiency Rating:36.9%1/31/2022Deficiency:FUNCTIONAL1/14/2004

FUNCTIONAL
Funding Eligibility:

Estimated New Structure Length:

575 FT.

Funding Eligibility:

575 FT.

Funding Eligibility:

575 FT.


Estimated Total Project Cost: \$787,388 ---Year of Cost Estimate: 2024 ----

NOTE: The above structure length and cost estimates are computer generated using algorithms in the TMS system. These algorithms are generalized to use NBI items to come up with a new structure length and width to calculate a new area which is taken times a representative cost per square foot. The actual structure size and cost may vary significantly from these numbers once site specific engineering is done.

OUTFALL INSPECTION INFORMATION

OUTFALLS: INSPECTOR: STATUS: DATE:


NOTES:





MISSOURI STATE HIGHWAY DEPARTMENT

FED ROAD STATE FED. AID FISCAL SHEET TOTAL DIST. NO. PROJ. NO. YEAR NO. SHEETS

MO. STATE FEB. 19







In Size (exact) About (acation	Bending Sketches & Cutting Diagrams	Ma Size / a porth Mand / a se disco	Bending Sketches & Cutting Diogra
Substructure	101	Substructure (Contd.)	Dericing Skerches & Curring Diogra
3 2 5 5-3" HI Wing	4:101. 41	30 1 7'G' DI Footing	and sinds diale and
2 3 5 G H2 "		10 fr 5'G' 02	201 5 28 4 71 3 75
2 3 6 2'G' H3		10 3 5 6 02 ···	
3 \$ 3'0" H4 "	7:46" 4:108"	5 2 7 3 04	
	1 18		3'51' 3:91' 5'115' 7'3
2 5" 13'9" HS Abutment		1 300 5.00 05	7'3" /3'3"
8 2 12 9 HG .	L-J 7-H8 BARS CUT 7	1 2" G'G' OG	5-D4 BARS CUT 5 2-DE BARS CU
3 11 10-3" H7 .	H2	714 0 0 0	2-2-2-10-00-3 2-00-00-00
7 8" 12'-3" HB Wing	144	2 3 /3 3 D8	2:32" 23" 7/
4 8 7 G" H9 "	5:41.91	5 24 9-9 29	18 4 G'8 72
2 5'-3" HIO .		300 00 00	3:9" 7"CF 73
2 3" 4'9" HII	1 3	4 3 6'0' C4 Curb	3.3 1/101 /3
2 3'-G" HIZ "	3' 1 010 50 510 80	2 3" 7'-G" C5 "	- DO
8 8 17 3 HI3	6 3-443-44	14 8"5 4'0" CG	\$ 100 miles
2 8 15:6" HI4 "	B.H S 4'9"	2 1 G'0" C7 "	222
2 8 d 12 G HI5 "	6-HI7 BARS CUT 6 &		195
3 1° 13'0" HIG Abutment	HI7	00 100 000 000	TI-T2-T3
G 2" 14'-9" HIT C+ft.		28 1 3 9 R3 Post	Varies Si
9 800 16'0" HIB Abutment	/±" /2.	6 5 G-0" R4 .	4:10% gl. 29:1' 3
8 19 13'9" 119		6 g G 9" R5 "	10.7 74
1 3 HZ-3" HZO -	G41 6:10E	• • • • • • • • • • • • • • • • • • • •	70-7
	1 /6 / 84	2.1. 5.9. 76 Wing	30:7% 4:10%
	ामन =====	2 1 5 6 7/ "	
2 8 13-3° VI Wing	6:6f 6:0f	2 4 8 9 72 -	
0 1 3'9' VZ	9 8	2 4 12'0" 73	46-51 BARS CUT 92 SI-S2-T4
4 8° 3'G' V3 .	THE SUI BARS CITT 2 &	7 2" 12'9" 74 Ctft.	& BEND AS SHOWN
2 2 14'0" V4 Abutmem	HI9-H20 BEND AS SHOWN	2 1 11.9" 75 Wing	19" 52 3:42"
5 8 4'0" V5		4 50 5.6" DIO Footing	J-47
5 5 8 8 0 VG	Vories 158	Superstructure	1 - 22 - 55
G 19 10-0" V7 .	」 	92 5° 35'6' 31 Slob	980 3
4 10-3" V8 .		39 31:00 52	R6
4 2 7'3" V9 "		39 1 79 3 33 .	
2 50 5'9" VIO Wing		108 8'3 27'6' 34 .	C2-C6
2 3 9'0' V// "	19 12te	4 2 18-9 55 1	
3 8 10'G" V/2 "		4 8 24 24 9 56 1	\sum_{\infty}
3 8 12 0 V/3 "	VI V3 V4	20 3 9 9 6 37 "	8:74"
2 8 8 3 VIA Abutmen	A		[5]
1 106 9'3" VIS "	75m a: a: a: a:	6 2" 29'9" CI Curb	<u> </u>
9 8 # 19:9" VIG Wing	المراجعة الم	52 3° 3'9° C2 .	E
1 8 8 8 3 V/7 .		6 2" 23'-6" C3 "	57 1/7
3 2"# 7'3" Y/8 Abutmen	7 § 	14 80 4'0" CG "	7/:3
4 50 6:3° VI9 C+ft.	1 1/2/18/80	28 100 3'9" R3 Post	76 3'5' 221'
4 1 3-9 V2C ·	/9'9"	50 1 9 RI Rail	15 36 710F KK
3 2'0' V21 Footing	V22 9-VI6 BARS CUT 9	32 2" 8'6" RZ	
6 1 6 6 V22 Wing	1	40 1 7'3' RG Subpost	2 9 H5-H6
7	1	320 2 18° R7 Balusters	S. S. J. W.
 	1	8 1 10-9 RB Roil	
1 1 1	1	6 10 6'0 A4 Post	75-76
	1	6 4.0 6:0 00	

COMPLETE BILL OF REINFORCING STEEL

GENERAL NOTES:

Design Specifications A.A. 5.H 0.

Loading H-15 A.A.3.H.O.

Reinforcing Steel Stress 18,000 % a*

Structural Steel Stress 18,000 % a*

Concrete Class 8* 900 % a*

All concrete shall be Closs 8*.

Rivets 2**, Holes 18**. All field connections shall riveted.

be riveted.

Qualification of all welding operators and electrodes will be required in accordance with Specifications, except that a proper certification of electrodes previously qualified will be acceptable.

Point: Shop, none, field, surfaces inaccessible after erection three coats of red lead. No other paint to be applied by Contractor. Red lead required shall be furnished by the Commator. Payment for cleaning and painting such surfaces will be included in unit price bid for structural steel.

All rubber compound shall be gray in Color.

ESTIMATED QUANTITIES							
Item .		Supersin	Substr	Total			
Class I Excavation for Structures	Cu.Yda		85	85			
Class 2 Excavation for Structures	Cu: Yds		62	G2			
Class "8" Concrete (Handrail)	Cu.Yds	6. 3	1.6	7.9			
Class "B" Concrete	Cu.Yds	42.2	64.4	106.6			
Fobricated Structural Steel	16s.	.195GO		19560			
Reinforcing Steel	Lbs.	10790	3910	14760			
Creasated Timber Piles in Place	Lin.Ft		325	325			
Special Work (See Special Provisions)	<u>ump 3u</u> m						

Note: Excovation for bridge made above Elev. 297.0 will be paid for as Class I Excovation for Structures.

Excovation for bridge made below Elev. 297.0 will be paid for as Class 2

Excavation for bridge mode below Elev. 297.0 will be paid for as Crass Excavation for Structures.

Weight of barman and included in weight of carrier my steel.

B. M. Elev. 303.24 NIR. 24" Elm 100'Rt. Sto. 719+25. Add 0.18 for USGS. Datum

BRIDGE OVER HARVIELL DITCH

STATE ROAD FROM JUNCTION ROUTE 14 SOUTH ABOUT 6.5 MILES S.W. OF HARVIELL PROJECT SN-FA 58-8(4) (U.S.67) STA. 719+0801

BUTLER

COUNTY

SUBNITTED BY TRANSCENDENCE 1/17/4/
APPROVED BY CUC BROWNING 1/17/4/

STD. C-IIOR2


Drown July 1940 by D.K.M. Traced Nov. 1940 by G.W. Checked Jon. 1941 by RAS.


of at least 23 ton per pile.


Note: This drawing is not to scale. Follow dimensions.


Sheet No. 1 of 5 .

F-665R











MISSOURI STATE HIGHWAY DEPARTMENT

FINAL PLANS TEO ROAL STATE TED ALS PISCAL SHEET 47 90 190 Blad 19



Note: /// z. . s driven to susiain a load of at least 17 ton per pile.



EPPS DITCH

£ Roadway ;

5to.719+CE!


LOCATION SKETCH

GENERAL NOTES:

Design Specifications A.A.S.H.O. Loading H-15 A.A.S.H.O.
Reinforcing Steel Stress 18,000 % or
Structural Steel Stress 18,000 % or Concrete Class "B" 300 "fe"
All concrete shall be Class "B".
Rivets \$"", Holes "B". All field connections shall be riveled.

Qualification of all welding operators and electrodes will be required in accordance with Specifications, except that a proper certification of electrodes previously qualified will be acceptable.

Paint: Shop, none, field, surfaces inaccessible after eraction three coots of red lead. No other point to be applied by Contractor. Red lead required shall be furnished by the Contractor. Payment for cleening and pointing such surfaces will be included in unit price bid for structural steel All rubber compound shall be gray in Colon.



ESTIMATI	ED QUAN	ITITIES		
Item		Superstr	Substr	Total
Class I Excavation for Structures	Cu.Yds.		101.0	101.0
Class 2 Excavation for Structures	Cu Yds		68.5	68.5
Class "8" Concrete (Handrail)	CuYas	G.3 .	1.G :	7.9
Class "B" Concrete	Cu Yds	42.2	- 644 -	106.6
Fobricated Structural Steel	Lbs.	19740 -		19740
Reinforcing Steel	155.	10790	35:0	- 700 -
Creosoted Timber Piles in Place	L1.7 FT.		53/	531 -
Special Work (See Special Provisions)	ump Sum			

Note: Excavation for bridge made above Siev. 297.0 will be poid for as Class. Excavation for Structures.

Excavation for bridge made below Elev. 297.0 will be paid for as class 2 Excavation for Structures. Weight of bor mot is included in weight of reinforcing steel.

B M Elex 303.24 NIR. 24" Elm 100'Rt. Sta. 719+25, Add C.15 for USGS. Datum

BRIDGE OVER HARVIELL DITCH

STATE ROAD FROM JUNCTION ROUTE 14 SOUTH ABOUT 6.5 MILES S.W. OF HARVIELL

PROJECT SN-F.A 58-B(4) (U.S.67) STA. 719+08.01

BUTLER

COUNTY

77R2+ack. 1/17/41 LEMENTS OF CLL Brown 1.07 4

FINAL PLANS


STD. CHIUP2 665R


Dravim July 1940 by D.K.M. Traced Nov 1940 by G.M. Checked Jan 1841 by PAB

Note This drawing is not to scale follow dimensions


Sheet No 1375

Droinage Area 3 50. Miles - Flat






なのが





Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: BUTLER F0665 R REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 3/15/2024 2024 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type LIS District 5B SE Route Signing Prefix MAINLINE **BUTLER** County 5C Designated Level of Service 00067 4499 8 Federal ID No. 5D Route Number 1922 NOT APPLICABLE 27 5E Year Built Directional Suffix US 67 S 106 1941 7 Year Reconstructed Facility Carried YES HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 000000015 21 Structure Maintenance 13A LRS Inventory Route No. 00 STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 02-RU PRINCPL ARTRIAL-OTH 37 Historical Significance NOT ELIGIBLE FOR NR OF HP 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES ON NHS National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway YES 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 6412 4 Place NEELY 29 AADT 51392 2023 Code 30 AADT Year 2-WAY TRAFFIC S 27 T 23 N R 5 E Location 102 Direction of Traffic 11 Milepoint 190.20 miles 27% 109 AADT Truck Percent 16 Latitude 36 D 36 M 29 S 11221 114 Future AADT 17 Longitude 90 D 31 M 14 S 2043 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 HARVIELL DRAIN DTC 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 26.25 miles Type of Service Under By pass Detour Length 00 28B Lanes Under Structure 32 Approach Roadway Width 23 Ft. 11 In. N/A 45.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 25 Ft. 11 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 54 Ft. 2 In. 54 Ft. 2 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 25 Ft. 11 In. 40 Nav Horizontal Clear 51 28 Ft. 10 In. Nav. Pier Protection Deck Width (Out-Out) 111 52 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck





Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: BUTLER BRIDGE: F0665 R REVIEW STATUS: APPROVED NBI STATUS: T

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 3/15/2024 SUBMITTAL YEAR: 2024

RECORD TYPE: ROUTE CARRIED ON STRUCT	RUN DATE: 5/15/2024 SUBMITTAL TEAR: 2024
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION
31 Design Load H 15 41 Structure Status OPEN NO RESTRICTIONS 63 Oper. Rating Meth. LOAD FACTOR 64 Operating Rating 35 Tons. 65 Inventory Rating Meth LOAD FACTOR 66 Inventory Rating 21 Tons. 70 Bridge Posting Code =>LEGAL LOADS PROPOSED IMPROVEMENT INFORMATION	43A Main Struc. Mat type STEEL 43B Main struc Constr. Type STRINGER/MULTIBEAM - GRD 45 # of Main Spans 1 44A Appr Struc. Mat type 000 44B Appr Struc. Cnstr. type 000 46 # of Approach Span 0 107 Deck Mat/Constr. 1 CONCRETE CIP 108A Wear Surf Mat/Constr. 6 BITUMINOUS 108B Membrane Mat/Constr. 0 NONE
Sufficiency Rating 36.9 Percent Perfectory Pering FUNCTIONAL	108C Deck Protect Mat/Constr. 0 NONE
Deficiency Rating Funding Eligibility FULL 75A Proposed Work REPLACEMENT SUBSTND LOAD 75B Work Done By Contract 76 New Struc Length 75 Ft. 6 In. 94 Struc Improve Cost \$ 525,000 95 Roadway Improve Cost \$ 52,000	CONDITION RATING INFORMATION 58 Deck Cond. Rating 5 59 Superstructure Cond. Rating 5 60 Substructure Cond. Rating 5 61 Channel /Channel Protection Cond. Rating 5 62 Culvert Cond. Rating N
96 Total Project Cost \$ 787,000	INSPECTION INFORMATION
97 Year of Cost Estimates 2024	90 Gen. Insp Date 2 / 23
APPRAISAL RATING INFORMATION 36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND 36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND 36C Approach Rail App. Rating MEETS ACCEPTBLE STND 36D Rail End Treat. App. Rating MEETS ACCEPTBLE STND 67 Struc Eval App. Rating 4 68 Deck Geometry App. Rating 2 69 Underclearance App. Rating N 71 Waterway Adeq. App. Rating 6 72 Approach Road App. Rating 8 113 Scour Assess App. Rating 8	91 Gen. Insp. Frequency 24 Months 92A Frac. Critical Inspection N Months 93A Frac. Critical Insp. Date 92B Underwater Inspection N Months 93B Underwater Insp. Date 92C Special Inspection N Months 93C Special Inspection Date BORDER BRIDGE INFORMATION 98 Neighboring State Code 98B Neighboring State % Respon 99 Neighboring State Struc. No.
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION
Approved Posting Category S-1	Field Posting Category S-1
Ton1 Ton2 Ton3 Tonnage Values for Posting Sign General Text for Posting Sign NO POSTING REQUIRED	Ton1 Ton2 Ton3 Tonnage Values for Posting Sign General Text for Posting Sign NO POSTING REQUIRED

Design_No = f0665 and Inventory_Appraisal_Submittal_Year = 2024

Bridge Number:	Route/County:
FOGUSR	67/Butler
Asbestos-Containing Yes: If yes, see report	No: X
Structural Ste Yes: 🔀	el Present? No: If No, then skip the following.
Lead-Based Paint Yes: X	(LBP) Present? No:
Trusses LBP? Yes: No:	Girder LBP? → •~~ds Yes: 🔀 No:
Railing LBP? Yes: No:	Pile LBP? Yes: No:

~

MEMORANDUM



Missouri Department of Transportation **Construction and Materials Central Laboratory**

TO:

FROM:

Leonard Vader Koral Vadu **Environmental Chemist**

DATE:

May 15, 2019

SUBJECT:

Materials

Asbestos Inspection & Heavy Metal Paint Survey

Route 67

Bridge F-0665R **Butler County**

We are providing you with the results of the inspection on the above referenced bridge. The inspection report contains an asbestos and a heavy metals survey. The asbestos inspection included identifying suspect asbestos-containing material and NVLAP accredited testing to confirm the presence of asbestos.

Form T746 – This will show if samples were taken, where from, and, if the sample was found to contain asbestos, our estimated quantity of material present. Under the column "Friability Category" this is the meaning for the following:

N-ACM – No asbestos detected.

I NF – Asbestos is present. Material shall be handled carefully by a licensed abatement worker and kept wet if removing as part of a maintenance activity.

II NF – Asbestos is present. If removal is required for the maintenance activity, use an abatement contractor.

In accordance with Missouri Department of Natural Resources' Technical Bulletin "Managing Construction and Demolition Waste" dated January 31, 2003, a heavy metal paint survey has been performed on the above referenced bridge. This survey includes locating concrete which has been painted with something other than traffic paint or graffiti, and testing the painted surface(s) to determine if hazardous heavy metals are present. If the bridge is being removed completely, or the maintenance repairs include removing the painted concrete, then, nonhazardous painted concrete may be used as clean fill materials, if properly handled. You must contact the Central Office Design Division for proper handling of the reported painted surfaces.

Although our survey included observing and sampling all accessible areas, it is possible that potentially hidden asbestos-containing materials may exist within the structure. Should you have any questions regarding these reports, please contact me at (573) 751-9252.

sm/lv

http://sharepoint/systemdelivery/cm/chemicallab/environmental/shared documents/asbestos/districts/southeast (se)/mt/f0665r/f0665r asbestos cover letter.docx

Attachments

Page 1 of 1

Form T746 Rev. 08/2012

ROUTE: MODOT JOB NO:	MISSOURI DE CONST	CONSTRUCTION AND MATERIALS Asbestos Survey Report All Suspect ACM SURVEYED BY: Ro	Robert Marshall and Leonard Vader 7020101818MOIR18860, R.M.
DISTRICT:	SE	CERTIFICATION #:	7020101818MOIR2672, L.V.
COUNTY:	Butler	SITE ADDRESS:	Over Harviell Drain Ditch
DATE OF SURVEY:	April 23, 2019	TYPE(S) OF STRUCTURE(S): Bridge	: Bridge
PARCEL NO.:	Bridge F-0665R		

Sample ID	Type of Materials	Location of Material	Friability Category	Field Measure
	No Samples taken. No Suspect ACM located.			
The state of the s				
100				
	Bridge Paint is not a suspect ACM per MSDS's			
	on file.			
A CONTRACTOR OF THE CONTRACTOR				
TO THE PARTY OF TH				
117 (117)				

The state of the s				

rial I NF = Category I Nonfriable * = Tested By Point Count Procedure N-ACM = Non-Asbestos Containing Material NAFD = No Asbestos Fiber Detected *= ^

II NF = Category II Nonfriable

F = Friable

Form T747 Rev. 08/2012

MISSOURI DEPARTMENT OF TRANSPORTATION CONSTRUCTION AND MATERIALS

Asbestos Survey Report
Nonfriable Asbestos-Containing Materials
(Abatement not required if not made friable during demolition.)

Over Harviell Drain Ditch 7020101818MOIR2672 Leonard Vader 70201000 Bridge TYPE(S) OF STRUCTURE(S): CERTIFICATION #: SITE ADDRESS: TESTED BY: Bridge F-0665R Butler N/A N/A SE 29 MODOT JOB NO.: DATE OF TESTS: PARCEL NO.: DISTRICT: COUNTY: ROUTE:

			Friability	Field	Asbestos	
Sample ID	Type of Material	Location of Material	Category	Measure	Type	Percent
		None Located	INF			
-	:					

All necessary work to handle this material is the contractor's responsibility.

I NF = Category I Nonfriable

Form T748 Rev. 08/2012

MISSOURI DEPARTMENT OF TRANSPORTATION CONSTRUCTION AND MATERIALS Asbestos Survey Report All materials requiring removal or special handling.

ROUTE:	67	TESTED BY:
MODOT JOB NO.:	N/A	CERTIFICATION #:
DISTRICT:	SE	SITE ADDRESS:
COUNTY:	Butler	TYPE(S) OF STRUCTURE(S
DATE OF TESTS:	N/A	
PARCEL NO.:	Bridge F-0665R	

Leonard Vader	7020101818MOIR2672	Over Harviell Drain Ditch	Bridge	
			;(S):	

	1				 r	ı	1	1	,	ı.	ı	ı				 _
Percent			A Company of the Comp													
Asbestos Type																
Field Measure																
Friability Category	II NF	ĹΤ														
Location of Material		None Located														
Type of Material																
Sample ID																
Bid Item No.																

Form C760 Rev. 08/2012

MISSOURI DEPARTMENT OF TRANSPORTATION CONSTRUCTION AND MATERIALS Metals Survey Report of Painted Concrete, Block, Brick Surfaces for Clean Fill Purposes

		۵	ņ										Ī
		H°	Ö.										
		Z Z											
R Orain Ditch	Metals (ppm)	<u>ر</u> م											
A idge F-0665 ver Harviell I	Me (p)	Ü											
N/A N/A Brid Over URE(S): Brid		Pb							777777		anni ti		
DATE OF TESTS: PARCEL NO: SITE ADDRESS: Over Harviell Drain Ditch TYPE(S) OF STRUCTURE(S): Bridge Over Harviell Drain Ditch Bridge		<u>ئ</u>											
TESTED BY: DATE OF TESTS: PARCEL NO: SITE ADDRESS: TYPE(S) OF STRU		A											
0.: N/A SE Butler Robert Marshall € EY: April 23, 2019		Color/Location of Material/Substrate	No samples taken. No painted surfaces located.										
ROUTE: MODOT JOB NO.: DISTRICT: COUNTY: SURVEYED BY: DATE OF SURVEY:		Sample ID								117 To a delication of the second of the sec			

All results are by XRF unless otherwise indicated: a = USEPA~SW-846~Method~3050 b = USEPA~SW-846~Method~7471

MEMORANDUM



Missouri Department of Transportation Construction and Materials Central Laboratory

TO:

TMS

FROM:

Robert Marshall 21

Environmental Chemist, Lead License #161121-300005166

DATE:

May 29, 2019

SUBJECT:

Materials

Job No. N/A

Route 67/Butler County

Bridge F-0665R

On April 23, 2019, a Lead Based Paint (LBP) survey was performed on the subject bridge. Painted girder and girder ends were present. The following results show the existing paint system on the girder and girder ends is LBP. Therefore any painting project on the railing and girder will be subject to DHSS notification and regulation:

	Girder end	Girder
	19MRSM133	19MRSM136
Lead (Pb)	> 5.0 mg/cm ² (Positive)	> 5.0 mg/cm ² (Positive)

In addition, a heavy metals screening was also performed on the painted structural steel. The following results are for informational purposes only:

	Girder end	Girder
	19MRSM134	19MRSM135
Arsenic (As)	< LOD *	45719 ppm **
Chromium (Cr)	< LOD	61 ppm
Lead (Pb)	217667 ppm **	688898 ppm
Cadmium (Cd)	202 ppm	1274 ppm
Selenium (Se)	< LOD	< LOD *
Barium (Ba)	423 ppm	117 ppm
Mercury (Hg)	< FOD	< LOD
Silver (Ag)	< LOD	< LOD

^{*&}lt; LOD = below the detection limit of the instrument

Should any further screenings be required, please contact Todd Bennett, Chemical Laboratory Director, at (573) 751-1045. Should you have any questions regarding the screenings, feel free to call me at (573) 751-9252.

rm/lv

 $http://sp/sites/cm/chemicallab/environmental/shared\ documents/asbestos/districts/southeast\ (se)/mt/f0665r/f0665r\ lbp\ letter.docx$

^{**}ppm = parts per million

CERTIFICATION NUMBER:

7020101818MOIR2672

THIS CERTIFIES

Leonard A. Vader

HAS COMPLETED THE CERTIFICATION

REQUIREMENTS FOR

Inspector

APPROVED: 10/22/2018

EXPIRES: 10/22/2019

Director of Air Pollution Control Program

TRAINING DATE: 10/18/2018

CERTIFICATION NUMBER:

7020101818MOIR18860

THIS CERTIFIES

Robert S Marshall

HAS COMPLETED THE CERTIFICATION

REQUIREMENTS FOR

Inspector

APPROVED: 10/22/2018

EXPIRES: 10/22/2019

TRAINING DATE: 10/18/2018

Director of Air Pollution Control Program