



March 13, 2025 4:30:42PM

COUNTY: MISSISSIPPI DISTRICT: SE CLASS: STATBR FED-ID: 9131 BRIDGE: T0418

\*\*\*GENERAL STRUCTURE INFORMATION\*\*\* \*\*\*BRIDGE INSPECTION INFORMATION\*\*\* **ROUTE: MO77S** # **SPANS**: 1 PLACE CODE: 48926 MISSISSIPPI **DATE:** 11/04/2024 **RESPONSIBILITY: DISTRICT** LANES ON: 1 LENGTH: 47 FT 0 IN FEATURE: LATERAL DTCH #3 FREQUENCY: 12 CALCULATED INTERVAL\*\*: 12 LANES UNDER: 0 **STATUS: P-POSTLOAD** MAXIMUM SPAN: 45 FT 0 IN **TEAM LEADER:** STEVE RIGHTNOWAR **ELEMENT: NO LOG MILE: 51.658 COMPASS DIRECTION: NORTH to SOUTH** APPROACH ROADWAY: 20 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR: 21.00 MILES DIRECTION OF TRAFFIC: 1-LN/2-WAY CURB TO CURB: 20 FT 0 IN INSPECTOR 3:** OUT TO OUT: 21 FT 4 IN NHS: NO FUNCTIONAL CLASS: RL-MAJOR COLLECTOR \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1935 **NBI OWNER: MODOT AADT:** 270 **GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2024** MAINTENANCE DISTRICT: SE LOCATION: S 3 T 25 R 17 E **AADT TRUCK: 25.0% LATITUDE:** 36 50 6.47 (DMS) MAINTENANCE COUNTY: MISSISSIPPI **FUTURE AADT: 378 LONGITUDE:** 89 12 42.24 (DMS) SUB AREA: 7H09 **FUTURE AADT YEAR: 2044** \*\*\*INDEPTH INSPECTION INFORMATION\*\*\* \*\*\*FRACTURE CRITICAL INSPECTION INFORMATION\*\*\* DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** \*\*\*SPECIAL INSPECTION INFORMATION\*\*\* \*\*\*UNDERWATER INSPECTION INFORMATION\*\*\* **DATE:** 06/13/2023 CATEGORY: CHANNEL CROSS SECT **DATE:** 11/04/2024 **CATEGORY: DRY RESPONSIBILITY: DISTRICT RESPONSIBILITY: DISTRICT** FREOUENCY: 120 **NBI:** NO FREOUENCY: 60 NBI: NO CALCULATED INTERVAL\*\*: 116 CALCULATED INTERVAL\*\*: 12 TEAM LEADER: STEVE RIGHTNOWAR **TEAM LEADER: INSPECTOR 3: METHOD:** WT TAPE **INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 2:** JERROD JERNIGAN **INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS DATE **FREQUENCY CATEGORY** CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** NO 01/30/2018 **QUALITY BRIDGEDIV ASSURANCE** 

March 13, 2025 4:30:42PM

**COUNTY: MISSISSIPPI** 

**DISTRICT: SE** 

**CLASS: STATBR** 

FED-ID: 9131

**BRIDGE: T0418** 

\*\*\*STRUCTURE POSTING\*\*\* **APPROVED CATEGORY:** S-17 CL OF BR AND TRK OVR 15 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 19 T OTHR TRKS WT LMT 35 T. **Ton 1:** 15 **Ton 2:** 19 **Ton 3:** 35 **COMMENTS:** FIELD CATEGORY: S-17 CL OF BR AND TRK OVR 15 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 19 T OTHR TRKS **PROBLEM: Ton 1:** 15 **Ton 2:** 19 **Ton 3:** 35 PROBLEM DIRECTION: COMMENTS: (WIESEJ1, 08/08/2011)--S APPR NOT POSTED \*\*\*GENERAL COMMENTS/MAJOR RATED ITEMS\*\*\* GENERAL COMMENTS: (BOWDEJ1, 09/05/2008)--(45') SMP WF GDR SPAN [ITEM 58] DECK: 5-FAIR CONDITION COMMENTS: (SHUNAT1, 02/08/2018)--SPALLS AND DELAMS THROUGHTOUT **RATING:** 05/18/2001 [ITEM 59] SUPER: 5-FAIR CONDITION COMMENTS: (LAMBEJ1, 11/04/2011)--TOP FLANGE RUSTING ON EXT. GIRDERS **RATING:** 11/03/2016 (DENNIB1, 11/03/2016)--INITIAL SECTION LOSS BOTTOM FLANGE [ITEM 60] SUB: 6-SATISFACTORY CONDITION COMMENTS: (LAMBEJ1, 11/04/2011)--MINOR TIMBER DECAY **RATING:** 05/18/2001 [ITEM 61] BANK/CHANNEL: 6-WIDESPREAD MINOR DAMAGE COMMENTS: (SHUNAT1, 02/08/2018)--MINOR BANK EROSION SOUTH BANK **RATING:** 11/13/2017 [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED **COMMENTS: RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: DECK ABOVE FLOOD ELEV **COMMENTS: RATING:** 05/18/2001 [ITEM 72] APPRRDWY ALIGNMENT: 8-VERYGOOD **COMMENTS: RATING:** 05/18/2001 \*\*\*RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS\*\*\* [ITEM 36A] BRIDGE RAILING RATING: DOESN'T MEET CURRN'T STND-0 **RATING**: 02/24/2004 **COMMENTS:** MATERIAL **CONSTRUCTION DIRECTION COMMENTS** REINFORCED CONCRETE **CURB BOTH CONDITION** LOCATION 1 LOCATION 2 **SEVERITY COMMENT** COLLISION DAMAGE **RANDOM** MINOR (BLALOR1, 11/13/2014)--SE CORNER BROKE OFF **RANDOM** (BLALOR1, 11/13/2014)--W/ REBAR **SPALLS MODERATE STEEL** CHANNEL-DOUBLE **BOTH CONDITION** LOCATION 1 LOCATION 2 **SEVERITY COMMENT RUSTING THROUGHOUT MINOR** [ITEM 36B] TRANSITION RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** 

MoDOT

### Missouri Department of Transportation State Bridge Inspection Report

March 13, 2025 4:30:42PM

**COUNTY: MISSISSIPPI** 

**DISTRICT: SE** 

**CLASS: STATBR** 

FED-ID: 9131

BRIDGE: T0418

[ITEM 36D] RAIL END TR	EATMENT RATING: NOT I	PROVIDED-0	<b>RATING</b> : 05/18/2001	COMMENTS:				
APPROAC	CH PAVEMENT: *Overall co	ondition assigned for each approach paveme	enet component is shown below.					
<u>MATERIAL</u>		STRUCTION DIRECTION	<b>CONDITION*</b>	<u>COMMENTS</u>				
ASPHALT		IINOUS MAT BOTH	POOR	(BLALOR1, 11/13/2014)				
	<u>CONDITION</u> DETERIORATION	<u>LOCATION 1</u> DRIVING SURFACE	<u>LOCATION 2</u>	<u>Severity</u> Minor	COMMENT	/08/2018)BREAKING UP THROUGHTOUT		
	DETERIORATION		ANSION DEVICES, BANK			,		
DECK PROTECTIVE COMPO	ONENTS:	Diaminate, Em	THISTOTY DE VICES, BATTI	AGEOTE, AND DECI	TROTECTIV	E COMI OILEITIS		
<u>SERIES TYPE-#</u> MAIN SERIES-1	<u>COMPONENT</u> WEARING SURFACE	<u>MATERIAL</u> ASPHALT	<u>CONSTRUCTIO</u> BITUMINOUS SEAL		<u>YEAR APPL.</u> 2013	<u>LIED</u> <u>MANUFACTURE</u> <u>OVERALL CONDITION</u> GOOD		
<u>COMMENT:</u>								
COMMENT	DECK PROTECTION	LIQUID SEALANT	INTERNALLY SEAL	LED	2011	PAVON INDECK		
<u>COMMENT:</u>								
	MEMBRANE	NOTAPPLICABLE	NONE					
<u>COMMENT:</u>	MEMBRUITE	No mi i Brenzaz	110112					
DRAINAGE COMPONENTS:								
	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>	N DIRECTI	<u>ON</u> <u>COMME</u>	ENTS		
	DRAINAGE	REINFORCED CONCRETE		_	<u> </u>			
EVDANCION DEVICE COMP	ONENTS.							
EXPANSION DEVICE COMPONENTS:   SUB UNIT-# SUB LABEL   COMPONENT   MATERIAL   CONSTRUCTION   GAP   YEAR APPLIED   MANUFACTURE   OVERALL CONDITION								
<u>COMMENT:</u>								
BANK/SLOPE PROTECTION	COMPONENTS:							
	COMPONENT	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>	<u>DIRECTI</u>	<u>ON</u> <u>COMME</u>	ENTS		
	BANK PROTECTION	ROCK	GROUTED	SOUTH				
***DECK COMPONENTS***								
SPAN TYPE-#	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>					
MAIN SPANS-1 <b>COND</b>	DECK	REINFORCED CONCRETE <b>LOCATION 1</b>	CAST-IN-PLACE LOCATION 2		<u>UREMENT</u> CO	OMMENT		
	N DAMAGE	RANDOM	LUCATION 2	<u>SEVERITY</u> <u>Meas</u> Minor	(RC	<u>OMMENT</u> OBINC3, 11/28/2018)W/EFFLO. DAMAGE OCCURRED IN SE CORNER WHEN RAILING WAS HIT. ECK REBAR EXPOSED		
DELAM	INATION	THROUGHOUT		MODERATE	DE	Dek KEDIK EM OULD		
DETERIORATION EDGE		EDGE	MEDIUM					
SPALLS THROUGHOUT MEDIUM (BLALOR1, 11/13/2014)W/ REBAR TRANSVERSE CRACKS THROUGHOUT MEDIUM		LALOR1, 11/13/2014)W/ REBAR						
			***SUPERSTRUC	CTURE COMPONEN	I'S***			
Design No = T0418								

**CLASS: STATBR COUNTY: MISSISSIPPI DISTRICT: SE FED-ID: 9131 BRIDGE: T0418** 

CONSTRUCTION SERIES TYPE-# SPAN TYPE **MATERIAL LABEL COMMENTS** MAIN SERIES-1 SIMPLE SPAN STEELWIDE FLANGE GIRDERS

**WEATHERING STEEL COMMENTS** <u>SPAN</u> **COMPOSITE INDICATOR LENGTH** MAIN SPANS-1 45 FT 0 IN NON-COMPOSITE NO

(ROBINC3, 12/21/2018)--DEAD LOAD DEFLECTION ON ALL BEAMS MINOR 1/2" **CONDITION LOCATION 1 SEVERITY MEASUREMENT COMMENT LOCATION 2** 

MINOR DECK LIFTING THROUGHOUT MINOR PACK RUST THROUGHOUT (LAMBEJ1, 11/04/2011)--EXT. GIRDERS RUSTING MODERATE THROUGHOUT

SECTION LOSS **BOTTOM FLANGE** INITIAL SECTION LOSS TOP FLANGE INITIAL

					URE COMPONENTS**		
<u>UBSTRUCTURE</u>	<u>SKEW</u>	<u>LENGTH</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>	<u>LABEL</u> <u>COMMENTS</u>	<u>S</u>	
ABUTMENT-1		20 FT 6 IN	TIMBER	NON-INTEGRAL			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIATED C	<u>OMPONENT</u>	<u>MATER</u>		<u>CONSTRUCTION</u>			
BEAM CAP		TIMBER		BEAM			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DECAYING		THROUGHOUT		MINOR		
PILING		TIMBER		OTHER			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SPLITTING		THROUGHOUT		MINOR		
STRAIGHT WIN		TIMBER		PLANKS			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	OTHER		BACKWALL		NOT APPLICABLE		(SHUNAT1, 02/08/2018)MINOR DECAY
WING PILES		TIMBER		OTHER			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SPLITTING		THROUGHOUT		MODERATE		(SHUNAT1, 02/08/2018)MODERATE DECAY THROUGHOUT
BACKWALL		TIMBER		PLANKS			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	OTHER		RANDOM		NOT APPLICABLE		(SHUNAT1, 02/08/2018)MINOR DECAY
FIXED BEARING		STEEL		FLAT PLATE			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	PACK RUST		THROUGHOUT		MINOR		
	RUSTING		THROUGHOUT		MINOR		
ABUTMENT-2		20 FT 6 IN K	REINFORCED CONCRETE	NON-INTEGRAL			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
ASSOCIATED C	<u>OMPONENT</u>	<u>MATER</u>		<u>CONSTRUCTION</u>			
BEAM CAP		TIMBER		BEAM			
	<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DECAYING		THROUGHOUT		MINOR		
PILING		TIMBER		OTHER			
	<u>CONDITION</u>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DECAYING		GROUND LINE		MINOR		
	SPLITTING		THROUGHOUT		MINOR		
STRAIGHT WIN		TIMBER		PLANKS			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WING PILES		TIMBER		OTHER			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DECAYING		THROUGHOUT		MODERATE		
BACKWALL		TIMBER	₹	PLANKS			

MODOT

March 13, 2025 4:30:42PM

**COUNTY: MISSISSIPPI DISTRICT: SE CLASS: STATBR FED-ID: 9131 BRIDGE: T0418** LOCATION 2 **SEVERITY** MEASUREMENT COMMENT

LOCATION 1 **CONDITION DECAYING** THROUGHOUT **SPLITTING THROUGHOUT** 

**MODERATE MODERATE** 

FIXED BEARING

STEEL

FLAT PLATE LOCATION 2

**SEVERITY MEASUREMENT COMMENT** 

**MINOR** MINOR (ROBINC3, 11/28/2018)--INITIAL

(ROBINC3, 11/28/2018)--NO LOSS OF BEARING

\*\*\*OVER/UNDER ROUTES CLEARANCE INFORMATION\*\*\*

**CLEARANCES OVER DECK** 

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

**DATE** 

VERTICAL CLEARANCE TYPE\*\*

VALUE

DIRECTION

LOCATION 1

**THROUGHOUT** 

THROUGHOUT

**COMMENT** 

CLEARANCES UNDER BRIDGE

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

RECORD # **ROUTE**  **# LANES** 

**CONDITION** 

**RUSTING** 

SECTION LOSS

**DIRECTION OF TRAFFIC** 

RIGHT LATERAL CLEARANCE

**LEFT LATERAL CLEARANCE** 

**UR-ID** 

**VERTICAL CLEARANCE TYPE\*\*** 

**VALUE** 

**DIRECTION** 

**DATE** 

**COMMENT** 

\*\*\*STRUCTURE PAINT INFORMATION\*\*\*

**CONDITION:** 

**POOR** 

**RUST AMOUNT:** 4=10% OF SURFACE RUSTED

STEEL TONS: 11

**ORIGINAL PAINT** 

**CONTRACT REPAINT** 

**DEPARTMENT REPAINT** 

**PAINT TYPE:** NAME: **PAINT TYPE:** NAME:

**PAINT YEAR:** 

**PAINT TYPE:** S SYSTEM NAME: CAL SULPH/LEAD PAINT **MANUFACTURE: SURFACE PREP:** 

**PAINT COLOR: PAINT YEAR:** 1974 **PAINT COLOR:** 

**PAINT COLOR:** GRAY

PAINT YEAR: 2000

MILS:

MILS:

**MILS**: 9

\*\*\*REQUESTED WORK ITEMS\*\*\*

**GENERAL WORK COMMENTS:** 

Design No = T0418

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

March 13, 2025 4:30:42PM

**COUNTY: MISSISSIPPI** 

**DISTRICT: SE** 

**CLASS: STATBR** 

FED-ID: 9131

**BRIDGE: T0418** 

RESPONSIBILITY

**LOCATION** 

**ITEM** 

**CATEGORY** 

PRIORITY

**DATE** 

**WORK ITEM COMMENT** 

\*\*\*UTILITY ATTACHMENTS\*\*\*

UTILITY OWNER

**METHOD** 

**MEASUREMENT TYPE** 

**VALUE** 

**NUMBER** 

UTILITY ATTACHMENT COMMENT

\*\*\*PROGRAM NOTES INFORMATION\*\*\*

<u>YEAR</u> <u>PROJECT #</u> SE0062

OJECT # MONTH LET

LET Y

YEAR LET ITEMS REPLACE

<u>ITEMS</u> REPLACE BRIDGE **COMMENT** 

***COMP	UTER GENERATED RATINGS AND DE	***ADVANCED SIGN INFORMATION***				
NOTE: The items listed in this section are updated whenever computer edits are ran on a structure after the inspection updates have been entered in to TMS.				SIGN TYPE	PROBLEM	PROBLEM DIRECTION
Rated Item	<u>Rating</u>	Rating Date	1	YIELD TO ONCOMING TRAFFIC		
[Item 67] Structure Evaluation Rating:	2-BASICALLY INTOLRBLE REQ	1/3/2024	2	B - ONE LANE BRIDGE		
[Item 68] Deck Geometry Rating:	4-MEETS MINIMUM TOLERABLE	3/25/2002				
[Item 69] Underclearance:	N-NOT APPLICABLE	5/18/2001				
Sufficiency Rating:	47.2%	3/6/2024				
Deficiency:	STRUCTURAL	1/3/2024				
Funding Eligibility: FULL			***OUTFALL INSPECTION INFORMATION***			
Estimated New Structure Length:	69 FT.				om o p	
Estimated Structure Cost:	\$358,731		# OUTFALLS	: INSPEC	CTOR:	
<b>Estimated Total Project Cost:</b>	\$538,097		STATUS	:	DATE:	
Year of Cost Estimate:	2025	<del></del>	NOTES	:		
NOTE: The above structure length and cost estimates are computer generated using algorithms in the TMS system. These algorithms are generalized to use NBI items to come up with a new structure length and width to calculate a new area which is taken times a representative cost per square foot. The actual structure size and cost may vary significantly from these numbers once site specific engineering is done.						



#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

March 13, 2025 4:57:21pm

COUNTY: MISSISSIPPI T0418 REVIEW STATUS: CONVERTED T **BRIDGE:** NBI STATUS: 3/7/2025 2025 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District 5B SE Route Signing Prefix MAINLINE MISSISSIPPI County 5C Designated Level of Service 00077 9131 8 Federal ID No. 5D Route Number 1935 NOT APPLICABLE 27 5E Year Built Directional Suffix 106 MO 77 S 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 21 Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance NOT ELIGIBLE FOR NR OF HP 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS 112 National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 270 4 Place MISSISSIPPI 29 AADT 2024 48926 Code 30 AADT Year ONE LANE BRIDGE FOR 2-WAY S 3 T 25 N R 17 E Location 102 Direction of Traffic 11 Milepoint 51.96 miles 25% 109 AADT Truck Percent 16 Latitude 36 D 50 M 6 S 378 114 Future AADT 17 Longitude 89 D 12 M 42 S 2044 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 LATERAL DTCH #3 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 By pass Detour Length 21.25 miles Type of Service Under 00 20 Ft. 0 In. 28B Lanes Under Structure 32 Approach Roadway Width N/A 0.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B NO Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 20 Ft. 0 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 44 Ft. 11 In. 46 Ft. 11 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 20 Ft. 0 In. 40 Nav Horizontal Clear 51 21 Ft. 4 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck



#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

March 13, 2025 4:57:21pm

COUNTY: MISSISSIPPI BRIDGE: T0418 REVIEW STATUS: CONVERTED NBI STATUS: T
RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 3/7/2025 SUBMITTAL YEAR: 2025

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT	RUN DATE: 3///2025 SUBMITTAL YEAR: 2025					
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION					
LOAD RATING AND POSTING INFORMATION  31 Design Load H 10  41 Structure Status POSTED FOR LOAD  63 Oper. Rating Meth. LOAD FACTOR  64 Operating Rating 18 Tons.  65 Inventory Rating Meth LOAD FACTOR  66 Inventory Rating 11 Tons.  70 Bridge Posting Code 30.0-39.9% BELOW  PROPOSED IMPROVEMENT INFORMATION  Sufficiency Rating 47.2 Percent STRUCTURAL	MATERIAL/CONSTRUCTION INFORMATION  43A Main Struc. Mat type STEEL  43B Main struc Constr. Type STRINGER/MULTIBEAM - GRD  45 # of Main Spans 1  44A Appr Struc. Mat type 000  44B Appr Struc. Cnstr. type 000  46 # of Approach Span 0  107 Deck Mat/Constr. 1 CONCRETE CIP  108A Wear Surf Mat/Constr. 6 BITUMINOUS  108B Membrane Mat/Constr. 7 INTERNALLY SEALED					
Funding Eligibility FULL	CONDITION RATING INFORMATION					
75A Proposed Work REPLACEMENT SUBSTND LOAD  75B Work Done By Contract  76 New Struc Length 68 Ft. 11 In.  94 Struc Improve Cost \$359,000  95 Roadway Improve Cost \$36,000	58         Deck Cond. Rating         5           59         Superstructure Cond. Rating         5           60         Substructure Cond. Rating         6           61         Channel /Channel Protection Cond. Rating         6           62         Culvert Cond. Rating         N					
96 Total Project Cost \$ 538,000						
97 Year of Cost Estimates 2025	INSPECTION INFORMATION					
APPRAISAL RATING INFORMATION  36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND  36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND  36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND  36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND  67 Struc Eval App. Rating 2  68 Deck Geometry App. Rating 4  69 Underclearance App. Rating N  71 Waterway Adeq. App. Rating 8  72 Approach Road App. Rating 8  113 Scour Assess App. Rating 8	90 Gen. Insp Date 11 / 24  91 Gen. Insp. Frequency 12 Months  92A Frac. Critical Inspection N Months  93A Frac. Critical Insp. Date  92B Underwater Inspection N Months  93B Underwater Insp. Date  92C Special Inspection N Months  93C Special Inspection Date  BORDER BRIDGE INFORMATION  98 Neighboring State Code  98B Neighboring State % Respon  99 Neighboring State Struc. No.					
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION					
Approved Posting Category S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 15 19 35  General Text for Posting Sign	Field Posting Category S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 15 19 35  General Text for Posting Sign					
CL OF BR AND TRK OVR 15 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 19 T OTHR TRKS WT LMT 35 T.	CL OF BR AND TRK OVR 15 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 19 T OTHR TRKS WT LMT 35 T.					

Design\_No = T0418 and Inventory\_Appraisal\_Submittal\_Year = 2025