



# I-55 West Outer Road At Rock Creek

## *Bridge Replacement Project*



Years of moisture have caused extensive deterioration to the underside of the Rock Creek Bridge.



The concrete on the sides and under the bridge itself is cracking. Excessive rust has corroded the structural steel beams under the bridge.