

2'-8" BLOCKOUT






Include this note (I1.62) on plans when asbestos is present between rail posts and top of parapet:

Asbestos (Friability Category II NF) has been detected in the insulation compound between the top of the existing concrete parapet and the base of the existing handrail posts. The contractor has the option to remove the handrail and posts or leave in place. Should the contractor elect to remove the handrail and posts, the contractor will be required to use a licensed abatement contractor during the removal. No direct payment will be made for removal of the handrail and posts, or for asbestos abatement. The described work will be considered completely covered by the contract unit price for other items in the contract.

SECTION THRU SAW CUT JOINT



\$\frac{3}{3} \ \frac{1}{2} \ \