


FED. ROAL STATE FED. AID FISCAL SHEET TOTAL DIST. NO. PROJ. NO. YEAR NO. SHEETS MO. 5.J-33 19



Note: Dimensions are given along centerline of bars and are for computed lengths. Reinforcing bars #"or over in diameter, which are bent to an angle greater than 90°, shall be of structural

ES	TIMATED	QUANTITIES			FINAL QUAN.
Item		Superstruct	Substructure	Total	CZUITY.
Excavation Class I	Cu.Yds.	`	25	25	30-
Excavation Class II	Cu. Yds.		76	76	76.
Concrete 1.2.4mix "B"	Cu. Yds		53.7	53.7	53.7
Concrete 1:2:32 mix "X"	Q: Yds.	68.4		68.4	68.4
Fabricated Structural Steel	Lbs.	<i>58 400</i>		5840CI	
Reinforcina Steel	Lbs.	17 720	6250	23970	23470
Heating Concrete	Su Yds				46.8
brilling Test hules _	115 FI				10.

Note: Bridge excavation above Elex. 1135.0 will be paid for as Class I Bridge Excavation. Bridge excavation below Elev. 1135.0 will be paid for as Class II Bridge Excavation.

B.M.Elev. 1137.33 - Nail in side 16" Sycamore 130' Rt Sta. 336+35.

#### BRIDGE OVER PINE CREEK

STATE ROAD FROM WILLOW SPRINGS TO ROUTE 17 ABOUT 6.5 MILES N.E. OF WILLOW SPRINGS

PROJECT NO. S.J.-S3

STA. 334 + 87. 5

SUBMITTED BY
SUBMITTED BY
APPROVED BY
APPR

Revetment Fill under and in front of end bents to be firmly tamped FRONT OF END BENTS SIDE SLOPES OF FILL Heavy stone revetment shall be placed on fill at end or bridge as shown in startches. Approximately 100 59, yds. of heavy stone revetment work included in road

LOCATION SKETCH

roposed Bridge

1. Roadway 7

ETangent to & Roadway at 5ta.335 t 59.06.

HEAVY STONE REVETMENT

rainr. snop, Mone.
Field; Surfaces inaccessible after erection, three coats of red lead; contact surfaces with bolted field connections, one coat of red lead. No other paint to be applied by contrator All paint required will be furnished by the Missouri State Highway. Department.

Cost of metallic edge moulding will be included in unit bid price for concrete.


Miere rubber compound is specified on plans for use in partition and expansion joints, the premoulded joint shall be securely stitched to one face of concrete with copper vire.

Bridge excavation in accordance with Section I of Standard Specifications issued April 1, 1930.

Drawn Oct. 1932 By N.W.R. Traced Oct. 1932 By H.W.H. Checked Nov. 1932 By 1.B.


P.I. Sta. 337+58.i A-Gl\*40'Lt. D-5\* T-684.2' L-12**33**3' R-146.3'

5ta.334+87.5-




60

THPERIAL" TRACING CL



MPIRIAL" TRACING CL. A. R. ALOT CO. ST. LOUIS



ERIAL" TRACING CLOT

. ..



December 21, 2022 10:26:45AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528

\*\*\*GENERAL STRUCTURE INFORMATION\*\*\* \*\*\*BRIDGE INSPECTION INFORMATION\*\*\* ROUTE: MO137S # **SPANS**: 3 PLACE CODE: 57476 PIERCE **RESPONSIBILITY: DISTRICT DATE:** 11/07/2022 LANES ON: 2 FEATURE: PINE CR LENGTH: 143 FT 0 IN FREQUENCY: 12 CALCULATED INTERVAL\*\*: 12 LANES UNDER: 0 **STATUS:** P-POSTLOAD MAXIMUM SPAN: 49 FT 0 IN **TEAM LEADER: ED HESS ELEMENT: NO LOG MILE: 36.004 COMPASS DIRECTION: WEST to EAST** APPROACH ROADWAY: 20 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR: 22.00 MILES DIRECTION OF TRAFFIC: 2-WAY TRAF CURB TO CURB: 20 FT 0 IN INSPECTOR 3: OUT TO OUT:** 21 FT 0 IN NHS: NO FUNCTIONAL CLASS: RL-MAJOR COLLECTOR \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. **AADT:** 550 **BUILT:** 1932 **NBI OWNER: MODOT GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2021** MAINTENANCE DISTRICT: SE LOCATION: S 34 T 28 R 9 W **AADT TRUCK:** 7.1% **LATITUDE:** 37 3 21.24 (DMS) **MAINTENANCE COUNTY: TEXAS FUTURE AADT: 770 LONGITUDE:** 91 54 31.56 (DMS) SUB AREA: 7H51 **FUTURE AADT YEAR: 2041** \*\*\*INDEPTH INSPECTION INFORMATION\*\*\* \*\*\*FRACTURE CRITICAL INSPECTION INFORMATION\*\*\* DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** \*\*\*SPECIAL INSPECTION INFORMATION\*\*\* \*\*\*UNDERWATER INSPECTION INFORMATION\*\*\* CATEGORY: CHANNEL CROSS SECT **DATE:** 11/07/2022 **CATEGORY: DRY DATE:** 06/13/2014 RESPONSIBILITY: DISTRICT **RESPONSIBILITY: DISTRICT** FREOUENCY: 120 **NBI:** NO FREOUENCY: 60 NBI: NO **CALCULATED INTERVAL\*\*:** CALCULATED INTERVAL\*\*: 12 **TEAM LEADER: ED HESS METHOD:** VISUAL **TEAM LEADER: INSPECTOR 3: METHOD:** WT TAPE **INSPECTOR 3: INSPECTOR 2:** ED HESS **INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS **DATE FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** 



December 21, 2022 10:26:45AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528

\*\*\*STRUCTURE POSTING\*\*\* **APPROVED CATEGORY: S-7** TRUCKS OVER 18 TONS 15 MPH ON BRIDGE. **Ton 2: Ton 3: Ton 1:** 18 **COMMENTS:** FIELD CATEGORY: S-7 TRUCKS OVER 18 TONS 15 MPH ON BRIDGE. **PROBLEM:** PROBLEM DIRECTION: **Ton 1:** 18 **Ton 2: Ton 3: COMMENTS:** \*\*\*GENERAL COMMENTS/MAJOR RATED ITEMS\*\*\* GENERAL COMMENTS: (BOWDEJ1, 01/06/2010)--(47'-49'-47') SMP WF GDR SPANS (CURVED) [ITEM 58] DECK: 4-POOR CONDITION COMMENTS: (BRAWLK1, 11/04/2021)--DECK BOLTED, SATURATION THROUGH OUT **RATING:** 11/04/2021 [ITEM 59] SUPER: 5-FAIR CONDITION COMMENTS: (SHRUBM1, 12/23/2011)--RUSTING OF TOP & BOTTOM FLANGES **RATING:** 11/16/2015 [ITEM 60] SUB: 4-POOR CONDITION COMMENTS: (STEGEC, 05/02/2005)--TWO BEARING SEATS AND ONE CAP END REPAIRED ON SOUTH BENT BY DIV. REPAIR CREW (HR2) IN 4 / 2005 **RATING:** 11/07/2022 [ITEM 61] BANK/CHANNEL: 6-WIDESPREAD MINOR DAMAGE **COMMENTS:** (DENNIB1, 11/05/2019)--MINOR EROSION ON BANK **RATING:** 11/05/2019 [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED **COMMENTS: RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: DECK/APPRCH OVERTOP SLIGT **COMMENTS: RATING:** 05/18/2001 [ITEM 72] APPRRDWY ALIGNMENT: 6-SATISFACTORY **COMMENTS: RATING:** 05/18/2001 \*\*\*RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS\*\*\* [ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 01/06/2010 **COMMENTS: DIRECTION MATERIAL CONSTRUCTION COMMENTS** REINFORCED CONCRETE **CURB BOTH** STEEL **BOTH** ANGLE-DOUBLE **COMMENTS: [ITEM 36B] TRANSITION RAILING RATING:** NOT PROVIDED-0 **RATING:** 05/18/2001 [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS: RATING:** 05/18/2001 [ITEM 36D] RAIL END TREATMENT RATING: NOT PROVIDED-0 **COMMENTS:** 

MODOT

## **Missouri Department of Transportation State Bridge Inspection Report**

**December 21, 2022** 10:26:45AM

**DISTRICT: SE** 

**CLASS: STATBR** 

**FED-ID: 8748** 

**BRIDGE: S0528** 

**COUNTY: TEXAS** APPROACH PAVEMENT: \*Overall condition assigned for each approach pavemenet component is shown below. **MATERIAL CONSTRUCTION DIRECTION CONDITION\* COMMENTS ASPHALT BITUMINOUS MAT BOTH** \*\*\*DRAINAGE, EXPANSION DEVICES, BANK/SLOPE, AND DECK PROTECTIVE COMPONENTS\*\*\* **DECK PROTECTIVE COMPONENTS:** SERIES TYPE-# **COMPONENT MATERIAL THICKNESS** YEAR APPLIED MANUFACTURE **OVERALL CONDITION** MAIN SERIES-1 WEARING SURFACE **ASPHALT** BITUMINOUS SEAL COAT 2.7 IN 2009 GOODCOMMENT: (BOWDEJ1, 04/28/2010)--SEALED IN 91- STRIPPING & MAT OVERLAY 2005 - CHIP SEAL OVER MAT OVERLAY 2009 NONE DECK PROTECTION *NOTAPPLICABLE* **COMMENT: NONE** *MEMBRANE NOTAPPLICABLE* **COMMENT: DRAINAGE COMPONENTS: COMPONENT MATERIAL CONSTRUCTION DIRECTION COMMENTS** DRAINAGE CURB OUTLET REINFORCED CONCRETE **EXPANSION DEVICE COMPONENTS: COMPONENT CONSTRUCTION** SUB UNIT-# SUB LABEL **MATERIAL** GAPYEAR APPLIED **MANUFACTURE OVERALL CONDITION** BENT-2 CLOSED EXPANSION JOINT **FELT** FILLED JOINT **COMMENT:** BENT-3 CLOSED EXPANSION JOINT FELTFILLED JOINT **COMMENT: BANK/SLOPE PROTECTION COMPONENTS: COMMENTS COMPONENT MATERIAL CONSTRUCTION DIRECTION** BANK PROTECTION ROCKGROUTEDBOTH\*\*\*DECK COMPONENTS\*\*\* **MATERIAL** SPAN TYPE-# **COMPONENT CONSTRUCTION COMMENTS** MAIN SPANS-1 CAST-IN-PLACE DECKREINFORCED CONCRETE **SEVERITY CONDITION** LOCATION 1 LOCATION 2 **MEASUREMENT COMMENT** AT ABUTMENTS **NTERIOR GIRDER BOLTED** EFFLORESCENCE THROUGHOUT **MODERATE FULL DEPTH PATCHES** THROUGHOUT FEW **MODERATE** 60 % SATURATION THROUGHOUT TRANSVERSE CRACKS THROUGHOUT MANY MAIN SPANS-2 DECKREINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT EFFLORESCENCE** THROUGHOUT **MODERATE** 

December 21, 2022 10:26:45AM

## **Missouri Department of Transportation State Bridge Inspection Report**

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528

FULL DEPTH PATCHESTHROUGHOUTFEWSATURATIONTHROUGHOUTMODERATE

TRANSVERSE CRACKS THROUGHOUT MANY

MAIN SPANS-3 DECK REINFORCED CONCRETE CAST-IN-PLACE

<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>

BOLTED AT ABUTMENTS NTERIOR GIRDER EFFLORESCENCE THROUGHOUT MODERATE FULL DEPTH PATCHES THROUGHOUT FEW

SATURATION THROUGHOUT MINOR 20 %

TRANSVERSE CRACKS THROUGHOUT MANY

#### \*\*\*SUPERSTRUCTURE COMPONENTS\*\*\*

60 %

SERIES TYPE-#SPAN TYPEMATERIALCONSTRUCTIONLABELCOMMENTSMAIN SERIES-1SIMPLE SPANSTEELWIDE FLANGE GIRDERS

SPANCOMPOSITE INDICATORLENGTHWEATHERING STEELCOMMENTSMAIN SPANS-1NON-COMPOSITE47 FT 0 INNO

<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>

DECK LIFTING AT JOINTS MODERATE RUSTING AT JOINTS MODERATE RUSTING TOP FLANGE MODERATE

MAIN SPANS-2 NON-COMPOSITE 49 FT 0 IN NO

<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>

DECK LIFTINGAT JOINTSMODERATERUSTINGAT JOINTSMODERATERUSTINGTOP FLANGEMODERATE

MAIN SPANS-3 NON-COMPOSITE 47 FT 0 IN NO

<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>
DECK LIFTING

AT JOINTS

MINOR

RUSTING TOP FLANGE MODERATE

### \*\*\*SUBSTRUCTURE COMPONENTS\*\*\*

				SCESTRECTE	THE COMMITTEE THE		
<b>SUBSTRUCTURE</b>	<u>SKEW</u>	<u>LENGTH</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>	<u>LABEL</u> <u>COMMENTS</u>		
ABUTMENT-1	RA-11 DEGREES	22 FT 4 IN	REINFORCED CONCRETE	OPEN CONCRETE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<b>COMMENT</b>
<u>ASSOCIAT</u>	TED COMPONENT	<u>MAT</u>	<u>ERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CA	ΛP	REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<b>COMMENT</b>
	SEALED		BEAM CAP		ROOF FLEX		
COLUMN		REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<b>COMMENT</b>
STRAIGH	T WINGS	REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<b>COMMENT</b>
FOOTING	ł	REIN	FORCED CONCRETE	SPREAD			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
BACKWA	LL	REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
				<del></del>			

Design No = S0528

MODOT

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528

EXPANSION BEARING STEEL SLIDING CURVED/FLAT PL/

EXPANSIO	N BEARING	STEE	EL	SLIDING CURVED/FLAT PL			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
	RUSTING		THROUGHOUT		MODERATE		
BENT-2	RA-14 DEGREES	21 FT 8 IN	REINFORCED CONCRETE	MULTIPLE COLUMN			
BENT 2	CONDITION	2111 0111	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
4SSOCIATE	ED COMPONENT	MAT	ERIAL	CONSTRUCTION	<u>SE, ERITT</u>	MENSUREMENT	COMMENT
BEAM CAP			FORCED CONCRETE	CAST-IN-PLACE			
BEAM CAI	<b>CONDITION</b>	KEIN	LOCATION 1	LOCATION 2	<b>SEVERITY</b>	MEASUREMENT	COMMENT
		NIZ C		<u>LOCATION 2</u>		MEASUREMENT	COMMENT
	HORIZONTAL CRAC	KS	RANDOM		MEDIUM POOF FLEY		
COLUMN	SEALED	DEIN	BEAM CAP FORCED CONCRETE	CAST-IN-PLACE	ROOF FLEX		
COLUMN	CONDITION	KEIN			CEVEDITY	MEACHDEMENT	COMMENT
	<u>CONDITION</u>		LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	REBAR EXPOSED		RANDOM		MINOR		
FOOTNIC	VERTICAL CRACK		RANDOM	CDDEAD	MODERATE		
FOOTING	COMPUTION	KEIN	FORCED CONCRETE	SPREAD	CELEDITY	ME ACUDEMENT	COMMENT
	<u>CONDITION</u>	~~~	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSIO	N BEARING	STEE		SLIDING CURVED/FLAT PL	~		~~~
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	RUSTING		THROUGHOUT		MODERATE		
BENT-3	RA-16 DEGREES	21 FT 8 IN	REINFORCED CONCRETE	MULTIPLE COLUMN			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
<i>ASSOCIATE</i>	ED COMPONENT	MAT	ERIAL	<b>CONSTRUCTION</b>			
BEAM CAP	_	REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
	REBAR EXPOSED	)	BOTTOM		MODERATE		
	SEALED		BEAM CAP		ROOF FLEX		
	SPALLS		BOTTOM		MODERATE		
COLUMN		REIN	FORCED CONCRETE	CAST-IN-PLACE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	LOCATION 2	<b>SEVERITY</b>	<b>MEASUREMENT</b>	<u>COMMENT</u>
	VERTICAL CRACK	S	RANDOM	· · · · · · · · · · · · · · · · · · ·	MODERATE		
FOOTING			FORCED CONCRETE	SPREAD			
	<b>CONDITION</b>		<u>LOCATION 1</u>	LOCATION 2	<b>SEVERITY</b>	<b>MEASUREMENT</b>	<u>COMMENT</u>
EXPANSIO1	N BEARING	STEE	EL EL	SLIDING CURVED/FLAT PL			
	<b>CONDITION</b>		<u>LOCATION 1</u>	LOCATION 2	<b>SEVERITY</b>	<b>MEASUREMENT</b>	COMMENT
	RUSTING		THROUGHOUT		MODERATE		
ABUTMENT-4	<i>RA-19 DEGREES</i>	21 FT 8 IN	REINFORCED CONCRETE	OPEN CONCRETE			
ADOIMENT-4	<u>CONDITION</u>	2111 0111	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
ASSOCIATE	ED COMPONENT	MAT	ERIAL	<u>CONSTRUCTION</u>	<u>SEVERITT</u>	MEMBURENT	COMMENT
BEAM CAP			FORCED CONCRETE	CAST-IN-PLACE			
DEAW CAI	<b>CONDITION</b>	KEIIV	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED		BEAM CAP	<u>LOCATION 2</u>	ROOF FLEX	MEASUREMENT	COMMENT
COLUMN	SEALED	DEIN	FORCED CONCRETE	CAST-IN-PLACE	ROOF FLEA		
COLUMN	<b>CONDITION</b>	KEIN	LOCATION 1	LOCATION 2	CEVEDITV	<u>MEASUREMENT</u>	<u>COMMENT</u>
OTD A LOTTE		DED:			<u>SEVERITY</u>	MEASUREMENT	COMMENT
STRAIGHT		KEIN	FORCED CONCRETE	CAST-IN-PLACE	CEL/EDITU	MEACHDEMENT	COMMENT
FOOTBIC	<u>CONDITION</u>	DED	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING	COMPTEND	REIN	FORCED CONCRETE	SPREAD	CELIEDIEN	ME (CIDE) CONT	COMMENT
<b>.</b>	<u>CONDITION</u>		LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BACKWAL	L	REIN	FORCED CONCRETE	CAST-IN-PLACE			

MODOT

**December 21, 2022** 10:26:45AM

**COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528** 

**EXPANSION BEARING** 

LOCATION 1

LOCATION 2 **SEVERITY** 

STEEL

SLIDING CURVED/FLAT PLA

RIGHT LATERAL CLEARANCE

MEASUREMENT COMMENT

**CONDITION** 

**ROUTE** 

CONDITION

**RUSTING** 

**LOCATION 1 THROUGHOUT**  **LOCATION 2 SEVERITY** 

MEASUREMENT COMMENT

**MODERATE** 

\*\*\*OVER/UNDER ROUTES CLEARANCE INFORMATION\*\*\*

**CLEARANCES OVER DECK** 

MODOT

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

**VERTICAL CLEARANCE TYPE\*\*** 

**VALUE** 

**DIRECTION** 

DATE

**COMMENT** 

CLEARANCES UNDER BRIDGE

RECORD#

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

**LEFT LATERAL CLEARANCE** 

**UR-ID** 

**VERTICAL CLEARANCE TYPE\*\*** 

**VALUE** 

# LANES

**DIRECTION** 

**DATE** 

**DIRECTION OF TRAFFIC** 

**COMMENT** 

\*\*\*STRUCTURE PAINT INFORMATION\*\*\*

CONDITION:

**FAIR** 

**ORIGINAL PAINT** 

**RUST AMOUNT:** 6=1.0% OF SURFACE RUSTED

**CONTRACT REPAINT** 

STEEL TONS: 29

**DEPARTMENT REPAINT** 

**PAINT TYPE:** 

**PAINT TYPE:** 

**PAINT TYPE:** C SYSTEM

**MANUFACTURE:** 

NAME: **PAINT COLOR:**  NAME:

**NAME:** INORGANIC ZINC/VINYL

**SURFACE PREP:** 

**PAINT YEAR:** 

**PAINT COLOR: PAINT YEAR:** 

PAINT YEAR: 1999

**PAINT COLOR:** ALUMINUM

MILS:

MILS:

MILS: 8

\*\*\*REQUESTED WORK ITEMS\*\*\*

**GENERAL WORK COMMENTS:** 

RESPONSIBILITY

**LOCATION** 

**ITEM** 

**CATEGORY** 

**PRIORITY** 

**DATE** 

**WORK ITEM COMMENT** 

Design No = S0528



December 21, 2022 10:26:45AM

**COUNTY: TEXAS** 

**DISTRICT: SE** 

**CLASS: STATBR** 

**FED-ID: 8748** 

BRIDGE: S0528

UTILITY OWNER METHOD MEASUREMENT TYPE VALUE NUMBER UTILITY ATTACHMENT COMMENT

\*\*\*PROGRAM NOTES INFORMATION\*\*\*

\*\*\*UTILITY ATTACHMENTS\*\*\*

<u>YEAR</u> <u>PROJECT #</u> SE0027

MONTH LET

YEAR LET

ITEMS REPLACE BRIDGE **COMMENT** 


***COMP	UTER GENERATED RATINGS AND D	EFICIENCY ITEMS***	***ADVANCED SIGN INFORMATION***				
NOTE: The items listed in this section are u	pdated whenever computer edits are ran on a struct	ure after the inspection updates have been entered in to TMS.	SIGN#	SIGN TYPE	PROBLEM	PROBLEM DIRECTION	
Rated Item	Rating	Rating Date	1				
[Item 67] Structure Evaluation Rating:	2-BASICALLY INTOLRBLE REQ	2/17/2022					
[Item 68] Deck Geometry Rating:	3-BASICALLY INTOL CORRECT	3/25/2002					
[Item 69] Underclearance:	N-NOT APPLICABLE	5/18/2001					
Sufficiency Rating:	4.0%	11/10/2022					
Deficiency:	STRUCTURAL	4/2/2003					
Funding Eligibility:	FULL			***OUTFALL INSP	ECTION INFORMATIO	N***	
<b>Estimated New Structure Length:</b>	174 FT.					·	
<b>Estimated Structure Cost:</b>	\$1,009,026	<del></del>	# OUTFALLS:	IN	SPECTOR:		
<b>Estimated Total Project Cost:</b>	\$1,513,539		STATUS:		DATE:		
Year of Cost Estimate:	2022		NOTES:				
generalized to use NBI items to come up with	stimates are computer generated using algorithms a new structure length and width to calculate a new t may vary significantly from these numbers once s	v area which is taken times a representative cost per					



December 21, 2022 10:26:45AM

OUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8748 BRIDGE: S0528


 $Design\_No = S0528$ 





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS S0528 REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 11/10/2022 2022 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District 5B SE Route Signing Prefix MAINLINE **TEXAS** County 5C Designated Level of Service 00137 8748 8 Federal ID No. 5D Route Number 1932 NOT APPLICABLE 27 5E Year Built Directional Suffix MO 137 S 106 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 21 Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance HISTORICAL SIGNIF UNKNWN 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 550 4 Place PIERCE 29 AADT 57476 2021 Code 30 AADT Year 2-WAY TRAFFIC S 34 T 28 N R 9 W Location 102 Direction of Traffic 11 Milepoint 36.21 miles 7% 109 AADT Truck Percent 16 Latitude 37 D 3 M 21 S 770 114 Future AADT 17 Longitude 91 D 54 M 32 S 2041 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 PINE CR 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 21.88 miles Type of Service Under By pass Detour Length 00 28B Lanes Under Structure 32 Approach Roadway Width 20 Ft. 0 In. N/A 15.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 20 Ft. 0 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 48 Ft. 11 In. 143 Ft. 1 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 20 Ft. 0 In. 40 Nav Horizontal Clear 51 20 Ft. 12 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck






#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS BRIDGE: S0528 REVIEW STATUS: APPROVED NBI STATUS: T

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 11/10/2022 SUBMITTAL YEAR: 2022

RECORD TYPE: ROUTE CARRIED ON STRUCT	RUN DATE: 11/10/2022 SUBMITTAL YEAR: 2022
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION
31 Design Load H 10 41 Structure Status POSTED FOR LOAD 63 Oper. Rating Meth. ALLOWABLE STRESS 64 Operating Rating 22 Tons. 65 Inventory Rating Meth ALLOWABLE STRESS 66 Inventory Rating 11 Tons. 70 Bridge Posting Code 20.0-29.9% BELOW  PROPOSED IMPROVEMENT INFORMATION  Sufficiency Rating 4.0 Percent STRUCTURAL Funding Eligibility FULL	43A   Main Struc. Mat type   STEEL     43B   Main struc Constr. Type   STRINGER/MULTIBEAM - GRD     45
75A Proposed Work REPLACEMENT SUBSTND LOAD  75B Work Done By Contract  76 New Struc Length 173 Ft. 11 In.  94 Struc Improve Cost \$1,009,000  95 Roadway Improve Cost \$101,000	58         Deck Cond. Rating         4           59         Superstructure Cond. Rating         5           60         Substructure Cond. Rating         4           61         Channel /Channel Protection Cond. Rating         6           62         Culvert Cond. Rating         N
96 Total Project Cost \$ 1,514,000 97 Year of Cost Estimates 2022	INSPECTION INFORMATION
APPRAISAL RATING INFORMATION  36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND  36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND  36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND  36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND  67 Struc Eval App. Rating 2  68 Deck Geometry App. Rating 3  69 Underclearance App. Rating N  71 Waterway Adeq. App. Rating 6  72 Approach Road App. Rating 6  113 Scour Assess App. Rating 8	90 Gen. Insp Date 11 / 22  91 Gen. Insp. Frequency 12 Months  92A Frac. Critical Inspection N Months  93A Frac. Critical Insp. Date  92B Underwater Inspection N Months  93B Underwater Insp. Date  92C Special Inspection N Months  93C Special Inspection Date  BORDER BRIDGE INFORMATION  98 Neighboring State Code  98B Neighboring State % Respon  99 Neighboring State Struc. No.
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION
Approved Posting Category S-7  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 18  General Text for Posting Sign  TRUCKS OVER 18 TONS 15 MPH ON BRIDGE.	Field Posting Category S-7  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 18  General Text for Posting Sign  TRUCKS OVER 18 TONS 15 MPH ON BRIDGE.

Design\_No = S0528 and Inventory\_Appraisal\_Submittal\_Year = 2022



## MISSOURI STATE HIGHWAY DEPARTMENT

No. Size Length Mark Location

3"\$ 7'9" FE

End Bents No. 185 5'9" DI Footing

3"4 11'6" HI Wing

### 22'3" H3 Beam
### 20'0" H4 ??

### 22'3" H5 ??

13'9" 71 Wing

3"4 21'0" T2 Backwall \$"\$ 7'6" VI Wing \$"\$ 6'0" V2 " \$"\$ 10'0" V3 Beam

10 \$\frac{3}{2}\tau 22.9\tau V4 Column Bent\tau 40 \$\frac{3}{2}\tau 4'-6" V5 Backwall

12 \$\frac{3}{2}\tau \tau 6'-0" V6 Haunch

10 \$\frac{3}{2}\tau 17'-9\tau V7 Col. Bent\tau 5

Interior Bents No. 2,384


3"4 16'5" P3 >> >> #3 3"4 17'9" P4 >> >> #4

69 2"\$ 8'6" U2 Beams

Haunch

-Metallic Edge Moulding 8 Layers of Roofing Felt 24"0.00 8"x1"x10" Bearing Plate - ½"Grout 3" Anchor Bolt, No Head, Hex. Nut.

SECTION THRU BENT NO.1 AT &



SECTION THRU	INTERIOR	BENT AT &
--------------	----------	-----------

						,,,,,,		.INF										
NO.	512	Έ	LEN	GTH	M.	4RK	LOCA	710.V				BEN	DING	SKET	CH			
"A"	5	P	"E	77		C)	Cui	-b			2	*	305					
"C"	3"	ø	2'-	0"		C2	• •	'				6)	-34	121				
0"	31	ø	204		Τ.	51	Sla	ь			4		<i>§</i> "	2	C S			
E"	30	ø	"F	"	3	52	9 1	9					2					
		5/	NGLE	SP	4//		Γ_	OILE		D 5P	AN			ONE		. <i>5P.</i>	<u>4N</u>	
PAN	"A"	"B"			"E"	"F"	<b>"</b> 4"	<i>"B</i> "	"C"	"D"	"E"	"F"	"A"	"B"	"C"			
520"	8		24		26		8		22		26		3_	14-9"	20	64	26	14-9
7-1"	8		28		26		8		24		26		8	16'9"	20	74	26	16-9
9-0"	8		28		26		8		28		26		8	18-9"	28	84	26	18-9
120"	8		30		26		8		28		26		8	2029"	26	92	26	2019 2219
3-0"	8		36		26		8		34		26		8	22'9"	32	100	26	24-9
5-0"	8		36		26		3		36	<u> </u>	26		8	24'9"	36	110	26	26-9
27-0"	8		36		26		8		34		25		8	26-9"	32	118	26	28-9
9-0"	8		44		26		8	Ĺ	42		26	Ì	8	28-9"	40	126	26	3019
31-0"	8		144		26		8		44	L	26		8	30-9"	44	134	52	17:6
33-0"	16		52	<u> </u>	52	L	16	ļ	50		52		16	17-6"	48	154	52	18-6
35 <del>'</del> 0"	16		52	L	52	ļ	16	<u> </u>	50	ļ	52		16	19-6"	48	164	52	1916
37-0"			52	<u> </u>	52		16		50		52	<del> </del>		20'6"	56	172	52	20-6
3940"		L	60		52		16	ļ	5.R	<u> </u>	52	<b>L</b>	16	21-6"	56	180	52	21-6
1/- 0"	16		60	L	52	l	16	<u> </u>	53	<b>⊢</b> −	52 52		16	22'6"	56	190	52	224
1340"	16		60	L_	52		16	<u> </u>	58		52	<del> </del>	16	2346"	64	198	52	23-6
<u> 520"</u>	16	<u> </u>	68	<u> </u>	52	ļ	1_	<del> </del>	66		52	<b>├</b> ──	16	24-6"	64	24	52	24-6
7 <u>'0"</u> 19 <u>'</u> 0"	16		68	<u> </u>	52		16	26'6		222		26:6	310	25-6"	64	216	52	25-6

BILL OF REINFORCING STEEL-SUBSTRUCTURE

7'3" 10'9"

/8<sup>4</sup>0"

S-H2,CUT 10 BARS

, '6"

6-VICUTIZBARS

7'3"

Note: Dimensions of bars are given along & and are for computed lengths. Reinforcing bars & or over in dimeter, which are bent to an angle great of than 90°, Enall be of st. setural grade.

F3

19'-8"

8" 21"

Bending sketches and Cutting viagroms


2'3"

VЗ

Note : Reinforcing bars in each span to be billed and tagged separately.

Hetallic Edge Moulding 3 Loyers of Foofing Felt 1-6 16 1×5 2 1-8" × 10"Bevel # --8" × 1" × 10" Brg. # .-2" Grout ---112 GZ Ind Anchor Bolt-No Head, Hex, Nut. P 18"0 0 12"

SECTION THRU BENT NO.5 AT &



ANCHOR BOLT PLAN

Designed Nov. 1929 By F.W.H.
Drawn Dec. 1930 By R.J.G. Assembled Oct. 1932 By R.R.C.-H.E.U.
Traced Dec. 1931 By R.J.G. Checked Oct. 1932 By A.F.K.
Checked Dec. 1931 By J.H.M.

Note: This drawing is not to scale.

F2

1/46° 20 T1 1/23° 40'

12"


135°-7

146°10'

FED RO. D STATE FED AID FISCAL SHEET TOTAL DIST NO. PROJ. NO YEAR NO. SHEETS MO. 5J-54 19

PIECE		LOCATION	NO DOC	SIZE	LENGTH	REMARKS
PIECE	+	LUGATION	NU.FGS.	SIZE	LENGIN	F.L. MAKNO
oacer Bo	75	Spans 15' to 31' Incl.	48	3"¢	Varies	
oacer Boi	175	5pans 33' to 49'Incl.	<i>34</i> =	344	Karies	Hachine Ballywasher für nat
endrail [		Spans 15'	16	2.0	6"	Sq. hds., washers, hex. nuts.
••	,,	to 19'Incl.	32	5.10	14"	Button heads.
11	"	Spans 21'	20	8110	6"	Sq. hds., washers, hex. nuts.
**	••	to 25'Incl.	40	3110	6"	Button heads.
**	"	Spans 27'	24	3"4		Sg hds., washers, hex. nuts. Button heads.
	"	to 31' Incl.	48 28	3110	6"	Sq. hds., washers, hex. nuts.
	97	Spans 33' to 37'Incl.	56	3110	14"	Button heads
	77	ל 39 מחניעל '10 מחניעל '15 מחניעל	32	5110	6"	Sq. hds., washers, hex. nuts.
- 77	**	to 43' Incl.	64	310	14"	Button heads.
	",	Spans 45	36	3.4	6"	59. hds., washers, hex nuts.
59	,,	to 49'incl.	16	310	14"	Button heads. +
Arrichor 3		Bearing Pls	16	30	14"	No Hds. Hex nut-Bevel was
				$\Box$		
Spacer Bo	o//s	Spans 15' to 31'Incl.	48	3"4	Varies	
Sparer Bo	0//5	Spans 33'	£#	3.4	100-105	Hochine Salls, washer for nut
·		to 49'Incl.	10	300	6	59 hds., washers, hex nuts.
Handraii L	**	to 19'Incl.	12 32	3/10	124"	Button heads.
	77	Spans 2/	16	300	6"	59. hus., washers, hex.nuts.
	77	to 25 incl.	40	3110	14"	Button heads.
<del></del>	1,	Spans 2'1'	20	2110	6"	5q. hds., washers, hex. nuts.
90	7,	to 31'Incl.	48	310	14"	Button heads.
7,	•••	Spans 33'	24	3110	6"	5q. nds., washers, hex.nuts.
21	,,	to 37'Incl	56	3"4	14"	Button heads.
99	99	Spans 39	28	3.10	6"	Sq. hds., washers, hex. nuts.
• •	,,	to 43'Incl.	64	\$110	14"	Button heads.
,,	45	Spans 45'	32	\$".0 500	6'	Sq. hds., washers, hex. nuts
9.	**	to 49 Incl.	72		14"	No Hds. Hex nut-Bevel wash
Archor B	0/15	Bearing Pls	. 16	160	14"	IVO MUS. HEN TIUT-DEVEL WUSIE
		<u> </u>	┼		<del></del>	<del> </del>
		<b></b>	┼	+	+	<del> </del>
		ļ	+-	+	+	+
		<del> </del> -	+	† —	+	

\* Total for entire bridge.



Note: Use bevel as shown for exposed faces of all joints consisting of rubber compound except at top surface of radway slab. Use edgins tool with a radius aftop surface of roadway each side of rubber compound joint.

DETAILS OF BEVEL FOR RUBBER COMPOUND JOINTS


## BRIDGE OVER SOUTH FORK OF JACKS FORK

STATE ROAD FROM WILLOW SPRINGS TO ROUTE 17 ABOUT II MILES N.E. OF WILLOW SPRINGS STA. 565 +47.5 PROJECT NO. SJ-S4


TEXAS ENISHED COUNTY

S-529

Sheet No. 2 of4.



Assembled Oct. 1932 by R.R.C.-H.E.U. Theched Oct. 1932 by A.F.K. Drawn Nov. 1930 by C.A.F.



ング



December 21, 2022 10:28:39AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8749 BRIDGE: S0529

\*\*\*GENERAL STRUCTURE INFORMATION\*\*\* \*\*\*BRIDGE INSPECTION INFORMATION\*\*\* ROUTE: MO137S # **SPANS**: 4 PLACE CODE: 57476 PIERCE **RESPONSIBILITY: DISTRICT DATE:** 11/07/2022 LANES ON: 1 FEATURE: S FK JACKS FK RVR LENGTH: 200 FT 0 IN FREQUENCY: 12 CALCULATED INTERVAL\*\*: 12 LANES UNDER: 0 **STATUS: P-POSTLOAD** MAXIMUM SPAN: 51 FT 0 IN **TEAM LEADER: ED HESS ELEMENT: NO LOG MILE: 31.678 COMPASS DIRECTION:** SOUTH to NORTH APPROACH ROADWAY: 20 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR: 22.00 MILES DIRECTION OF TRAFFIC: 1-LN/2-WAY** CURB TO CURB: 20 FT 0 IN **INSPECTOR 3: OUT TO OUT:** 21 FT 0 IN NHS: NO FUNCTIONAL CLASS: RL-MAJOR COLLECTOR \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1932 **NBI OWNER: MODOT AADT: 204 GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2021** MAINTENANCE DISTRICT: SE LOCATION: S 19 T 28 R 8 W **AADT TRUCK: 10.3% LATITUDE:** 37 5 23.65 (DMS) **MAINTENANCE COUNTY: TEXAS FUTURE AADT: 286 LONGITUDE:** 91 51 51.55 (DMS) SUB AREA: 7H51 **FUTURE AADT YEAR: 2041** \*\*\*INDEPTH INSPECTION INFORMATION\*\*\* \*\*\*FRACTURE CRITICAL INSPECTION INFORMATION\*\*\* DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** \*\*\*SPECIAL INSPECTION INFORMATION\*\*\* \*\*\*UNDERWATER INSPECTION INFORMATION\*\*\* **DATE:** 07/07/2020 **CATEGORY:** CHANNEL CROSS SECT **DATE:** 11/07/2022 **CATEGORY: DRY RESPONSIBILITY: DISTRICT RESPONSIBILITY: DISTRICT NBI:** NO FREOUENCY: 60 NBI: NO FREOUENCY: 72 CALCULATED INTERVAL\*\*: 73 CALCULATED INTERVAL\*\*: 12 **TEAM LEADER: ED HESS** TEAM LEADER: ED HESS **INSPECTOR 3: METHOD:** WT TAPE **INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS DATE **FREQUENCY CATEGORY** CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** NO 01/27/2016 **QUALITY** DISTRICT **ASSURANCE** 



December 21, 2022 10:28:39AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8749 BRIDGE: S0529

\*\*\*STRUCTURE POSTING\*\*\* **APPROVED CATEGORY:** S-17 CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T. **Ton 1:** 16 **Ton 2:** 22 **Ton 3:** 39 **COMMENTS:** FIELD CATEGORY: S-17 CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS **PROBLEM:** PROBLEM DIRECTION: **Ton 1:** 16 **Ton 2:** 22 **Ton 3:** 39 **COMMENTS:** \*\*\*GENERAL COMMENTS/MAJOR RATED ITEMS\*\*\* GENERAL COMMENTS: (BOWDEJ1, 08/28/2008)--(51'-49'-49'-51') SMP WF GDR SPANS [ITEM 58] DECK: 4-POOR CONDITION COMMENTS: (BRAWLK1, 11/04/2021)--PATCHINGD & SATURATION **RATING:** 11/04/2021 [ITEM 59] SUPER: 5-FAIR CONDITION **COMMENTS:** (DENNIB1, 11/13/2013)--RUSTING TOP FLANGES **RATING:** 11/16/2015 [ITEM 60] SUB: 6-SATISFACTORY CONDITION COMMENTS: (DENNIB1, 11/05/2019)--DIAG. CRACKS **RATING:** 11/05/2019 [ITEM 61] BANK/CHANNEL: 5-MAJOR DAMAGE COMMENTS: (DENNIB1, 11/29/2017)--EROSION ON BOTH SLOPES **RATING:** 11/29/2017 [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED **COMMENTS: RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: DECK/APPRCH OVERTOP SLIGT **COMMENTS: RATING:** 05/18/2001 [ITEM 72] APPRRDWY ALIGNMENT: 6-SATISFACTORY **COMMENTS: RATING:** 05/18/2001 \*\*\*RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS\*\*\* [ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 01/06/2010 **COMMENTS: DIRECTION MATERIAL CONSTRUCTION COMMENTS** REINFORCED CONCRETE **CURB BOTH** STEEL **BOTH** ANGLE-DOUBLE **COMMENTS: [ITEM 36B] TRANSITION RAILING RATING:** NOT PROVIDED-0 **RATING:** 05/18/2001 [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS: RATING:** 05/18/2001 [ITEM 36D] RAIL END TREATMENT RATING: NOT PROVIDED-0 **COMMENTS:** 

**December 21, 2022** 10:28:39AM

**DISTRICT: SE CLASS: STATBR FED-ID: 8749** 

**COUNTY: TEXAS BRIDGE: S0529** APPROACH PAVEMENT: \*Overall condition assigned for each approach pavemenet component is shown below. **MATERIAL CONSTRUCTION DIRECTION CONDITION\* COMMENTS ASPHALT BITUMINOUS MAT BOTH** \*\*\*DRAINAGE, EXPANSION DEVICES, BANK/SLOPE, AND DECK PROTECTIVE COMPONENTS\*\*\* **DECK PROTECTIVE COMPONENTS:** SERIES TYPE-# **COMPONENT MATERIAL THICKNESS OVERALL CONDITION** YEAR APPLIED MANUFACTURE MAIN SERIES-1 WEARING SURFACE **ASPHALT** BITUMINOUS SEAL COAT .3 IN 2008 *FAIR* **COMMENT:** DECK PROTECTION *NOTAPPLICABLE* NONE **COMMENT:** NONE*MEMBRANE NOTAPPLICABLE* **COMMENT: DRAINAGE COMPONENTS: COMPONENT MATERIAL CONSTRUCTION DIRECTION COMMENTS** DRAINAGE CURB OUTLET REINFORCED CONCRETE **EXPANSION DEVICE COMPONENTS: COMPONENT CONSTRUCTION** SUB UNIT-# SUB LABEL **MATERIAL** GAPYEAR APPLIED **MANUFACTURE OVERALL CONDITION COMMENT: BANK/SLOPE PROTECTION COMPONENTS: COMPONENT MATERIAL CONSTRUCTION DIRECTION COMMENTS BANK PROTECTION** ROCKGROUTEDBOTH\*\*\*DECK COMPONENTS\*\*\* SPAN TYPE-# **COMPONENT CONSTRUCTION MATERIAL COMMENTS** MAIN SPANS-1 DECKREINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT NTERIOR GIRDER BOLTED TOP FLANGE MINOR DELAMINATION** THROUGHOUT **FEW** EFFLORESCENCE THROUGHOUT **MODERATE PATCHES THROUGHOUT** 30 % SATURATION THROUGHOUT **MINOR** TRANSVERSE CRACKS THROUGHOUT MANY MAIN SPANS-2 DECK REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT BOLTED** TOP FLANGE **NTERIOR GIRDER** MINOR **DELAMINATION** THROUGHOUT **EFFLORESCENCE** THROUGHOUT **FEW MODERATE PATCHES** THROUGHOUT

Design No = S0529

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8749 BRIDGE: S0529

SATURATION THROUGHOUT MINOR 30 %

MANY TRANSVERSE CRACKS THROUGHOUT MAIN SPANS-3 DECKREINFORCED CONCRETE CAST-IN-PLACE LOCATION 1 **SEVERITY CONDITION LOCATION 2 MEASUREMENT COMMENT** TOP FLANGE **NTERIOR GIRDER BOLTED MINOR DELAMINATION** THROUGHOUT THROUGHOUT EFFLORESCENCE **FEW FEW PATCHES THROUGHOUT** SATURATION **THROUGHOUT MINOR** 10 % TRANSVERSE CRACKS THROUGHOUT MANY

MAIN SPANS-4 DECK REINFORCED CONCRETE CAST-IN-PLACE

SPAN TYPE

SIMPLE SPAN

**CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT BOLTED TOP FLANGE NTERIOR GIRDER DELAMINATION** THROUGHOUT **MINOR EFFLORESCENCE** THROUGHOUT **FEW FEW PATCHES** THROUGHOUT **MINOR** 10 % SATURATION THROUGHOUT TRANSVERSE CRACKS THROUGHOUT MANY

\*\*\*SUPERSTRUCTURE COMPONENTS\*\*\*

<u>CONSTRUCTION</u>
<u>LABEL</u>

WIDE FLANGE GIRDERS

**COMMENTS** 

**COMPOSITE INDICATOR SPAN LENGTH WEATHERING STEEL COMMENTS** MAIN SPANS-1 NON-COMPOSITE 51 FT 0 IN NO **SEVERITY CONDITION** LOCATION 1 LOCATION 2 **MEASUREMENT COMMENT** RUSTING **TOP FLANGE MODERATE** SECTION LOSS **TOP FLANGE MODERATE** 49 FT 0 IN MAIN SPANS-2 NON-COMPOSITE NO **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT RUSTING TOP FLANGE MODERATE** SECTION LOSS **TOP FLANGE MODERATE** MAIN SPANS-3 NON-COMPOSITE 49 FT 0 IN NO LOCATION 2 **CONDITION LOCATION 1 SEVERITY MEASUREMENT COMMENT** RUSTING **TOP FLANGE MODERATE** SECTION LOSS **TOP FLANGE MODERATE** MAIN SPANS-4 NON-COMPOSITE 51 FT 0 IN NO **CONDITION LOCATION 1** LOCATION 2 **SEVERITY COMMENT MEASUREMENT** RUSTING **TOP FLANGE MODERATE** SECTION LOSS **ENDS MODERATE** SECTION LOSS **TOP FLANGE MODERATE** 

\*\*\*SUBSTRUCTURE COMPONENTS\*\*\*

SUBSTRUCTURESKEWLENGTHMATERIALCONSTRUCTIONLABELCOMMENTSABUTMENT-120 FT 6 INREINFORCED CONCRETEOPEN CONCRETE

**MATERIAL** 

STEEL

MODOT

SERIES TYPE-#

MAIN SERIES-1

**COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8749 BRIDGE: S0529** CONDITION LOCATION 2 SEVERITY MEASUREMENT COMMENT LOCATION 1 ASSOCIATED COMPONENT **MATERIAL CONSTRUCTION** BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY** MEASUREMENT COMMENT **SEALED** BEAM CAP ROOF FLEX COLUMN REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 2 **SEVERITY MEASUREMENT COMMENT LOCATION 1** STRAIGHT WINGS REINFORCED CONCRETE **CAST-IN-PLACE CONDITION LOCATION 1 LOCATION 2 SEVERITY** <u>MEASUREMENT</u> <u>COMMENT</u> **BROKEN** TOP OFF **FOOTING** REINFORCED CONCRETE SPREAD **CONDITION** LOCATION 2 **SEVERITY LOCATION 1** MEASUREMENT COMMENT BACKWALL CAST-IN-PLACE REINFORCED CONCRETE **COMMENT CONDITION LOCATION 1 LOCATION 2 SEVERITY** *MEASUREMENT* SLIDING FLAT PLATE **EXPANSION BEARING** STEEL **CONDITION LOCATION 1 LOCATION 2 SEVERITY** <u>MEASUREMENT</u> <u>COMMENT</u> PACK RUST **BOTTOM** HEAVY BENT-2 20 FT 6 IN REINFORCED CONCRETE MULTIPLE COLUMN **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY** MEASUREMENT COMMENT ASSOCIATED COMPONENT **MATERIAL CONSTRUCTION** BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY** MEASUREMENT **COMMENT SEALED** BEAM CAP ROOF FLEX COLUMN CAST-IN-PLACE REINFORCED CONCRETE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT** HIGH STEEL SPALLS **FEW** RANDOM **FOOTING** REINFORCED CONCRETE SPREAD **CONDITION LOCATION 2 SEVERITY LOCATION 1** MEASUREMENT **COMMENT EXPANSION BEARING** STEEL SLIDING FLAT PLATE **CONDITION LOCATION 1 LOCATION 2 SEVERITY** COMMENT MEASUREMENT BENT-3 20 FT 6 IN REINFORCED CONCRETE MULTIPLE COLUMN **CONDITION SEVERITY** LOCATION 1 **LOCATION 2** MEASUREMENT COMMENT ASSOCIATED COMPONENT **MATERIAL CONSTRUCTION** BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY COMMENT** MEASUREMENT DIAGONAL CRACKS **ENDS MODERATE SEALED ROOF FLEX** BEAM CAP COLUMN REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY** MEASUREMENT COMMENT **FOOTING** REINFORCED CONCRETE SPREAD **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY** MEASUREMENT **COMMENT EXPANSION BEARING STEEL** SLIDING FLAT PLATE **CONDITION SEVERITY LOCATION 1 LOCATION 2** MEASUREMENT **COMMENT** BENT-4 20 FT 6 IN REINFORCED CONCRETE MULTIPLE COLUMN **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY** <u>MEASUREMENT</u> <u>COMMENT</u> ASSOCIATED COMPONENT **MATERIAL CONSTRUCTION** BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE **LOCATION 1 LOCATION 2 CONDITION SEVERITY** MEASUREMENT COMMENT

MoDOT

7	MoDOT		

December 21, 2022 10:28:39AM

COUNT	Y: TEXAS	DISTRICT: SE	CLASS: STATBR	FED-II	D: 8749	BRIDGE: S0529
	SEALED	BEAM CAP		ROOF FLEX		
COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	RIZONTAL CRAC			MEDIUM		
FOOTING		REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BE		STEEL	SLIDING FLAT PLATE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ABUTMENT-5		20 FT 6 IN REINFORCED CONCRETE	OPEN CONCRETE			
	<b>CONDITION</b>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<u>ASSOCIATED C</u>	<u>OMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	SEALED	BEAM CAP		ROOF FLEX		
COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
STRAIGHT WIN		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING		REINFORCED CONCRETE	SPREAD			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BACKWALL		REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BE		STEEL	SLIDING FLAT PLATE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	PACK RUST	BOTTOM		HEAVY		

#### \*\*\*OVER/UNDER ROUTES CLEARANCE INFORMATION\*\*\*

**CLEARANCES OVER DECK** 

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

VERTICAL CLEARANCE TYPE\*\*

**VALUE** 

**DIRECTION** 

**DATE** 

**COMMENT** 

Design\_No = S0529

\*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

Missouri Department of Transportation
State Bridge Inspection Report

**COMMENT** 

COUNTY: TEXAS

CLEARANCES UNDER BRIDGE

**DISTRICT: SE** 

**ITEMS** 

REPLACE BRIDGE

YEAR LET

2025

**CLASS: STATBR** 

FED-ID: 8749

**BRIDGE: S0529** 

**December 21, 2022** 

10:28:39AM

RECORD # **ROUTE DIRECTION OF TRAFFIC** RIGHT LATERAL CLEARANCE LEFT LATERAL CLEARANCE **UR-ID** # LANES **VERTICAL CLEARANCE TYPE\*\* VALUE DIRECTION DATE COMMENT** \*\*\*STRUCTURE PAINT INFORMATION\*\*\* **CONDITION: FAIR** STEEL TONS: 42 **RUST AMOUNT:** 6=1.0% OF SURFACE RUSTED **ORIGINAL PAINT CONTRACT REPAINT** DEPARTMENT REPAINT PAINT TYPE: **PAINT TYPE: MANUFACTURE: PAINT TYPE:** C SYSTEM NAME: NAME: **NAME:** INORGANIC ZINC/VINYL **SURFACE PREP: PAINT COLOR: PAINT COLOR: PAINT COLOR:** GRAY **PAINT YEAR: PAINT YEAR:** PAINT YEAR: 1999 MILS: **MILS**: 9 MILS: \*\*\*REQUESTED WORK ITEMS\*\*\* **GENERAL WORK COMMENTS: LOCATION ITEM** RESPONSIBILITY **CATEGORY PRIORITY** DATE **WORK ITEM COMMENT** \*\*\*UTILITY ATTACHMENTS\*\*\* **OWNER UTILITY METHOD MEASUREMENT TYPE** UTILITY ATTACHMENT COMMENT **VALUE NUMBER** \*\*\*PROGRAM NOTES INFORMATION\*\*\*

<u>YEAR</u> 2025

PROJECT#

SE0029


MONTH LET



December 21, 2022 10:28:39AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8749 BRIDGE: S0529


COUNTI. TEAR	DISTRICT. SE	CLASS, STATER	FED-ID: 0747	DRIDGE, 5032)		
***COMP	UTER GENERATED RATINGS AND I		***ADVANCED	SIGN INFORMATION**	*	
NOTE: The items listed in this section are u	apdated whenever computer edits are ran on a struct	ure after the inspection updates have been entered in to T	ΓMS. SIGN #	SIGN TYPE	PROBLEM	PROBLEM DIRECTION
Rated Item	<u>Rating</u>	Rating Date	1			
[Item 67] Structure Evaluation Rating:	2-BASICALLY INTOLRBLE REQ	2/17/2022				
[Item 68] Deck Geometry Rating:	4-MEETS MINIMUM TOLERABLE	3/25/2002				
[Item 69] Underclearance:	N-NOT APPLICABLE	5/18/2001				
Sufficiency Rating:	43.2%	3/8/2022				
Deficiency:	STRUCTURAL	10/7/2019				
Funding Eligibility:	FULL			***OUTFALL INSP	ECTION INFORMATION	V***
Estimated New Structure Length:	131 FT.		# OX/FFF 1 1 C	737		
<b>Estimated Structure Cost:</b>	\$1,211,367		# OUTFALLS:	IN	SPECTOR:	
Estimated Total Project Cost:	\$1,817,051		STATUS:		DATE:	
Year of Cost Estimate:	2022		NOTES:			
generalized to use NBI items to come up with	estimates are computer generated using algorithms a a new structure length and width to calculate a new at may vary significantly from these numbers once s					





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS S0529 REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 11/10/2022 2022 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District 5B SE Route Signing Prefix MAINLINE TEXAS County 5C Designated Level of Service 00137 8749 8 Federal ID No. 5D Route Number 1932 NOT APPLICABLE 27 5E Year Built Directional Suffix 106 MO 137 S 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 21 Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance HISTORICAL SIGNIF UNKNWN 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS 112 National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway NO 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 204 4 Place PIERCE 29 AADT 57476 2021 Code 30 AADT Year ONE LANE BRIDGE FOR 2-WAY S 19 T 28 N R 8 W Location 102 Direction of Traffic 11 Milepoint 31.86 miles 10% 109 AADT Truck Percent 37 D 5 M 24 S 16 Latitude 286 114 Future AADT 17 Longitude 91 D 51 M 52 S 2041 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 S FK JACKS FK RVR 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 By pass Detour Length 21.88 miles Type of Service Under 00 20 Ft. 0 In. 28B Lanes Under Structure 32 Approach Roadway Width N/A 0.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B NO Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 20 Ft. 0 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 50 Ft. 10 In. 200 Ft. 2 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 20 Ft. 0 In. 40 Nav Horizontal Clear 51 20 Ft. 12 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS BRIDGE: \$0529 REVIEW STATUS: APPROVED NBI STATUS: T

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 11/10/2022 SUBMITTAL YEAR: 2022

RECORD TYPE: ROUTE CARRIED ON STRUCT	RUN DATE: 11/10/2022 SUBMITTAL TEAR: 2022
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION
31 Design Load H 10 41 Structure Status POSTED FOR LOAD 63 Oper. Rating Meth. LOAD FACTOR 64 Operating Rating 17 Tons. 65 Inventory Rating Meth LOAD FACTOR 66 Inventory Rating 10 Tons. 70 Bridge Posting Code 30.0-39.9% BELOW  PROPOSED IMPROVEMENT INFORMATION	43A   Main Struc. Mat type   STEEL     43B   Main struc Constr. Type   STRINGER/MULTIBEAM - GRD     45
Sufficiency Rating 43.2 Percent  Deficiency Rating STRUCTURAL	108C Deck Protect Mat/Constr. 0 NONE
Funding Eligibility FULL  75A Proposed Work REPLACEMENT SUBSTND LOAD  75B Work Done By Contract  76 New Struc Length 232 Ft. 11 In.	CONDITION RATING INFORMATION           58         Deck Cond. Rating         4           59         Superstructure Cond. Rating         5           60         Substructure Cond. Rating         6
94 Struc Improve Cost \$ 1,211,000 95 Roadway Improve Cost \$ 121,000	61 Channel /Channel Protection Cond. Rating 5  62 Culvert Cond. Rating N
96 Total Project Cost \$ 1,817,000	
97 Year of Cost Estimates 2022	INSPECTION INFORMATION
APPRAISAL RATING INFORMATION  36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND  36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND  36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND  36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND  67 Struc Eval App. Rating 2  68 Deck Geometry App. Rating 4  69 Underclearance App. Rating N  71 Waterway Adeq. App. Rating 6  72 Approach Road App. Rating 6  113 Scour Assess App. Rating 8	90 Gen. Insp Date 11 / 22  91 Gen. Insp. Frequency 12 Months  92A Frac. Critical Inspection N Months  93A Frac. Critical Insp. Date  92B Underwater Inspection N Months  93B Underwater Insp. Date  92C Special Inspection N Months  93C Special Inspection Date  BORDER BRIDGE INFORMATION  98 Neighboring State Code  98B Neighboring State % Respon  99 Neighboring State Struc. No.
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION
Approved Posting Category  S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 16 22 39  General Text for Posting Sign  CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT	Field Posting Category S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 16 22 39  General Text for Posting Sign  CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT
TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T.	TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T.

Design\_No = S0529 and Inventory\_Appraisal\_Submittal\_Year = 2022

Assembled Nov 1932 By L.K.S.-G.W.


Traced Dec. 1931 By R.J.G. Assembled Nov. 1932 By L.K.S. Checked Dec. 1931 By GIAM hecked Nov. 1932 By TAB

10-15-32.


The state of the second second

### MISSOURI STATE HIGHWAY DEPARTMENT







Note: This drawing is not to scale. Follow dimensions.



DETAILS OF BENTS NO. 1 &4





PLAN

DETAILS OF BENTS NO. 2 & 3

#### BRIDGE OVER BIG CREEK

STATE ROAD FROM WILLOW SPRINGS TO ROUTE 17
ABOUT 22 MILES NORTH OF WILLOW SPRINGS, FINIGHED
PROJECT NO.S.J.-S6
STA 1156 + 65

TEXAS

COUNTY

FINISHED


Assembled Nov. 1932 by L.K.S. Checked Nov. 1932 by R.S. Drawn 190v. 1930 by C.1.F. Checked Ava.1932 by P.H.S.

Sheet No. 2 of 4.

S-607

. .9-17-32

#### MISSCURI STATE HIGHWAY DEPARTMENT




NO.	5/2	E	LEN	GTH	M	ARK	LOCA	TION				BEN	DINO	3 SKE	тсн			
"A"	\$	ø		3 ""	Τ.	CI	Cu	rb			2	*	1.					
"C"	3"	ø		0"		C.2	•	,	l		4	2.4	ار.					
""	3	P	20'	9"	T .	51	S/a	5			4	( <u>6</u> 2)	25"	2,"	Ç2			
"E"	3"	ø	"F	97		52	,	,			i.e.		2		•			
SPAN	_	5/	NGLE	SPA	I/V		T	ONE	EN	D 5F				ONE		. 5P		
"5"	"A"	"B"	"C"	"0"	"E"	"F"	"A"	"B"	"c"	"D"	"E"	"/="	"A"	"B"	"C"	<i>D</i> "	"E"	"F"
15-0"	8		24		26		8		22		26	,	8	14'-9"	20	64	26	14-9"
17-0	8		28		26		8		24		26		8	16-9"	20	74	26	16-9"
19'-0"	8	,	28		26		8		28		26		8	1819"	28	84	26	18-9"
21-0"	8		30		26		8		28		26		8	2019"	26	92	26	20-9
23'-0"	8		36		26		8		34		26	<u> </u>	18	22:9"	32	100	26	22-9
25-0"	8		- 6		26		-8	26.9	38	118	26	26.90		24-9"	36	7/0	26	24-9
27-0"	8		36		26	L _	18		34	ļ	26			26-9"	32	118	26	2629
29-0"	8		44		26		8		42		26		8	28'5"	40	126	26	28-9
31-0"	R	,	14		26		8		44		26		8	30-9"	24	134	26	3019
33'0"	16		52		52		16		50	L	52	L _	16	17-6"	48	146	52	17-6"
35-0"	16		52		52	L	16	L	50	L	52		16	18'-6"	48	154	52	18-6"
37-0"	16		52		52		16		50		52		16	19-6"	48	164.	52	1916
3910"	16		60		52		16		58		52		16	20'6"	56	172	52	20:6
41-0"	16		60		52		16		58		52		16	21-6"	56	180	52	21-6"
43-0"	16		60		52		16		58	L	.52		16	22-6"	56	190	52	22-6
45-0"	16		68		52		16		66	L	52		16	2346"	64	198	52	23-6
47-0"	16		68		52		16		66		52	ļ	16	24-6"	64	204	52	246
49'0"	7,5		10		52		76		66		572		16	25-6"	64	214	52	25-6

BILL OF REINFORCING STEEL -SUPERSTR.

Note: Reinforcing bars in each span to be billed and tagged separately.

SECTION THRU INT. BENTAT &

SECTION THRU END BENT AT &




<i>No-</i>	Size	Length	Mark	Locotion	Bending Sketches & Cutting Diagram
	Bei	nts No. 1	84		3
12	3,10	7-3"	FI	Hounches	135.
12	310	7:6"	F2	"	\4T
12	3"0	9'.9"	HI	Wing	
6	3,110	16-6"	HZ	. "	14 3 Ext.
6	300	22'-3"	H3	Beam	3:9"
4	李110	20-3"	H4	"	FZ la cirrie
16	3110	22'-3"	H5	4	1060 71 160 01 BA
8	3/10	11-6"	71	Wol/	102 142 3
4	李//0	20-9"	72	"	746.10
8	12110	6'-0"	V/	Wing	7-42 9:12" 10 1230 40'
8	210	4-9"	V2	,	16:6' 17
<i>40</i>	200	8-6"	V3	Beam	3-H2 CUT G BARS
20	3/10	10-6"	V4	Column	e e
10	多10	3'.3"	V5	Wall	3,2:0
12	3/10	7'-9"	V6	Column	H3 19:84°
			l		H5 19'84" 2-0" 4'0"
		nts No. 2			GI 19 84" G'0" H3:H5 <sub>100</sub> GI 4-VI CUT 8 BARS
12	3/10	7:3"	Fi	Haunches	
12	34110	8:0"	.=3	1	150000
32	34.4	22.3"	61	Beam	20" V3 = 30
4	3/10	20'3"	G2	"	Z" UZ
16	3200	9:9"	PI	Columns	13" PE N N N
16	4"0	6'0"	P2.		V3-U2-P2 1400
42	214	8'-6"	111	Beam	10 TO
	<del> </del>		ļ		
	<b></b>				16 7460
			<del> </del>		
	1		L	<u> </u>	9:22" 14. 6"
	<b></b>			-	8'-52" PI
	ļ		<b> </b>	ļ	V4-P1 (1)
	1		ļ		A 10 - 10 4 1
			!	<del> </del>	5 5 8 2"

Note: Dimensions given are along & of bars and are for computed lengths.
Reinforcing bars \( \frac{3}{2}\) "or over in diameter, which are bent to an angle greater than 90°, shall be of structural grade.

FED. ROAD STAYE FED. AID FISCAL SHEET NOTAL DIST NO. PROJ. NO. YEAR NO. SHEETS 5 MD. 3J-56 19

PIECE	$\neg$	LOCATION	NO.PCS	SIZE	/ FNGTH	REMARKS
77200	-1		715.7 00.	0/21-	L =/VC-///	ALIMANIO .
	-1					
		Soares 15'		400		
er Bol	73	Sparis 15' To 31' Incl.	-48	<b>-</b> #	1 1/2/702	bolts, washer for nut.
îpacer Bol	<i>†s</i>	Spans 33'	64	3"\$	<i>Varies</i>	bolts, washer for nut.
tandrail Bo	1/5	Spans 15'	16	3"\$	6"	59. hds., washers, hex. nuts.
11	,,	to 19' Inc.	32	\$"¢	14"	Button heads.
,,	••	Spans 2/'	20	2110	6"	Sq. hds., washe &, hex. nuts.
99	"	to 25'Incl.	40	4.0	18"	Button heads
7,	"	Spans 27'	24	£10	6"	59 hds., washers, hex. nuts.
97	••	to 31' Incl.	48	<b>3</b> ″φ	14	Button heads.
**	,,	Spans 33'	28	3"0	6"	Sq. hds., washers, hex. nuts
**	11	to 37'Incl.	56	3110	14"	Butron heads
***	,,	Spans 3.	32	510	6"	Sq. hds., washers, hex. nuts.
	,,	to 43' Incl.	64	# " ¢	12"	Burion heads.
**	,,	Spans 45"	36	510	6"	Sq. hds., washers, hex.nuts
77	,,	to 49'Incl.	72	210	14"	Button heads
Bolts		Bearing Pls		210	1 - 1 <del>4</del>	So heads, no threads.
00110	_	Dogring 110	<b>1</b>	4		34.7.6803; 7.0776803;
		Soons 15'		===		
Spacer Bo	<i>l\1</i> 5	10 3!'Incl.	48	2110	Varies-	bolfs, washer for nut.
Spacer Bo	1/5	5pans 33'.	64	3"0	Varies	bolls, washer for nut
Yandrali B			12	500	6"	59. hu washers, hex. nuts.
	22	to 19'Incl.	32	3110	121"	But on neads
	77		16	3110	6"	
		Spans 2/	10	7 70	14."	Sq. hds., washers, hex.nuts
	"	to 25'Incl.		3"0	6"	Button heads
	,,	Spans 27'	20	300	6	59. hds., washers, hex. nuts
	99	to 31'Incl.	48	14, 1	i .	Button heads.
······································	**	Spans 33'	24.	25	5.70	5q. hds., washers, hex nuts
	"	to 37'Incl.	56	310	14" 6"	Button heads.
	,,	Spans 39'	28,	8,10	6"	Sq. hds., washers, hex. nuts
11	,,	to 43'Incl.	64	\$110	<i>i4</i> "	Button heads.
11	**	[ Spans 45']	32	£"\$	6"	59. hds., washers, hex. nuts
	,,	to 49 Incl.	8	3/10	14"	Button heads.
Bolts		Bearing Pls.	16	<i>3"</i> φ	12"	Sq. heads, no threads.
•					7	
	٠.	·	i		T	
		· · · · · ·		<u> </u>	t	
		<u> </u>	<del></del>	<u> </u>	<del> </del>	<del> </del>

\* 2 Washers plus washers for fill required for alignment of railposts.



Note: Use bevel as shown for exposed faces of all joints consisting of rubber compound except at top surface of roadway slob Use edging tool with it radius at top surface of roadway slob each side of rubber compound joint.

DETAILS OF BEVEL FOR RUBBER COMPOUND JOINTS

#### BRIDGE OVER BIG CREEK

STATE ROAD FROM WILLOW SPRINGS TO ROUTE IT ABOUT 22 MILES NORTH OF WILLOW SPRINGS FINISHED STA.1156+65

PROJECT NO. SJ-S6

**TEXAS** 

COUNTY


FINISHED


Note: This drawing is not to scale. Follow dimensions.

S-607

Sheet No. 3 of 4.

Designed Nov. 1929 By F.W.H. Drawn Dec. 1930 By R.J.G. Assembled Nov. 1932 By L.K.S.-G.W. Traced Dec. 1931 By R.J.G. Checked Nov. 1932 By FNB. Checked Dec. 1931 By J.H.M.





つるい

Designed Nov. 1929 By F.W.H. Drawn Dec. 1930 By R.J.G. Traced Dec. 1931 By R.J.G. Checked Dec. 1931 By LYTJ.

Assembled Nov. 1932 By L.K.S. - G.W. Checked Nov. 1932 By FAB. Note: This drawing is not to scale. Follow dimensions.

Sheet No.4 of 4.

S-607



December 21, 2022 10:27:45AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607

\*\*\*GENERAL STRUCTURE INFORMATION\*\*\* \*\*\*BRIDGE INSPECTION INFORMATION\*\*\* ROUTE: MO137S # **SPANS**: 3 PLACE CODE: 55820 OZARK **RESPONSIBILITY: DISTRICT DATE:** 11/07/2022 FEATURE: BIG CR LANES ON: 1 LENGTH: 103 FT 0 IN FREQUENCY: 12 CALCULATED INTERVAL\*\*: 12 LANES UNDER: 0 **STATUS:** P-POSTLOAD MAXIMUM SPAN: 49 FT 2 IN **TEAM LEADER: ED HESS ELEMENT: NO LOG MILE: 20.474 COMPASS DIRECTION:** SOUTH to NORTH APPROACH ROADWAY: 20 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR:** 16.00 MILES **DIRECTION OF TRAFFIC: 1-LN/2-WAY CURB TO CURB: 20 FT 0 IN INSPECTOR 3: OUT TO OUT:** 21 FT 0 IN NHS: NO FUNCTIONAL CLASS: RL-MAJOR COLLECTOR \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1932 **NBI OWNER: MODOT AADT:** 335 **GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2021** MAINTENANCE DISTRICT: SE LOCATION: S 5 T 29 R 8 W **AADT TRUCK: 9.0% LATITUDE:** 37 13 58.72 (DMS) **MAINTENANCE COUNTY: TEXAS FUTURE AADT: 469 LONGITUDE:** 91 51 .27 (DMS) SUB AREA: 7H46 **FUTURE AADT YEAR: 2041** \*\*\*INDEPTH INSPECTION INFORMATION\*\*\* \*\*\*FRACTURE CRITICAL INSPECTION INFORMATION\*\*\* DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **FREQUENCY: CALCULATED INTERVAL\*\*: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** \*\*\*SPECIAL INSPECTION INFORMATION\*\*\* \*\*\*UNDERWATER INSPECTION INFORMATION\*\*\* CATEGORY: CHANNEL CROSS SECT **DATE:** 11/07/2022 **CATEGORY: DRY DATE:** 06/13/2014 **RESPONSIBILITY: DISTRICT RESPONSIBILITY: DISTRICT** FREOUENCY: 120 **NBI:** NO FREOUENCY: 60 NBI: NO **CALCULATED INTERVAL\*\*:** CALCULATED INTERVAL\*\*: 12 **TEAM LEADER: ED HESS TEAM LEADER: INSPECTOR 3: METHOD:** WT TAPE **INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 2:** ED HESS **INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** \* When calculated interval exceeds the frequency, a justification comment per BIRM is required. \*\* When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS **DATE FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** 

December 21, 2022 10:27:45AM

**COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607** 

\*\*\*STRUCTURE POSTING\*\*\* **APPROVED CATEGORY: S-17** CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T. **Ton 2:** 22 **Ton 1:** 16 **Ton 3:** 39 **COMMENTS:** FIELD CATEGORY: S-17 CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS **Ton 1:** 16 **Ton 2:** 22 **Ton 3:** 39 **PROBLEM:** PROBLEM DIRECTION: **COMMENTS:** \*\*\*GENERAL COMMENTS/MAJOR RATED ITEMS\*\*\* GENERAL COMMENTS: (BOWDEJ1, 08/28/2008)--(26'-49'-26') SMP WF GDR SPANS [ITEM 58] DECK: 4-POOR CONDITION COMMENTS: (DENNIB1, 11/13/2013)--EDGE DETERIORATION **RATING:** 11/07/2022 [ITEM 59] SUPER: 5-FAIR CONDITION COMMENTS: (DENNIB1, 11/13/2013)--TOP FLANGE RUSTING **RATING:** 05/18/2001 [ITEM 60] SUB: 3-SERIOUS CONDITION COMMENTS: (DENNIB1, 11/16/2015)--VERTICLE CRACKS & SPALL AT BEARING **RATING:** 11/07/2022 [ITEM 61] BANK/CHANNEL: 6-WIDESPREAD MINOR DAMAGE **COMMENTS: RATING:** 05/18/2001 [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED **COMMENTS: RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: DECK/APPRCH OVERTOP SLIGT **COMMENTS: RATING:** 05/18/2001 **COMMENTS: RATING:** 05/18/2001 \*\*\*RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS\*\*\* [ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 01/06/2010 **COMMENTS: DIRECTION MATERIAL CONSTRUCTION COMMENTS** REINFORCED CONCRETE **CURB BOTH SEVERITY CONDITION** LOCATION 1 LOCATION 2 **COMMENT DETERIORATION THROUGHOUT MODERATE** STEEL ANGLE-DOUBLE **BOTH [ITEM 36B] TRANSITION RAILING RATING:** NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS: RATING:** 05/18/2001 [ITEM 36D] RAIL END TREATMENT RATING: NOT PROVIDED-0 **COMMENTS:** 

MODOT

## **Missouri Department of Transportation State Bridge Inspection Report**

**December 21, 2022** 10:27:45AM

**COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607** 

APPROACH PAVEMENT: \*Overall condition assigned for each approach pavemenet component is shown below.

**MATERIAL ASPHALT** 

**CONSTRUCTION BITUMINOUS MAT**  **DIRECTION BOTH** 

**CONDITION\*** 

**COMMENTS** 

\*\*\*DRAINAGE, EXPANSION DEVICES, BANK/SLOPE, AND DECK PROTECTIVE COMPONENTS\*\*\*

**DECK PROTECTIVE COMPONENTS:** 

SERIES TYPE-# **COMPONENT MATERIAL** MAIN SERIES-1 WEARING SURFACE **ASPHALT** 

**CONSTRUCTION** BITUMINOUS MAT **THICKNESS** 1 IN

YEAR APPLIED MANUFACTURE

**OVERALL CONDITION** *FAIR* 

**COMMENT:** (BOWDEJ1, 04/28/2010)--APPLIED IN 2000 & RESEALED 2006 & 2008

DECK PROTECTION

*NOTAPPLICABLE* 

NONE

**COMMENT:** 

*MEMBRANE* 

*NOTAPPLICABLE* 

**NONE** 

**COMMENT:** 

**DRAINAGE COMPONENTS:** 

**COMPONENT** DRAINAGE

**MATERIAL** REINFORCED CONCRETE **CONSTRUCTION** CURB OUTLET

**DIRECTION** 

**COMMENTS** 

**COMMENTS** 

**COMMENT** 

**COMMENT** 

2013

**EXPANSION DEVICE COMPONENTS:** 

SUB UNIT-# SUB LABEL

**COMPONENT** 

**MATERIAL** 

**CONSTRUCTION** 

GAP

YEAR APPLIED

**MANUFACTURE** 

**OVERALL CONDITION** 

**COMMENT:** 

**BANK/SLOPE PROTECTION COMPONENTS:** 

**COMPONENT BANK PROTECTION**  **MATERIAL** ROCK

**CONSTRUCTION** GROUTED

**DIRECTION** BOTH

**MEASUREMENT** 

**MEASUREMENT** 

\*\*\*DECK COMPONENTS\*\*\*

SPAN TYPE-# MAIN SPANS-1 **CONDITION** 

> **DETERIORATION EFFLORESCENCE**

> > **PATCHES**

SATURATION TRANSVERSE CRACKS

**CONDITION** 

**PATCHES** 

TRANSVERSE CRACKS

**COMPONENT** DECK

**MATERIAL** REINFORCED CONCRETE **CONSTRUCTION** CAST-IN-PLACE

**COMMENTS** 

**EDGE** 

LOCATION 1

THROUGHOUT

THROUGHOUT THROUGHOUT

THROUGHOUT

LOCATION 1

THROUGHOUT

THROUGHOUT

LOCATION 2

LOCATION 2

**SEVERITY** 

**MODERATE** 

**MINOR** FEW

**MODERATE** 40 %

MANY

MAIN SPANS-2

DECK

REINFORCED CONCRETE

CAST-IN-PLACE

**SEVERITY** 

**DETERIORATION EDGE** THROUGHOUT **EFFLORESCENCE** 

**MODERATE** 

MINOR **FEW** 

MANY

Design No = S0607

**December 21, 2022** 10:27:45AM

**COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607** 

CAST-IN-PLACE MAIN SPANS-3 DECKREINFORCED CONCRETE

**SEVERITY CONDITION** LOCATION 1 LOCATION 2 **MEASUREMENT COMMENT** 

DETERIORATION **EDGE MODERATE** THROUGHOUT MINOR EFFLORESCENCE **PATCHES** THROUGHOUT FEW MANY TRANSVERSE CRACKS THROUGHOUT

\*\*\*SUPERSTRUCTURE COMPONENTS\*\*\*

SERIES TYPE-# SPAN TYPE MATERIAL CONSTRUCTION LABEL **COMMENTS** 

MAIN SERIES-1 SIMPLE SPAN STEELWIDE FLANGE GIRDERS

<u>SPAN</u> **COMPOSITE INDICATOR LENGTH WEATHERING STEEL COMMENTS** MAIN SPANS-1 NON-COMPOSITE 26 FT 11 IN NO

**CONDITION SEVERITY** LOCATION 1 **LOCATION 2 MEASUREMENT COMMENT** PACK RUST **EXTERIOR GIRDERS MODERATE** 

RUSTING **TOP FLANGE MODERATE** SECTION LOSS **MODERATE** AT BEARING

SECTION LOSS **BOTTOM FLANGE MODERATE** 

MAIN SPANS-2 NON-COMPOSITE 49 FT 2 IN NO

**CONDITION** LOCATION 1 **SEVERITY** LOCATION 2 **MEASUREMENT COMMENT** PACK RUST **EXTERIOR GIRDERS MODERATE BOTTOM FLANGE** RUSTING **MODERATE** RUSTING **TOP FLANGE** MODERATE SECTION LOSS **BOTTOM FLANGE MODERATE** 

SECTION LOSS **TOP FLANGE** MINOR

MAIN SPANS-3 NON-COMPOSITE 26 FT 11 IN NO

**CONDITION** LOCATION 1 **LOCATION 2 SEVERITY MEASUREMENT COMMENT** PACK RUST **EXTERIOR GIRDERS MODERATE** 

RUSTING **MODERATE BOTTOM FLANGE** TOP FLANGE **RUSTING MODERATE** 

SECTION LOSS **BOTTOM FLANGE** MODERATE (WILSOJ, 08/18/2003)--AT BEARINGS MINOR

SECTION LOSS **TOP FLANGE** 

#### \*\*\*SUBSTRUCTURE COMPONENTS\*\*\*

<u>SUBSTRUCTURE</u>	<u>SKEW</u>	<b>LENGTH</b>	<u>MATERIAL</u>		<b>CONSTRUCTION</b>	<u>LABEL</u>	<b>COMMENTS</b>	<u> </u>	
ABUTMENT-1		20 FT 6 IN	REINFORCED CONCRETE	TE	OPEN CONCRETE				
	<b>CONDITION</b>		<u>LOCATION 1</u>		<b>LOCATION 2</b>		<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
<u>ASSOCIATED C</u>	<u>OMPONENT</u>	<u>MAT</u>	<u>ERIAL</u>		<b>CONSTRUCTION</b>				
BEAM CAP		REIN	FORCED CONCRETE		CAST-IN-PLACE				
	<b>CONDITION</b>		<u>LOCATION 1</u>		<b>LOCATION 2</b>	<u>.s</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
	SEALED		TOP			ASP	PHALTICBASE		
COLUMN		REIN	FORCED CONCRETE		CAST-IN-PLACE				
	<b>CONDITION</b>		<u>LOCATION 1</u>		LOCATION 2	<u>s</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
STRAIGHT WIN	GS	REIN	FORCED CONCRETE		CAST-IN-PLACE				
	<b>CONDITION</b>		<u>LOCATION 1</u>		<b>LOCATION 2</b>	<u>s</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<b>COMMENT</b>
FOOTING		REIN	FORCED CONCRETE		SPREAD				
	<b>CONDITION</b>		<u>LOCATION 1</u>		<b>LOCATION 2</b>	<u>s</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<b>COMMENT</b>
BACKWALL		REIN	FORCED CONCRETE		CAST-IN-PLACE				

MoDOT		Missouri Department of T	ransportation		December 21, 2022
		State Bridge Inspection	on Report		10:27:45AM
COUNTY: TEXAS	DISTRICT: SE	CLASS: STATBR	FED-ID	<b>):</b> 8779	BRIDGE: S0607
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BEARING	STEEL	SLIDING FLAT PLATE	CELLEBIEN	ME ACUREMENT	COMMENT
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BENT-2	20 FT 6 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<b>SEVERITY</b>	<b>MEASUREMENT</b>	<u>COMMENT</u>
ASSOCIATED COMPONENT	<u>MATERIAL</u>	<b>CONSTRUCTION</b>			
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
REBAR EXPOSED			EXCESSIVE		
SEALED VERTICAL CRACK	TOP S RANDOM		ASPHALTICBASE MINOR		
COLUMN	REINFORCED CONCRETE	CAST-IN-PLACE	MINOK		
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
REBAR EXPOSED	<u> </u>		EXCESSIVE		
SPALLS	COLUMN		SEVERE		
FOOTING	REINFORCED CONCRETE	SPREAD			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPOSED EXPOSED	ТОР		MINOR		
EXPANSION BEARING <i>CONDITION</i>	STEEL <i>LOCATION 1</i>	SLIDING FLAT PLATE <i>LOCATION 2</i>	<u>SEVERITY</u>	MEASUREMENT	COMMENT
CONDITION	<u>LOCATION I</u>	<u>LOCATION 2</u>	<u>SEVERITI</u>	MEASUREMENT	COMMENT
BENT-3	20 FT 6 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
ASSOCIATED COMPONENT	MATERIAL	CONSTRUCTION	<del></del>		
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
REBAR EXPOSED			MODERATE		
SEALED	TOP	CACT DI DI ACE	ASPHALTICBASE		
COLUMN <i>CONDITION</i>	REINFORCED CONCRETE <i>LOCATION 1</i>	CAST-IN-PLACE <i>LOCATION 2</i>	SEVERITY	MEASUREMENT	COMMENT
REBAR EXPOSED	<u> </u>	<u>LOCATION 2</u>	MODERATE	MEASUREMENT	COMMENT
VERTICAL CRACK			MODERATE		
FOOTING	REINFORCED CONCRETE	SPREAD			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EXPANSION BEARING	STEEL	SLIDING FLAT PLATE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ADMITTACENTE A	AN ET A DA DEDUCADA CON CONCRETE	ODEN GONGDETTE			
ABUTMENT-4 <b>CONDITION</b>	20 FT 6 IN REINFORCED CONCRETE <u>LOCATION 1</u>	OPEN CONCRETE <b>LOCATION 2</b>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
ASSOCIATED COMPONENT	<u>EOCATION 1</u> <u>MATERIAL</u>	CONSTRUCTION	<u>SEVERITI</u>	MEASUREMENT	COMMENT
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<b>MEASUREMENT</b>	COMMENT
SEALED	TOP		ASPHALTICBASE		(BOWDEJ1, 04/28/2010)ALL CAPS SEALED 4/2005 & RESEALED 2009
COLUMN	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
STRAIGHT WINGS	REINFORCED CONCRETE	CAST-IN-PLACE	ODI/D DIZZ	ME (CHEST SEE	COMMENT
<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING <u>Condition</u>	REINFORCED CONCRETE <u>LOCATION 1</u>	SPREAD <i>LOCATION 2</i>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
BACKWALL	REINFORCED CONCRETE	CAST-IN-PLACE	<u>SEVERIII</u>	MEASUREMENT	COMMENT
DI CIK WILL	TELL I SKELD CONCRETE				

December 21, 2022 10:27:45AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607

CONDITIONLOCATION 1LOCATION 2EXPANSION BEARINGSTEELSLIDING FLAT PLATE

<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>

\*\*\*OVER/UNDER ROUTES CLEARANCE INFORMATION\*\*\*

**SEVERITY** 

MEASUREMENT COMMENT

CLEARANCES OVER DECK \*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

<u>VERTICAL CLEARANCE TYPE\*\*</u> <u>VALUE</u> <u>DIRECTION</u> <u>DATE</u> <u>COMMENT</u>

CLEARANCES UNDER BRIDGE \*\*NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

RECORD# ROUTE # LANES DIRECTION OF TRAFFIC RIGHT LATERAL CLEARANCE LEFT LATERAL CLEARANCE UR-ID

\*\*\*STRUCTURE PAINT INFORMATION\*\*\*

**CONDITION:** FAIR **RUST AMOUNT:** 7 = .2% OF SURFACE RUSTED **STEEL TONS:** 17

ORIGINAL PAINT CONTRACT REPAINT DEPARTMENT REPAINT

PAINT TYPE: PAINT TYPE: PAINT TYPE: C SYSTEM MANUFACTURE: NAME: NAME: NAME: INORGANIC ZINC/VINYL SURFACE PREP:

PAINT COLOR: PAINT COLOR: PAINT COLOR: ALUMINUM
PAINT YEAR: PAINT YEAR: PAINT YEAR: 2000

MILS: MILS: 8

\*\*\*REQUESTED WORK ITEMS\*\*\*

GENERAL WORK COMMENTS:

MODOT

RESPONSIBILITY LOCATION ITEM CATEGORY PRIORITY DATE WORK ITEM COMMENT

REGIONAL ABUTMENT-COLUMN REPAIR COLUMN OR SHAFT SUBSTRUCTURE 2 11/28/2017 (DENNIB1, 11/05/2019)--REPAIR ALL COLUMNS IN BENTS 2 & 3 & CAP @ BENT 2

\*\*\*UTILITY ATTACHMENTS\*\*\*



December 21, 2022 10:27:45AM

**COUNTY: TEXAS** 

**DISTRICT: SE** 

**CLASS: STATBR** 

FED-ID: 8779

**BRIDGE: S0607** 

UTILITY OWNER METHOD MEASUREMENT TYPE VALUE NUMBER UTILITY ATTACHMENT COMMENT

\*\*\*PROGRAM NOTES INFORMATION\*\*\*

YEAR<br/>2025PROJECT #<br/>SE0028MONTH LET<br/>1YEAR LET<br/>2025ITEMS<br/>REPLACE BRIDGE

**COMMENT** 


***COMF	PUTER GENERATED RATINGS AND D	EFICIENCY ITEMS***		***ADVANCED SI	GN INFORMATION <sup>*</sup>	***
NOTE: The items listed in this section are	updated whenever computer edits are ran on a struct	ure after the inspection updates have been entered in to TMS.	SIGN #	SIGN TYPE	PROBLEM	PROBLEM DIRECTION
Rated Item	<u>Rating</u>	Rating Date	1	B - ONE LANE BRIDGE		
[Item 67] Structure Evaluation Rating:	3-BASICALLY INTOL CORRECT	11/10/2022	2	YIELD TO ONCOMING TRAFFIC		
[Item 68] Deck Geometry Rating:	4-MEETS MINIMUM TOLERABLE	11/13/2019				
[Item 69] Underclearance:	N-NOT APPLICABLE	5/18/2001				
Sufficiency Rating:	34.4%	11/10/2022				
Deficiency:	STRUCTURAL	11/9/2021				
Funding Eligibility:				***OUTFALL INSPEC	TION INFORMATIO	ON***
Estimated New Structure Length:			# O.T.	~	ama n	
<b>Estimated Structure Cost:</b>			# OUTFALLS	S: INSPE	CTOR:	
Estimated Total Project Cost:			STATUS	S:	DATE:	
Year of Cost Estimate:			NOTES	S:		
generalized to use NBI items to come up wit	estimates are computer generated using algorithims h a new structure length and width to calculate a new st may vary significantly from these numbers once s	area which is taken times a representative cost per				



December 21, 2022 10:27:45AM

COUNTY: TEXAS DISTRICT: SE CLASS: STATBR FED-ID: 8779 BRIDGE: S0607


 $Design_No = S0607$ 





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS S0607 REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 11/10/2022 2022 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District 5B SE Route Signing Prefix MAINLINE **TEXAS** County 5C Designated Level of Service 00137 8779 8 Federal ID No. 5D Route Number 1932 NOT APPLICABLE 27 5E Year Built Directional Suffix 106 MO 137 S 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 21 Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance HISTORICAL SIGNIF UNKNWN 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway NO 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 335 4 Place **OZARK** 29 AADT 55820 2021 Code 30 AADT Year ONE LANE BRIDGE FOR 2-WAY S 5 T 29 N R 8 W Location 102 Direction of Traffic 11 Milepoint 20.59 miles 109 AADT Truck Percent 16 Latitude 37 D 13 M 59 S 469 114 Future AADT 17 Longitude 91 D 51 M 0 S 2041 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 BIG CR 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 16.25 miles Type of Service Under By pass Detour Length 00 20 Ft. 0 In. 28B Lanes Under Structure 32 Approach Roadway Width N/A 0.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 20 Ft. 0 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 49 Ft. 3 In. 103 Ft. 0 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 20 Ft. 0 In. 40 Nav Horizontal Clear 51 20 Ft. 12 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: TEXAS BRIDGE: \$0607 REVIEW STATUS: APPROVED NBI STATUS: T

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 11/10/2022 SUBMITTAL YEAR: 2022

RECORD TYPE: ROUTE CARRIED 'ON' STRUCT	RUN DATE: 11/10/2022 SUBMITTAL YEAR: 2022
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION
LOAD RATING AND POSTING INFORMATION  31 Design Load H 10  41 Structure Status POSTED FOR LOAD  63 Oper. Rating Meth. LOAD FACTOR  64 Operating Rating 22 Tons.  65 Inventory Rating Meth LOAD FACTOR  66 Inventory Rating 14 Tons.  70 Bridge Posting Code 10.0-19.9% BELOW  PROPOSED IMPROVEMENT INFORMATION  Sufficiency Rating Deficiency Rating STRUCTURAL Funding Eligibility FULL	MATERIAL/CONSTRUCTION INFORMATION  43A Main Struc. Mat type STEEL  43B Main struc Constr. Type STRINGER/MULTIBEAM - GRD  45 # of Main Spans 3  44A Appr Struc. Mat type 000  44B Appr Struc. Cnstr. type 000  46 # of Approach Span 0  107 Deck Mat/Constr. 1 CONCRETE CIP  108A Wear Surf Mat/Constr. 6 BITUMINOUS  108B Membrane Mat/Constr. 0 NONE  108C Deck Protect Mat/Constr. 0 NONE  CONDITION RATING INFORMATION
75AProposed WorkREPLACEMENT SUBSTND LOAD75BWork Done ByContract76New Struc Length131 Ft. 3 In.94Struc Improve Cost\$ 681,00095Roadway Improve Cost\$ 68,000	58         Deck Cond. Rating         4           59         Superstructure Cond. Rating         5           60         Substructure Cond. Rating         3           61         Channel /Channel Protection Cond. Rating         6           62         Culvert Cond. Rating         N
96 Total Project Cost \$ 1,022,000 97 Year of Cost Estimates 2022	INSPECTION INFORMATION
APPRAISAL RATING INFORMATION  36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND  36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND  36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND  36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND  67 Struc Eval App. Rating 3  68 Deck Geometry App. Rating 4  69 Underclearance App. Rating N  71 Waterway Adeq. App. Rating 6  72 Approach Road App. Rating 8  113 Scour Assess App. Rating 8	90 Gen. Insp Date 11 / 22  91 Gen. Insp. Frequency 12 Months  92A Frac. Critical Inspection N Months  93A Frac. Critical Insp. Date  92B Underwater Inspection N Months  93B Underwater Insp. Date  92C Special Inspection N Months  93C Special Inspection Date  BORDER BRIDGE INFORMATION  98 Neighboring State Code  98B Neighboring State % Respon  99 Neighboring State Struc. No.
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION
Approved Posting Category S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 16 22 39  General Text for Posting Sign  CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T.	Field Posting Category S-17  Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 16 22 39  General Text for Posting Sign  CL OF BR AND TRK OVR 16 T 15MPH ON BR EXCPT SNGLE UNT TRKS WT LMT 22 T OTHR TRKS WT LMT 39 T.

Design\_No = S0607 and Inventory\_Appraisal\_Submittal\_Year = 2022