



MISSOURI STATE HIGHWAY DEPARTMENT


	FED. R TO	STATE	PROJ. NO.	FISC46 + 51	TOTAL	ĺ
1	5	МО	R.51A-52	19	-	7




Note: This drawing is not to scale. Follow dimensions.



DETAILS OF BENT NO.1



Note:- Ui-Pi bars 8t. #2 Ui-P3 bars Et. #3 U2-P3 bars Bt. #5



DETAILS OF BENTS NO.2,3&5

BRIDGE OVER SALINE CREEK

STATE ROAD FROM PERRYVILLE TO SILVER LAKE
ABOUT 8 MILES S.W. OF PERRYVILLE
FINISHED

PROJECT NO. R.5IA-S.2 STA.4II+59

PERRY FINISHED COUNTY

Assembled Jan. 1933 by I.B. & H.E.C. Checked Jan. 1933 by P.H.S.


ر ر

Sheet No. 2 of 5


S-734

MISSOURI STATE HIGHWAY DEPARTMENT


PED. ROAD DIST. NO.	STATE	FED. AID PROJ. NO.		
, 5	M3	R5/A-5.2	19	





Note This drawing is not to scale. Follow dimensions.



DETAILS OF BENT NO. 7







DETAILS OF BENTS NO.4&6

BRIDGE OVER SALINE CREEK

Note:- Use ½° grout under all bearing plotes.

STATE ROAD FROM PERRYVILLE TO SILVER LAKE? ABOUT & MILES S.W. OF PERRYVILLE PROJECT NO. R. SIA-S. 2 STA. 411+59

PERRY F \ 3550

COUNTY

Assembled Jan. 1933 by I.B. & H.E.C. Checked Jan 1933 by P.H.S. Drawn Nov. 1930 by CAF. Checked AJ9.1932 by P.H.S.

5-734


MISSOURI STATE HIGHWAY DEPARTMENT

FED RGAD DIST NC.
5


				BILL	OF R	EINFOR	CING STEEL	\$ UB\$	STRUCTURE	
No.	Size	Longth	Mark	Location	No.	Size	Length	Mork	Location	Bending Sketches & Cutting Diagrams
	End B	Bents No. 1	87				ts No. 1 & 7	(Conti	nued)	6" 2'0" 0 0
20		5-9"	01	Footing	4	2"	5-0	V8	Wing Bt. 37	
12	211	7'-6"	F/	Hounch	24	₹.0	3:90	V9	8k.Wall	
12	2"	8'-0"	F2		_/0	2.4	12:0*	VIO	Column " "	455 66 16 16 16 16 16 16 16 16 16 16 16 16
/2	£"0	11'-0"	H!	Wing						DI FI 120
8	200	18:9"	HZ	,		Int. Bei	nts No. 2, 3	4,586	7	102 8:02 8 23 6 4 1
6	20	26'-0"	H3	Beam	40	₹'*	5:9	01	Footing	GI-H3-H5
4	\$10	24-0"	H4	"	30	1.4	7:6"	F/	Haunch	
14	100	26-0"	H5	"	30	270	8:3"	F3	"	8011081 23 47
4	2"	12-6"	7/	Wing Bf. #/	56	1"6	26-0"	GI	Beom	4-H2 CUT 8 5-V7 CUT 7
4	4.4	25-0"	72	Back Wall	10	老"	24'-0"	G2	"	4-H2 CUT 8 5-V7 CUT 7
4	20	12:30	73	Wing Bt. 7	8	2"	12'-0"	PI	COI. Bt. #2	5:12:35
5	2'4	7:00	VI	" B! 1	70 .	4"	6500	PZ	Column	73 737 NSW 73
4	2.0	5'-3"	V2	" " "	16	40	12-6"	PS	Col. 813 325	22 4:10 012 21
48	2.0	9'-6"	V3	Beam	16	4"	1/-3"	F4	" - 420	7-0-
10	- * "	12:3"	V4	Col. 81.#1	62	2"	8'6"	UI	Beam - 223	5-VI CUT 5 UI-U2-P2-V3
24	3"	4.0"	V5	Bk. Wall Bt. 1	93	200	9'0"	UZ.	" "4,586	3.8
/2	\$10	7-9"	VG	Hounch						ig 1 1 17-73
5	2"#	6:6'	V7	Wing Bt. 7					ì	
										Note: Dimensions given are along
										£ of bars and are far computed
										iengths.
						_				Reinforcing bars for over in
			. જ	2		eŽ	i3		Ų	diameter, which are bent to
		19	Ş	Ź		8	8		إنْ	an ongle greater than ea;
		20	8	હ		9	Š		હ	an ongle greater than 80; shall be of structural grade.
		210	3	*		3	.9.		74	21


					1	BILL	OF	REIN	FOR	CIN	5 S	TEEL-	SUF	PERST	RUCT	URE		
NO.	5/2	ZE	LEA	IGTH	M	ARK	LOC	ATION				BEN	DIN	G SKE	TCH			
"A"	Æ	* *	#2	9"	T	CI	CL	11-6			2	•	. _					
"c"	7	" 🏓	2'-	0"		CZ	,	,	1		-]	ادر	\longrightarrow				
<i>"D"</i>	3	•		9"	Τ.	51	5/4	96	1		Ų.	62		2	CZ	,		
"E"	3	4	"F	79	1 .	52	,	,	1		Ĺ		75"	نـــــــــــــــــــــــــــــــــــــ	-	•		
SPAN	_	5/	NGLE	SPA	<i>~</i>		Τ	ONE	EΛ	D 5	PAN			ONE	7//	T. 5F	AN	
SPAN S	"A"	"8"	"c"	0"	`E'"	"F"	"A"	"8"	"c"	"0"	"E"	"F"	"A"	"B"	! " C"	7"0"	"E"	14°F-70"
15º0°	8		24		26		8	\vdash	22	_	26	- -	8	14-5"	20	64	26	14-9
7200	8		28		26		8		24	I	26	Ι	8	16-9"	20	74	26	16291
9-0"	8		28		26		8	I = I	28	I	26	[_i]	8	18-9"	28	84	26	18-9"
21-0"	8		30	_	26	L	8	L	28		26		8	2029*	26	92	26	2029
23-0"	8		36		26		8		34	_	26	: /	8	22-9"	32	100	26	22-9
25-0"			.35		28		8	26'-9"	36	118	31	26-9	÷	24 ST	.M.	110	28	72
27'0"	8		36		26	L _	8	1 - 4	34	ļ	26		8	26'9"	32	118	26	26'9"
2970*	8		44		26		8		42	<u> </u>	26		8	28'9"	40	126	2	28- 9 *
31-00			44		1		_	82°9"		144	3/	3219"	8	30-9"	44		31	30-90
33'0"	16	<u> </u>	52		52		16	↓ — .	50	L	52		16	17:6"	48	146	52	17-6"
35 <u>'0"</u> 37 <u>'0</u> "	16		52 52		52 52		16	ļ 1	50	ļ	52		16	18-6	48_	154	52	1846"
19 ¹ 0°	<i>16</i>		60		52		16	F -4	50		52		16 16	19:6	48	164	52	1926"
1/200	16		60		52 52	-	16	ł- i	58 58	├ -	52 52		16	20-6	56	172		20'6"
3'0"	16		60		52		16	· ·	58	-	52	-	16	22-6	56 56	190	52 52	21-6"
15'0"	16		68		52		16	} ⊢	66		52	- 1	16	2316"	64	198	52	23-6
17:0"	16		68		52		16	1 - 1	66	- 1	52	1	16	24-6	64	204	52	24-6
19'0"			60		霾	==	i Ž		iii.				16	25-6		216	•	25-6

Note: Reinforcing bars in each span to be billed and tagged separately.




€. GRADE ELEVATIONS






Note:-Light Stone Reverment shall be placed on Fills at ends of bridge as shown in sketches, Approximately 230 square yards of riprap work included in road contract.

LIGHT STONE REVETMENT SKETCHES



* 2 Washers plus washers for fill required for alignment of railposts.



Note: Use bevel as shown for exposed faces of all joints consisting of rubber compound except at top surface of roadway slab. Use edging tool with a radius at top surface of roadway slab each side of rubber compound joint.

DETAILS OF BEVEL FOR RUBBER COMPOUND JOINTS

BRIDGE OVER SALINE CREEK

STATE ROAD FROM PERRYVILLE TO SILVER LAKE ABOUT 8 MILES S.W. OF PERRYVILLE FINISHED PROJECT NO. R.51A-S.2 STA. 411+59


PERRY

COUNTY

FIGURUAL

Designed Nov. 1929 By F.W.H.
Drawn Dec. 1930 By R.J.G. Assembled Jan. 1939 By I.B. & H.E.C.-GW.
Traced Dec. 1931 By R.J.G. Checked Jan. 1933 By P.H. 3.
Checked Dec. 1931 By J.H.M.

Sheet No. 4 of 5.



January 02, 2024 6:31:35AM

COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734

GENERAL STRUCTURE INFORMATION ***BRIDGE INSPECTION INFORMATION*** **ROUTE: RTTE # SPANS:** 6 PLACE CODE: 65036 ST. MARYS **DATE:** 10/10/2023 **RESPONSIBILITY: DISTRICT** LANES ON: 2 FEATURE: SALINE CR LENGTH: 220 FT 0 IN FREQUENCY: 12 **CALCULATED INTERVAL**:** LANES UNDER: 0 **STATUS:** P-POSTLOAD MAXIMUM SPAN: 49 FT 1 IN **TEAM LEADER: ED HESS ELEMENT: NO LOG MILE: 20.014 COMPASS DIRECTION: NORTH to SOUTH** APPROACH ROADWAY: 22 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR: 57.00 MILES DIRECTION OF TRAFFIC: 2-WAY TRAF** CURB TO CURB: 20 FT 0 IN **INSPECTOR 3: OUT TO OUT: 25 FT 0 IN** NHS: NO FUNCTIONAL CLASS: RL-MAJOR COLLECTOR ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1933 **NBI OWNER: MODOT AADT:** 1248 **GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2022** MAINTENANCE DISTRICT: SE LOCATION: S 36 T 35 R 9 E **AADT TRUCK: 10.7% LATITUDE:** 37 41 16.55 (DMS) **MAINTENANCE COUNTY: PERRY FUTURE AADT: 1747 LONGITUDE:** 89 59 1.16 (DMS) SUB AREA: 7H36 **FUTURE AADT YEAR: 2042** ***INDEPTH INSPECTION INFORMATION*** ***FRACTURE CRITICAL INSPECTION INFORMATION*** DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL**: NBI**: **FREQUENCY: CALCULATED INTERVAL**: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** ***SPECIAL INSPECTION INFORMATION*** ***UNDERWATER INSPECTION INFORMATION*** **CATEGORY: SUPERSTRUCTURE DATE:** 10/10/2023 **CATEGORY: DRY DATE:** 09/19/2023 **RESPONSIBILITY: DISTRICT RESPONSIBILITY: DISTRICT** FREOUENCY: 60 NBI: NO FREOUENCY: 999 CALCULATED INTERVAL**: **NBI:** NO CALCULATED INTERVAL**: 12 **TEAM LEADER: ED HESS** TEAM LEADER: TERRY L SHUNAMON **INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 3: METHOD:** VISUAL **INSPECTOR 2:** ED HESS **INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** * When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** NO WT TAPE 09/02/2020 72 CHANNEL CROSS 75 DISTRICT SECTIONS 05/09/2017 999 NO DISTRICT DAMAGE POST INCIDENT

January 02, 2024 6:31:35AM

COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734 ***STRUCTURE POSTING*** **APPROVED CATEGORY: S-16** TRKS OVR 14 TNS 15MPH ON BR EXCPT SNGLE UNIT TRKS WT LIMIT 19 TNS&ALL OTHR TRKS WT LIMIT 33 TNS. **Ton 1:** 14 **Ton 2:** 19 **Ton 3:** 33 **COMMENTS:** FIELD CATEGORY: S-16 TRKS OVR 14 TNS 15MPH ON BR EXCPT SNGLE UNIT TRKS WT LIMIT 19 TNS&ALL OTHR TRKS **Ton 1:** 14 **Ton 2:** 19 **Ton 3:** 33 PROBLEM: PROBLEM DIRECTION: **COMMENTS:** ***GENERAL COMMENTS/MAJOR RATED ITEMS*** GENERAL COMMENTS: (BOWDEJ1, 09/04/2008)--(33'-31'-30'-49'-49'-26') SMP WF GDR SPANS [ITEM 58] DECK: 3-SERIOUS CONDITION COMMENTS: (DENNIB1, 10/17/2013)--EDGE DETERIORATION & SATURATION (WILSOT2, 10/23/2017)--LARGE FULL DEPTH PATCHES HEAVY SPALLS AT JOINTS **RATING:** 10/27/2022 [ITEM 59] SUPER: 3-SERIOUS CONDITION **COMMENTS:** (HESSE, 09/20/2023)--SECTION LOSS OF BOTTOM FLANGES **RATING:** 09/20/2023 [ITEM 60] SUB: 4-POOR CONDITION COMMENTS: (GOODMJ1, 02/21/2002)--SOUTHEAST BEARING SEAT AT 2ND BENT FROM SOUTH REPAIRED 1-02 HR2 (DENNIB1, 10/17/2013)--EXPOSED SPREAD FOOTING **RATING:** 10/13/2023 (BRAWLK1, 10/13/2023)--EXPOSED REBAR THROUGHOUT [ITEM 61] BANK/CHANNEL: 5-MAJOR DAMAGE COMMENTS: (CROCKC1, 05/22/2017)--SOUTH SLOPE WASHED DOWNSTREAM (WILSOT2, 10/23/2017)--MINOR BANK EROSION **RATING:** 10/25/2017 (WILSOT2, 10/25/2017)--BANK PROTECTION IS BEING ERODED [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED COMMENTS: (WILSOT2, 10/23/2017)--STABLE **RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: MINOR DELAYS APPRCH **COMMENTS: RATING:** 05/18/2001 [ITEM 72] APPRRDWY ALIGNMENT: 6-SATISFACTORY **COMMENTS: RATING:** 05/18/2001 ***RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS*** [ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 02/23/2004 **COMMENTS: DIRECTION MATERIAL CONSTRUCTION COMMENTS** STEEL ANGLE-DOUBLE **BOTH** REINFORCED CONCRETE BOTH **CURB [ITEM 36B] TRANSITION RAILING RATING:** NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36D] RAIL END TREATMENT RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:**

Design No = S0734

January 02, 2024 6:31:35AM

COUNTY: PERRY DISTRICT: SE

CLASS: STATBR

FED-ID: 8828

BRIDGE: S0734

ASPHALT	·	TRUCTION DIRECTION NOUS MAT BOTH		<u>COMMENTS</u>				
				III/GI ODE AND DEGIZ DI				
X PROTECTIVE COMPO	ONENTS:	***DRAINAGE, I	EXPANSION DEVICES, BAN	K/SLOPE, AND DECK PI	ROTECTIVE CON	IPONEN IS***		
SERIES TYPE-#	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>	<u>ON</u> <u>THICKNESS</u>	YEAR APPLIED	MANUFACTURE	OVERALL CONDITION	
MAIN SERIES-1	WEARING SURFACE	ASPHALT	BITUMINOUS N	MAT	2005		POOR	
COMMENT:								
	D E CW DD OTTE CTION	NOTABBLIGARIE	WOME					
~~~~~	DECK PROTECTION	NOTAPPLICABLE	NONE					
<u>COMMENT:</u>								
	MEMBRANE	NOTAPPLICABLE	NONE					
COMMENT.	MEMDKANE	NOTALLECABLE	NONE					
<u>COMMENT:</u>								
RAINAGE COMPONENTS:								
	<u>COMPONENT</u>	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>	<u>ON</u> <u>DIRECTION</u>	<u>COMMENTS</u>			
	<u>COMI ONENT</u> DRAINAGE	<u>MATERIAL</u> REINFORCED CONCR			COMMENTS			
PANSION DEVICE COMP								
<u>SUB UNIT-#</u> <u>SUB</u>	<u>B LABEL</u> <u>COMPO</u>	<u>NENT</u> <u>M</u>	<u>ATERIAL</u> <u>C</u>	<u>CONSTRUCTION</u>	<u>GAP</u> <u>YEAR</u>	<u>APPLIED</u> <u>MANUI</u>	FACTURE OVERALL CONDITION	
COLCLEDA								
<u>COMMENT:</u>								
NK/SLOPE PROTECTION	COMPONENTS.							
INN/SLUFE FRUIECTION	COMPONENTS.	<u>MATERIAL</u>	<u>CONSTRUCTIO</u>	<u>ON</u> <u>DIRECTION</u>	<u>COMMENTS</u>			
	BANK PROTECTION	ROCK	GROUTED		COMMENTS			
			***DECI	K COMPONENTS***				
SPAN TYPE-#	<u>COMPONENT</u>	<u>MATERIAL</u>	CONSTRUCTION	<u>COMMENTS</u>				
MAIN SPANS-1	DECK	REINFORCED CONCR						
COMP	<u>OITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u> <u>MEASURE</u>	<u>COMMEN</u>	<u>T</u>		
·		THROUGHOUT EDGE		MODERATE MODERATE				
DELAM		THROUGHOUT		HEAVY				
DELAM DETERI						(00/2005) 3443137344	DE BRIOR TO OVERY AVIOUS	
DELAM DETERI EFFLOR	ESCENCE TH PATCHES	THROUGHOUT		MANY	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEPT REBAR	ESCENCE TH PATCHES EXPOSED	THROUGHOUT THROUGHOUT		MINOR	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEP REBAR SATUI	ESCENCE TH PATCHES EXPOSED RATION	THROUGHOUT THROUGHOUT THROUGHOUT		MINOR MODERATE	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEP REBAR SATUI SPA	ESCENCE TH PATCHES EXPOSED RATION ALLS	THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT		MINOR MODERATE HEAVY	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEP REBAR SATUI SPA	ESCENCE TH PATCHES EXPOSED RATION	THROUGHOUT THROUGHOUT THROUGHOUT		MINOR MODERATE	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEPT REBAR SATUI SPA TRANSVER	ESCENCE TH PATCHES EXPOSED RATION ALLS RSE CRACKS	THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT	FTE CAST-IN-PI AC	MINOR MODERATE HEAVY MODERATE	(SIMPSB, 10	/08/2005)MANY MAI	DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEPT REBAR SATUI SPA TRANSVER	ESCENCE TH PATCHES EXPOSED RATION ALLS	THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT	ETE CAST-IN-PLAC <b>LOCATION 2</b>	MINOR MODERATE HEAVY MODERATE			DE PRIOR TO OVERLAY 2005	
DELAM DETERI EFFLOR FULL DEPT REBAR SATUI SPA TRANSVER  MAIN SPANS-2 COND	ESCENCE ITH PATCHES EXPOSED RATION ALLS RSE CRACKS	THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT THROUGHOUT  REINFORCED CONCR		MINOR MODERATE HEAVY MODERATE			DE PRIOR TO OVERLAY 2005	

**COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734** THROUGHOUT MODERATE EFFLORESCENCE (SIMPSB, 10/08/2005)--MANY MADE PRIOR TO OVERLAY 2005 **FULL DEPTH PATCHES** THROUGHOUT MANY REBAR EXPOSED THROUGHOUT **HEAVY** SATURATION THROUGHOUT **HEAVY** THROUGHOUT MANY **SPALLS** TRANSVERSE CRACKS THROUGHOUT **MODERATE** MAIN SPANS-3 DECKCAST-IN-PLACE REINFORCED CONCRETE **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY MEASUREMENT COMMENT** DELAMINATION THROUGHOUT **MODERATE EDGE MODERATE** DETERIORATION THROUGHOUT **EFFLORESCENCE** HEAVY (SIMPSB, 10/08/2005)--MANY MADE PRIOR TO OVERLAY 2005 **FULL DEPTH PATCHES** THROUGHOUT MANY THROUGHOUT **HEAVY** REBAR EXPOSED SATURATION THROUGHOUT **MODERATE** THROUGHOUT MANY SPALLS TRANSVERSE CRACKS THROUGHOUT **MODERATE** MAIN SPANS-4 DECK CAST-IN-PLACE REINFORCED CONCRETE **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY MEASUREMENT COMMENT DELAMINATION** THROUGHOUT **MODERATE** (DENNIB1, 10/10/2019)--SECOND LOCATION-JOINTS DETERIORATION **EDGE MODERATE** HEAVY EFFLORESCENCE THROUGHOUT **FULL DEPTH PATCHES** THROUGHOUT MANY (SIMPSB, 10/08/2005)--MANY MADE PRIOR TO OVERLAY 2005 REBAR EXPOSED THROUGHOUT HEAVY SATURATION THROUGHOUT **MODERATE** THROUGHOUT **SPALLS MODERATE** TRANSVERSE CRACKS THROUGHOUT **MODERATE** MAIN SPANS-5 DECKREINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT** THROUGHOUT **DELAMINATION MODERATE** DETERIORATION **EDGE** HEAVY (ROBINC3, 11/30/2018)--W/RUST STAINS **MODERATE EFFLORESCENCE** THROUGHOUT **FULL DEPTH PATCHES** THROUGHOUT MANY (SIMPSB, 10/08/2005)--MANY MADE PRIOR TO OVERLAY 2005 **MINOR** REBAR EXPOSED THROUGHOUT SATURATION THROUGHOUT **MINOR** SPALLS THROUGHOUT MINOR TRANSVERSE CRACKS THROUGHOUT **MODERATE** DECK MAIN SPANS-6 REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT** THROUGHOUT **MODERATE** DELAMINATION DETERIORATION **EDGE MODERATE EFFLORESCENCE** THROUGHOUT **MODERATE FULL DEPTH PATCHES** THROUGHOUT MANY (SIMPSB, 10/08/2005)--MANY MADE PRIOR TO OVERLAY 2005 REBAR EXPOSED THROUGHOUT **MINOR** THROUGHOUT MINOR SATURATION **SPALLS** THROUGHOUT **MODERATE** TRANSVERSE CRACKS THROUGHOUT **MODERATE** 

MoDOT

COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734

				SUPERSTRUCTURE COM		
SERIES TYPE-#	SPAN TYPE	<u>MATERI</u> A		<u>CONSTRUCTION</u>	<u>LABEL</u>	<u>COMMENTS</u>
MAIN SERIES-1	SIMPLE SPAN	STEEL	WII	DE FLANGE GIRDERS		(REHAGM, 02/27/2004)DECK BOLTED
<u>SPAN</u>	COMPOSITE INDICATOR	<u>LENGTH</u> <u>V</u>	<b>VEATHERING STEEL</b>	<u>COMMENTS</u>		
MAIN SPANS-1	NON-COMPOSITE	33 FT 0 IN	NO	<u> </u>		
CONDITION	LOCATA	TON 1	LOCATION 2	SEVERITY	<b>MEASUREMENT</b>	COMMENT
PACK RUST	EXTERIOR			MINOR		
PACK RUST	THROUG			MINOR		
RUSTING	BOTTOM I			MINOR		
RUSTING	THROUG			MINOR		(ROBINC3, 11/30/2018)PUMPING RUST
SECTION LOSS	AT JOI			MINOR		
SECTION LOSS	BOTTOM I			INITIAL		
SECTION LOSS	TOP FL			INITIAL		
MAIN SPANS-2	NON-COMPOSITE	31 FT 0 IN	NO			
<u>CONDITION</u>	<u>LOCAT</u>	<u> 10N 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PACK RUST	EXTERIOR	GIRDERS		MINOR		
PACK RUST	THROUG	GHOUT		MINOR		
RUSTING	BOTTOM I	FLANGE		MINOR		
RUSTING	THROUG	GHOUT		MINOR		(ROBINC3, 11/30/2018)PUMPING RUST
SECTION LOSS	BOTTOM I	FLANGE		INITIAL		(ELSEMJ, 01/24/2012)AT BEARING AREAS
SECTION LOSS	TOP FLA	ANGE		INITIAL		
MAIN SPANS-3	NON-COMPOSITE	30 FT 11 IN	NO			
<u>CONDITION</u>	<u>LOCAT</u>		<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PACK RUST	EXTERIOR			MINOR		
PACK RUST	THROUG			MODERATE		
RUSTING	BOTTOM I			SEVERE		
RUSTING	THROUG			MINOR		(ROBINC3, 11/30/2018)PUMPING RUST
SECTION LOSS	BOTTOM I			SEVERE		
SECTION LOSS	TOP FL	ANGE		SEVERE		
MAIN SPANS-4	NON-COMPOSITE	49 FT 1 IN	NO			
WAIN SPANS-4 <u>CONDITION</u>	LOCAT		LOCATION 2	SEVERITY	<b>MEASUREMENT</b>	COMMENT
· · · · · · · · · · · · · · · · · · ·			<u>LOCATION 2</u>		MEASUREMENT	COMMENT
PACK RUST PACK RUST	EXTERIOR			MINOR		
	THROUG			MINOR		
RUSTING	BOTTOM I			SEVERE MODERATE		(DODING) 11/20/2019) DUMBING BUST
RUSTING	THROUG			MODERATE		(ROBINC3, 11/30/2018)PUMPING RUST
SECTION LOSS SECTION LOSS	BOTTOM I TOP FLA			SEVERE MINOR		
SECTION LOSS	IOPTLA	ANUE		MINOK		
MAIN SPANS-5	NON-COMPOSITE	49 FT 1 IN	NO			
<u>CONDITION</u>	LOCAT		LOCATION 2	<u>SEVERITY</u>	<b>MEASUREMENT</b>	COMMENT
PACK RUST	EXTERIOR		<u> </u>	MODERATE	TILLING TENTETT	<u> </u>
PACK RUST	THROUG			MODERATE		
RUSTING	BOTTOM I			MINOR		
RUSTING	THROUG			MODERATE		
SECTION LOSS	TOP FLA			MINOR		
MAIN SPANS-6	NON-COMPOSITE	26 FT 11 IN	NO			

MODOT

MODERATE

MODERATE

**MEASUREMENT** 

**COMMENT** 

**DISTRICT: SE CLASS: STATBR COUNTY: PERRY FED-ID: 8828 BRIDGE: S0734** <u>SEVERITY</u>

**LOCATION 2** 

LOCATION 1

EXTERIOR GIRDERS

THROUGHOUT

RUSTING THROUGHOUT SECTION LOSS BOTTOM FLANGE SECTION LOSS TOP FLANGE SECTION LOSS WEB			MODERATE MODERATE SEVERE MINOR MODERATE	(ROBINC	(ROBINC3, 11/30/2018)PUMPING RUST		
				***SUBSTRUC	TURE COMPONENTS*	**	
SUBSTRUCTURE	<u>SKEW</u>	<b>LENGTH</b>	<u>MATERIAL</u>	<b>CONSTRUCTION</b>	<u>LABEL</u> <u>COMMENT</u>	<u>S</u>	
ABUTMENT-1		25 FT 0 IN	REINFORCED CONCRETE	OPEN CONCRETE			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	<u>ED COMPONENT</u>		<u>'ERIAL</u>	<u>CONSTRUCTION</u>			
BACKWAL		REIN	NFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	HORIZONTAL CRAC		THROUGHOUT		MEDIUM		
	REBAR EXPOSED	)	THROUGHOUT		MINOR		
DEALGAI	SPALLS	DED	THROUGHOUT	CACT DIDI ACE	MEDIUM		
BEAM CAI		REII	NFORCED CONCRETE	CAST-IN-PLACE	CELEBREY	ME ACUDEMENT	COMMENT
	<u>CONDITION</u>		LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DELAMINATION  DEDAR SECTION I		RANDOM		MINOR INITIAL		
	REBAR SECTION LC SPALLS	088	THROUGHOUT THROUGHOUT		MODERATE		(ROBINC3, 11/30/2018)W/EXPOSED REBAR
	VERTICAL CRACK	2	THROUGHOUT		MINOR		(ROBINCS, 11/30/2016)W/EAI OSED REDAR
COLUMN	V LICITCAL CRACK		NFORCED CONCRETE	CAST-IN-PLACE	MINOR		
COLONIII	<b>CONDITION</b>	TCE11	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
FOOTING	0011211011	REIN	NFORCED CONCRETE	SPREAD	<del>227 233 2</del>		<u> </u>
10011110	<b>CONDITION</b>	1011	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
STRAIGHT		REIN	NFORCED CONCRETE	CAST-IN-PLACE	<del></del>		
	CONDITION		LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
FIXED BEA		STE		FLAT PLATE			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	COMMENT
	PACK RUST		THROUGHOUT		MODERATE		
BENT-2		24 FT 4 IN	REINFORCED CONCRETE	MULTIPLE COLUMN			
	<b>CONDITION</b>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<u>ASSOCIAT</u>	ED COMPONENT	<u>MAT</u>	<u>'ERIAL</u>	<u>CONSTRUCTION</u>			
BEAM CAI		REIN	NFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>		<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	DELAMINATION		THROUGHOUT		MINOR		
	HORIZONTAL CRAC		THROUGHOUT		RANDOM		
	REBAR EXPOSED	)	BOTTOM		EXCESSIVE		(WILSOT2, 10/23/2017)ADVANCED SEC LOSS REBAR
	SPALLS VERTICAL CRACK	C	THROUGHOUT		MODERATE		
COLUMN	VERTICAL CRACK		THROUGHOUT NFORCED CONCRETE	CAST-IN-PLACE	MINOR		
COLUMIN	<b>CONDITION</b>	KEII	LOCATION 1	LOCATION 2	SEVERITY	MEASUREMENT	COMMENT
	HORIZONTAL CRAC	rks	THROUGHOUT	LOCATION 2	MANY	THE ISOMERIENT	(ROBINC3, 01/24/2019)ON COLUMN CAPITOL
	REBAR SECTION LO		THROUGHOUT		INITIAL		(ROBINC3, 01/24/2019)ON COLUMN CAPITOL
	SPALLS	,55	COLUMN		MINOR		(ROBINC3, 11/30/2018)W/EXPOSED REBAR
					1122.021		(ROBINC3, 01/24/2019)ON COLUMN CAPITOL
FOOTING		REIN	NFORCED CONCRETE	SPREAD			
	<b>CONDITION</b>		LOCATION 1	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>

MODOT

**CONDITION** 

PACK RUST PACK RUST

**COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734** THROUGHOUT MODERATE EXPOSED FIXED BEARING STEEL FLAT PLATE **SEVERITY CONDITION** LOCATION 1 **LOCATION 2** MEASUREMENT COMMENT PACK RUST THROUGHOUT **MINOR** BENT-3 24 FT 4 IN REINFORCED CONCRETE MULTIPLE COLUMN **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY** MEASUREMENT COMMENT ASSOCIATED COMPONENT **MATERIAL CONSTRUCTION** REINFORCED CONCRETE BEAM CAP CAST-IN-PLACE LOCATION 1 LOCATION 2 **CONDITION SEVERITY MEASUREMENT COMMENT DELAMINATION** THROUGHOUT **MODERATE** HORIZONTAL CRACKS THROUGHOUT **MINOR** (ROBINC3, 11/30/2018)--W/RUST STAINS **SPALLS** THROUGHOUT **MEDIUM** VERTICAL CRACKS THROUGHOUT **MINOR** COLUMN REINFORCED CONCRETE **CAST-IN-PLACE CONDITION LOCATION 1** LOCATION 2 **SEVERITY** MEASUREMENT **COMMENT DELAMINATION MODERATE** THROUGHOUT REBAR EXPOSED THROUGHOUT MINOR (ROBINC3, 11/30/2018)--W/INIT SECT LOSS **SPALLS** THROUGHOUT **MEDIUM FOOTING SPREAD** REINFORCED CONCRETE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY** *MEASUREMENT* **COMMENT EXPOSED MODERATE THROUGHOUT SCALING THROUGHOUT MODERATE** FIXED BEARING STEEL FLAT PLATE **CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT** PACK RUST THROUGHOUT MINOR BENT-4 24 FT 4 IN REINFORCED CONCRETE MULTIPLE COLUMN **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY COMMENT** MEASUREMENT ASSOCIATED COMPONENT **CONSTRUCTION MATERIAL** BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 **LOCATION 2 SEVERITY** MEASUREMENT COMMENT **DELAMINATION** THROUGHOUT MINOR **EFFLORESCENCE** THROUGHOUT **MINOR** HORIZONTAL CRACKS THROUGHOUT FINE **MINOR** REBAR EXPOSED THROUGHOUT REBAR SECTION LOSS THROUGHOUT **MINOR SEALED** BEAM CAP ASPHALTICBASE **SPALLS** THROUGHOUT **MODERATE** COLUMN **CAST-IN-PLACE** REINFORCED CONCRETE LOCATION 1 LOCATION 2 **SEVERITY** MEASUREMENT COMMENT **CONDITION DELAMINATION** THROUGHOUT MINOR MANY HORIZONTAL CRACKS THROUGHOUT REBAR EXPOSED **MINOR THROUGHOUT REBAR SECTION LOSS** THROUGHOUT **INITIAL SCALING** THROUGHOUT MINOR **SPALLS** THROUGHOUT **MODERATE FOOTING** SPREAD REINFORCED CONCRETE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY COMMENT** MEASUREMENT **EXPOSED THROUGHOUT MODERATE** FIXED BEARING STEEL FLAT PLATE **LOCATION 1 CONDITION** LOCATION 2 **SEVERITY** MEASUREMENT COMMENT PACK RUST **THROUGHOUT MINOR** 

MODOT

COUNTY: PERRY DISTRICT: SE CLASS: STATBR FED-ID: 8828 BRIDGE: S0734

MATERIAL   LOCATION   SEVERITY   MEASUREMENT   COMMENT	DENTE C		ALET AN DENIEODOED CONCRETE				
### ASSOCIATED COMPONENT  ### RENT-60 CONCERTS    CONTROL   LOCATION   LOCATION   LOCATION	BENT-5			MULTIPLE COLUMN	CEI/EDITV	MEACHDEMENT	COMMENT
REFINENCE   CONCRETE   CASTIN-PLACE   CASTIN-PLAC	ASSOCIATEI				<u>SEVERITI</u>	MEASUREMENT	<u>COMMENT</u>
DELAMINATION THROUGHOUT MODERATE REAR EXPOSED THROUGHOUT MISSOR STALLS REPORTED THROUGHOUT MISSOR STALLS REPORTED THROUGHOUT MISSOR MIS		COMI ONENI					
BLLAMINATION RUBBER LEVOSUD  READ CONDITION  RUBBER LEVOSUD  SCALING  SCALING  SCALING  SCALING  SCALING  SCALING  SCALING  SPALLS  REINFORCED CONCRETE  LOCATION LOC	BEAW CAF	CONDITION			CFVFRITV	MEASUREMENT	COMMENT
REBAR EXPOSED SCALING SPALES SCALING SPALES SPALES SPALES SPALES SPALES SPALES SPALES SPALES COLUMN CODITION POOTING CONDITION POOTING CONDITION POOTING CONDITION PEXPOSED STEL COCATION: MATERIAL COCATION: PEXPOSED STEL COCATION: MATERIAL COCATION: PEXPOSED STEL COCATION: PEXPOSED STEL COCATION: MATERIAL COCATION: PEXPOSED STEL STEL COCATION: PEXPOSED STEL STEL COCATION: PEXPOSED STEL STEL STEL STEL STEL STEL S				EOCATION 2		MEASUREMENT	COMMENT
SCALING   THROUGHOUT   CAST-IN-PLACE   CAST-IN-PLACE   COMMENT							
SPALLS   THROUGHOUT   CAST-IN-PLACE   CAST-I							
COLUNN   CONDITION   LOCATION   LOCATION   LOCATION   SPENAD   LOCATION   LOCATION   SPENAD   LOCATION   LOC							
FOOTING	COLUMN	STALLS		CAST-IN-PLACE	MODERNIE		
FOOTING CONDITION EXPOSED CONCRETE LOCATION! FIXED BEARING CONDITION EXPOSED THROUGHOUT  BEATLA CONDITION PACK RIST THROUGHOUT  FINED BEARING CONCRETE  COLUMN CONDITION PACK RIST THROUGHOUT  FIXED BEARING CONDITION PACK RIST THROUGHOUT  FIXED BEARING CONDITION PACK RIST THROUGHOUT  FIXED BEARING STEEL LOCATION!  BEATLA CONDITION PACK RUST THROUGHOUT  ABRITMENT CONDITION PACK RUST THROUGHOUT  BEAK RUST THROUGHOUT  ABRITMENT CONDITION PACK RUST THROUGHOUT  ABRITMENT CONDITION PACK RUST THROUGHOUT  BEAK RUST THROUGHOUT  BEAK RUST THROUGHOUT  BEAK RUST THROUGHOUT  BEAK RUST ON THROU		<b>CONDITION</b>			SEVERITY	MEASUREMENT	COMMENT
EXPOSED THROUGHOUT HOLOGION PACK RUST THROUGHOUT SUPPLIES OF STEEL LOCATION PACK RUST THROUGHOUT SUPPLIES OF STEEL SUPPL	FOOTING						
EXPOSED THROUGHOUT FLAT PLATE  CONDITION PACK RUST THROUGHOUT LOCATION 1  BENT-6  BENT-6  CONDITION LOCATION 1  ASSOCIATED COMPONENT REINFORCED CONCRETE DELAMINOR LOCATION 2  BEAM CAP  CONDITION LOCATION 1  DELAMINATION HORIZONIAL CRACKS THROUGHOUT LOCATION 2  SELECTIVE MACSUREMENT COMMENT  BEAM CAP  COLUMN REINFORCED CONCRETE CAST-IN-PLACE  COLUMN REINFORCED CONCRETE CAST-IN-PLACE  COLUMN REINFORCED CONCRETE CAST-IN-PLACE  CONDITION LOCATION 1  BEAM CAP  CONDITION LOCATION 1  FINED BEAM CAP  CONDITION LOCATION 1  LOCATION 1  LOCATION 2  SEVERITY MEASUREMENT COMMENT  MINOR ASPHALITICABLE  CONDITION LOCATION 1  LOCATION 1  LOCATION 1  LOCATION 2  SEVERITY MEASUREMENT COMMENT  MATERIAL COMMENT  MASSUREMENT  MASSUR		<b>CONDITION</b>			SEVERITY	MEASUREMENT	COMMENT
FIXED BEARING CONDITION PACK RUST THROUGHOUT THROUGHOUT  BENT-6  CONDITION ASSOCIATED COMPONENT BEAM CAP CONDITION DELAMINATION HORIZONTAL CRACKS BEAM CAP HORIZONTAL CRACKS BEAM CAP COLUMN FOOTING CONDITION CONDITION DELAMINATION HORIZONTAL CRACKS BEAM CAP FOOTING CONDITION CONDITION FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FIXED BEARING CONDITION THROUGHOUT FIXED BEARING CONDITION THROUGHOUT FIXED BEARING CONDITION THROUGHOUT FIXED BEARING CONDITION THROUGHOUT THROUGHOU							
CONDITION   LOCATION   LOCATION   LOCATION   LOCATION   MINOR   MINOR	FIXED BEAR			FLAT PLATE			
BENT-6  24 FT 4 IN REINFORCED CONCRETE CONDITION ASSOCIATED COMPONENT BEAM CAP  DELAMINATION HORIZONTAL CRACKS FOOTING COLUMN FOOTING FOOTING CONDITION FOOTING FOR CONDITION FIRE CONCRETE CONDITION REINFORCED CONCRETE CONTROL CRACKS FOOTING FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FIXED BEARING FOOTING CONDITION FIXED BEARING FOOTING CONDITION FOOTING F		<b>CONDITION</b>			<u>SEVERITY</u>	<b>MEASUREMENT</b>	COMMENT
BENT-6  24 FT 4 IN REINFORCED CONCRETE CONDITION ASSOCIATED COMPONENT BEAM CAP  DELAMINATION HORIZONTAL CRACKS FOOTING COLUMN FOOTING FOOTING CONDITION FOOTING FOR CONDITION FIRE CONCRETE CONDITION REINFORCED CONCRETE CONTROL CRACKS FOOTING FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FOOTING CONDITION FIXED BEARING FOOTING CONDITION FIXED BEARING FOOTING CONDITION FOOTING F		PACK RUST	THROUGHOUT		MINOR		
CONDITION ASSOCIATED COMPONENT BEAM CAP BEAM CAP DELAMINATION HORIZONTAL CRACKS THROUGHOUT HORIZONTAL CRACKS THROUGHOUT COLUMN FOOTING CONDITION FINIOR CONDITION LOCATION I LOC							
CONDITION ASSOCIATED COMPONENT BEAM CAP BEAM CAP OLL AMINOTON HORIZONTAL CRACKS THROUGHOUT HORIZONTAL CRACKS THROUGHOUT  COLUMN SFALED CONDITION CONDITION LOCATION I	BENT-6		24 FT 4 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
ASSOCIATED COMPONENT BEAM CAP REINFORCED CONCETE CONSTRUCTION DELAMINATION THROUGHOUT HORIZONTAL CRACKS THROUGHOUT FOOTING FOOTING FOOTING FIXED BEARING FIX	BEITT 0				SEVERITY	MEASUREMENT	COMMENT
BEAM CAP  CONDITION DELAMINATION HORIZONTAL CRACKS THROUGHOUT ASPHALTICBASE  COLUMN REINFORCED CONCRETE CAST-IN-PLACE COLUMN REINFORCED CONCRETE SPREAD FOOTING REINFORCED CONCRETE LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT FIXED BEARING STEEL FLAT PLATE CONDITION PACK RUST THROUGHOUT FIXED BEARING STEEL FLAT PLATE ABUTMENT-7 CONDITION LOCATION 1 LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MODERATE  ABUTMENT-7 CONDITION LOCATION 1 LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MODERATE  ABUTMENT-7 CONDITION LOCATION 1 LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MODERATE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MODERATE  COMMENT ASSOCIATED COMPONENT MATERIAL CONSTRUCTION MATERIAL CONSTRUCTION MEASUREMENT COMMENT MEASUREMENT COMMENT COMMENT MEASUREMENT MEA	ASSOCIATEL			·	<del></del>		
CONDITION   LOCATION   LOCATION   LOCATION   MINOR							
DELAMINATION THROUGHOUT MINOR HORIZONTAL CRACKS THROUGHOUT MINOR SEALED BEAM CAP COLUMN REINFORCED CONCRETE CAST-IN-PLACE  COLUMN REINFORCED CONCRETE SPREAD FOOTING REINFORCED CONCRETE SPREAD  CONDITION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  FIXED BEARING STEEL FLAT PLATE  CONDITION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  FIXED BEARING THROUGHOUT MODERATE  ABUTMENT-7 25 FT 0 IN REINFORCED CONCRETE OPEN CONCRETE CONDITION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  ASSOCIATED COMPONENT MATERIAL CONSTRUCTION BACKWALL REINFORCED CONCRETE CAST-IN-PLACE CONDITION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  ASSOCIATED COMPONENT MATERIAL CONSTRUCTION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  ASSOCIATED CONFORCED CONCRETE CONSTRUCTION BACKWALL REINFORCED CONCRETE CAST-IN-PLACE CONDITION LOCATION I LOCATION 2 SEVERITY MEASUREMENT COMMENT  MATERIAL CONSTRUCTION LOCATION I LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT		<b>CONDITION</b>			SEVERITY	MEASUREMENT	COMMENT
HORIZONTAL CRACKS SEALED BEAM CAP SEALED COLUMN REINFORCED CONCRETE COLUMN REINFORCED CONCRETE COLUMN REINFORCED CONCRETE SPREAD  CONDITION REINFORCED CONCRETE SPREAD  CONDITION REINFORCED CONCRETE SPREAD  FIXED BEARING FIXED BEARING FIXED BEARING REASUREMENT CONDITION PACK RUST THROUGHOUT REINFORCED CONCRETE OPEN CONCRETE OPEN CONCRETE OPEN CONCRETE ABUTMENT-7 ASSOCIATED COMPONET BACKWALL REINFORCED CONCRETE CONDITION ASSOCIATED COMPONET REINFORCED CONCRETE CONDITION REINFORCED CONCRETE CONSTRUCTION CONSTRUCTION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MEASUREMENT MEASUREMENT COMMENT MEASUREMENT COMMENT MEASUREMENT COMMENT MEASUREMENT MEASUREM							
SEALED BEAM CAP  COLUMN REINFORCED CONCRETE CAST-IN-PLACE  CONDITION REINFORCED CONCRETE SPREAD  CONDITION REINFORCED CONCRETE SPREAD  CONDITION REINFORCED CONCRETE SPREAD  CONDITION FIXED BEARING FIXED BEARING PACK RUST THROUGHOUT  ABUTMENT-7  ASSOCIATED COMPONENT BACKWALL CONDITION LOCATION 1 REINFORCED CONCRETE CONDITION LOCATION 1 LOCATION 2 PENFORCED CONCRETE CONSTRUCTION 2 SEVERITY MEASUREMENT COMMENT MATERIAL CONSTRUCTION 2 SEVERITY MEASUREMENT COMMENT MATERIAL CONSTRUCTION 2 SEVERITY MEASUREMENT COMMENT COMMENT MEASUREMENT COMMENT	F						
FOOTING REINFORCED CONCRETE SPREAD  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT  FIXED BEARING STEEL FLAT PLATE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT  FIXED BEARING CONDITION PACK RUST THROUGHOUT MODERATE  ABUTMENT-7 25 FT 0 IN REINFORCED CONCRETE OPEN CONCRETE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT  ASSOCIATED COMPONENT MATERIAL CONSTRUCTION  BACKWALL REINFORCED CONCRETE CAST-IN-PLACE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT  ASSOCIATED CONDITION REINFORCED CONCRETE CAST-IN-PLACE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT					ASPHALTICBASE		
FOOTING CONDITION LOCATION 1 LOCATION 2 FIXED BEARING FIXED BEARING FIXED BEARING FIXED BEARING FIXED BEARING CONDITION LOCATION 1 LOCATION 1 LOCATION 2 FIXED BEARING CONDITION PACK RUST FIXED BEARING FIXED BEARING CONDITION FIXED BEARING CONDITION FIXED BEARING CONDITION FIXED BEARING CONDITION FIXED BEARING	COLUMN		REINFORCED CONCRETE	CAST-IN-PLACE			
FIXED BEARING FIXED PEACH STREET FLAT PLATE FLAT PLA		<b>CONDITION</b>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARING STEEL FLAT PLATE CONDITION LOCATION 1 PACK RUST THROUGHOUT  ABUTMENT-7 CONDITION LOCATION 1 LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MODERATE  OPEN CONCRETE CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT MATERIAL CONSTRUCTION BACKWALL REINFORCED CONCRETE CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT	FOOTING		REINFORCED CONCRETE	SPREAD			
ABUTMENT-7  25 FT 0 IN REINFORCED CONCRETE CONDITION BACKWALL REINFORCED CONCRETE CONDITION BACKWALL CONDITION LOCATION 1 LOCATION 2 CONDITION CONDITION BACKWALL CONDITION LOCATION 1 LOCATION 2 CONSTRUCTION CONSTRUCTION LOCATION 2 CONSTRUCTION CONSTRUCTION LOCATION 1 LOCATION 2 CONSTRUCTION CONSTRUCTION LOCATION 1 LOCATION 2 CONSTRUCTION CON		<b>CONDITION</b>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ABUTMENT-7  25 FT 0 IN REINFORCED CONCRETE  CONDITION  ASSOCIATED COMPONENT BACKWALL REINFORCED CONCRETE CONDITION  1 LOCATION 1 1 LOCATION 2 1 CONSTRUCTION CONSTRUCTION CONSTRUCTION CONDITION LOCATION 1 1 LOCATION 2 25 FT 0 IN REINFORCED CONCRETE CONSTRUCTION CONSTRUCTION CONSTRUCTION CONSTRUCTION CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT	FIXED BEAR	ING	STEEL	FLAT PLATE			
ABUTMENT-7  CONDITION  LOCATION 1  LOCATION 2  SEVERITY MEASUREMENT COMMENT  ASSOCIATED COMPONENT  BACKWALL  REINFORCED CONCRETE  CONDITION  LOCATION 1  LOCATION 2  SEVERITY MEASUREMENT COMMENT  CONSTRUCTION  SEVERITY MEASUREMENT COMMENT  MATERIAL  CONDITION  LOCATION 1  LOCATION 2  SEVERITY MEASUREMENT COMMENT		<b>CONDITION</b>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
CONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENTASSOCIATED COMPONENTMATERIALCONSTRUCTIONBACKWALLREINFORCED CONCRETECAST-IN-PLACECONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENT		PACK RUST	THROUGHOUT		MODERATE		
CONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENTASSOCIATED COMPONENTMATERIALCONSTRUCTIONBACKWALLREINFORCED CONCRETECAST-IN-PLACECONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENT							
CONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENTASSOCIATED COMPONENTMATERIALCONSTRUCTIONBACKWALLREINFORCED CONCRETECAST-IN-PLACECONDITIONLOCATION 1LOCATION 2SEVERITYMEASUREMENTCOMMENT	ABUTMENT-7		25 FT 0 IN REINFORCED CONCRETE	OPEN CONCRETE			
ASSOCIATED COMPONENT MATERIAL CONSTRUCTION  BACKWALL REINFORCED CONCRETE CAST-IN-PLACE  CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT					<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>	<u>ASSOCIATED</u>	O COMPONENT		<u>CONSTRUCTION</u>			
	BACKWALL		REINFORCED CONCRETE	CAST-IN-PLACE			
BEAM CAP REINFORCED CONCRETE CAST-IN-PLACE		<b>CONDITION</b>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
	BEAM CAP		REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>		<b>CONDITION</b>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<b>MEASUREMENT</b>	<u>COMMENT</u>
DELAMINATION RANDOM MINOR		DELAMINATION	RANDOM		MINOR		
HORIZONTAL CRACKS THROUGHOUT MEDIUM	F	HORIZONTAL CRACK	THROUGHOUT		MEDIUM		
VERTICAL CRACKS RANDOM MINOR		VERTICAL CRACKS			MINOR		
COLUMN REINFORCED CONCRETE CAST-IN-PLACE	COLUMN						
<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>		<u>CONDITION</u>		·	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FOOTING REINFORCED CONCRETE SPREAD	FOOTING						
<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>					<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
STRAIGHT WINGS REINFORCED CONCRETE CAST-IN-PLACE	STRAIGHT W						
<u>CONDITION</u> <u>LOCATION 1</u> <u>LOCATION 2</u> <u>SEVERITY</u> <u>MEASUREMENT</u> <u>COMMENT</u>			<u></u>	<u> </u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED BEARING STEEL FLAT PLATE	FIXED BEAR	ING	STEEL	FLAT PLATE			

MODOT

MoDOT

# **Missouri Department of Transportation State Bridge Inspection Report**

January 02, 2024 6:31:35AM

**COUNTY: PERRY DISTRICT: SE CLASS: STATBR**  **FED-ID: 8828** 

**BRIDGE: S0734** 

**CONDITION** PACK RUST

LOCATION 1 THROUGHOUT **LOCATION 2** 

RIGHT LATERAL CLEARANCE

**SEVERITY** MODERATE

MEASUREMENT COMMENT

***OVER/UNDER ROUTES CLEARANCE INFORMATION***

**CLEARANCES OVER DECK** 

**NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

**VERTICAL CLEARANCE TYPE**** 

**VALUE** 

**DIRECTION** 

**DIRECTION OF TRAFFIC** 

**DATE** 

**COMMENT** 

**COMMENT** 

CLEARANCES UNDER BRIDGE

RECORD #

**NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

**LEFT LATERAL CLEARANCE** 

**UR-ID** 

**DEPARTMENT REPAINT** 

**MANUFACTURE:** 

**SURFACE PREP:** 

**VERTICAL CLEARANCE TYPE**** 

**ROUTE** 

**VALUE** 

# LANES

**DIRECTION** 

**DATE** 

***STRUCTURE PAINT INFORMATION***

**CONDITION:** 

**RUST AMOUNT:** 5=3.0% OF SURFACE RUSTED

STEEL TONS: 42

**ORIGINAL PAINT PAINT TYPE:** 

**CONTRACT REPAINT** 

**PAINT TYPE:** C SYSTEM

PAINT COLOR: ALUMINUM

**NAME:** INORGANIC ZINC/VINYL

**PAINT TYPE:** NAME:

**PAINT COLOR: PAINT YEAR:** 

NAME:

PAINT YEAR: 1997

**PAINT COLOR: PAINT YEAR:** 

MILS:

**FAIR** 

**MILS:** 8

MILS:

***REQUESTED WORK ITEMS***

**GENERAL WORK COMMENTS:** 

RESPONSIBILITY **LOCATION** DISTRICT SPECIAL

**BENT JOINT** 

**ITEM** REPAIR DECK JOINTS W/CONC **CATEGORY** DECK

**PRIORITY** 2

**DATE** 

**WORK ITEM COMMENT** 10/26/2022

***UTILITY ATTACHMENTS***



January 02, 2024 6:31:35AM

COUNTY: PERRY DISTRICT: SE

**CLASS: STATBR** 

FED-ID: 8828

**BRIDGE: S0734** 

UTILITY OWNER METHOD MEASUREMENT TYPE VALUE NUMBER UTILITY ATTACHMENT COMMENT


***PROGRAM NOTES INFORMATION***

YEAR PROJECT # MONTH LET YEAR LET ITEMS COMMENT

2025 9S3670 0 2025 REPLACE BRIDGE

***COMPUTER GENERATED RATINGS AND DEFICIENCY ITEMS*** ***ADVANCED SIGN INFORMATION*** NOTE: The items listed in this section are updated whenever computer edits are ran on a structure after the inspection updates have been entered in to TMS. SIGN# **SIGN TYPE PROBLEM** PROBLEM DIRECTION **Rating Date** Rated Item Rating 2-BASICALLY INTOLRBLE REQ 12/7/2023 [Item 67] Structure Evaluation Rating: 1/5/2009 [Item 68] Deck Geometry Rating: 2-BASICALLY INTOLRBLE REQ [Item 69] Underclearance: N-NOT APPLICABLE 5/18/2001 10/28/2022 **Sufficiency Rating:** 2.0% STRUCTURAL 4/2/2003 **Deficiency: Funding Eligibility: FULL** ***OUTFALL INSPECTION INFORMATION*** **Estimated New Structure Length:** 253 FT. **# OUTFALLS: INSPECTOR: Estimated Structure Cost:** \$1,467,147 **STATUS:** DATE: **Estimated Total Project Cost:** \$2,200,721 2023 **Year of Cost Estimate: NOTES:** 

NOTE: The above structure length and cost estimates are computer generated using algorithms in the TMS system. These algorithms are generalized to use NBI items to come up with a new structure length and width to calculate a new area which is taken times a representative cost per square foot. The actual structure size and cost may vary significantly from these numbers once site specific engineering is done.





#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: PERRY S0734 REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 12/7/2023 2023 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District SE 5B Route Signing Prefix MAINLINE PERRY County 5C Designated Level of Service T0000 8828 8 Federal ID No. 5D Route Number 1933 NOT APPLICABLE 27 5E Year Built Directional Suffix RT T E 106 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY 21 Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance NOT ELIGIBLE FOR NR OF HP 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 1248 4 Place ST. MARYS 29 AADT 65036 2022 Code 30 AADT Year 2-WAY TRAFFIC S 36 T 35 N R 9 E Location 102 Direction of Traffic 11 Milepoint 20.13 miles 11% 109 AADT Truck Percent 16 Latitude 37 D 41 M 17 S 1747 114 Future AADT 17 Longitude 89 D 59 M 1 S 2042 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION 6 SALINE CR 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 57.50 miles Type of Service Under By pass Detour Length 00 28B Lanes Under Structure 32 Approach Roadway Width 21 Ft. 12 In. N/A 0.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 23 Ft. 11 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 49 Ft. 3 In. 220 Ft. 2 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 20 Ft. 0 In. 40 Nav Horizontal Clear 51 24 Ft. 11 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck



#### Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

January 2, 2024 6:29:36am

COUNTY: PERRY BRIDGE: \$0734 REVIEW STATUS: APPROVED NBI STATUS: T
RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 12/7/2023 SUBMITTAL YEAR: 2023

LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION					
LOAD RATING AND POSTING INFORMATION  31 Design Load H 10  41 Structure Status POSTED FOR LOAD  63 Oper. Rating Meth. LOAD FACTOR  64 Operating Rating 17 Tons.  65 Inventory Rating Meth LOAD FACTOR  66 Inventory Rating 10 Tons.  70 Bridge Posting Code >39.9% BELOW  PROPOSED IMPROVEMENT INFORMATION  Sufficiency Rating 2.0 Percent STRUCTURAL	MATERIAL/CONSTRUCTION INFORMATION  43A Main Struc. Mat type STEEL  43B Main struc Constr. Type STRINGER/MULTIBEAM - GRD  45 # of Main Spans 6  44A Appr Struc. Mat type 000  44B Appr Struc. Cnstr. type 000  46 # of Approach Span 0  107 Deck Mat/Constr. 1 CONCRETE CIP  108A Wear Surf Mat/Constr. 6 BITUMINOUS  108B Membrane Mat/Constr. 0 NONE  108C Deck Protect Mat/Constr. 0 NONE					
Funding Eligibility FULL  75A Proposed Work REPLACEMENT SUBSTND LOAD  75B Work Done By Contract  76 New Struc Length 252 Ft. 7 In.  94 Struc Improve Cost \$ 1,467,000  95 Roadway Improve Cost \$ 147,000	CONDITION RATING INFORMATION           58         Deck Cond. Rating         3           59         Superstructure Cond. Rating         3           60         Substructure Cond. Rating         4           61         Channel /Channel Protection Cond. Rating         5           62         Culvert Cond. Rating         N					
96 Total Project Cost \$ 2,201,000 97 Year of Cost Estimates 2023	INSPECTION INFORMATION  90 Gen. Insp Date 10 / 23					
APPRAISAL RATING INFORMATION  36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND  36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND  36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND  36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND  67 Struc Eval App. Rating 2  68 Deck Geometry App. Rating 2  69 Underclearance App. Rating N  71 Waterway Adeq. App. Rating 5  72 Approach Road App. Rating 6  113 Scour Assess App. Rating 8	90 Gen. Insp Date 10723  91 Gen. Insp. Frequency 12 Months  92A Frac. Critical Inspection N Months  93A Frac. Critical Insp. Date  92B Underwater Inspection N Months  93B Underwater Insp. Date  92C Special Inspection N Months  93C Special Inspection Date  BORDER BRIDGE INFORMATION  98 Neighboring State Code  98B Neighboring State % Respon					
APPROVED POSTING INFORMATION  Approved Posting Category S-16	99 Neighboring State Struc. No.  FIELD POSTING INFORMATION  Field Posting Category S-16					
Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 14 19 33  General Text for Posting Sign  TRKS OVR 14 TNS 15MPH ON BR EXCPT SNGLE UNIT TRKS WT LIMIT 19 TNS&ALL OTHR TRKS WT LIMIT 33 TNS.	Ton1 Ton2 Ton3  Tonnage Values for Posting Sign 14 19 33  General Text for Posting Sign  TRKS OVR 14 TNS 15MPH ON BR EXCPT SNGLE UNIT TRKS WT LIMIT 19 TNS&ALL OTHR TRKS WT LIMIT 33 TNS.					

Design_No = S0734 and Inventory_Appraisal_Submittal_Year = 2023