



1117


ending the major to an





TO COMPUTED ON SU SYOUS

し、し









March 05, 2024 6:59:05AM

COUNTY: STODDARD DISTRICT: SE CLASS: STATBR FED-ID: 4489 BRIDGE: F0565

GENERAL STRUCTURE INFORMATION ***BRIDGE INSPECTION INFORMATION*** ROUTE: MO114E # **SPANS**: 5 PLACE CODE: 61616 RICHLAND **DATE:** 10/16/2023 **RESPONSIBILITY: DISTRICT** LANES ON: 2 FEATURE: LIT RVR DRAIN DTCH LENGTH: 247 FT 0 IN FREQUENCY: 24 **CALCULATED INTERVAL**: 24** LANES UNDER: 0 STATUS: A-OPEN **MAXIMUM SPAN: 60 FT 5 IN TEAM LEADER: JERROD JERNIGAN ELEMENT: NO LOG MILE:** 13.946 **COMPASS DIRECTION: WEST to EAST** APPROACH ROADWAY: 26 FT 0 IN **INSPECTOR 2: INSPECTOR 4: DETOUR:** 8.00 MILES **DIRECTION OF TRAFFIC: 2-WAY TRAF CURB TO CURB: 26 FT 0 IN INSPECTOR 3: OUT TO OUT: 33 FT 0 IN** NHS: NO **FUNCTIONAL CLASS: RL-MAJOR COLLECTOR** ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. **BUILT:** 1949 **NBI OWNER: MODOT AADT:** 812 **GENERAL INSPECTION COMMENTS** REHAB: **NBI MAINTAINED: MODOT AADT YEAR: 2023** MAINTENANCE DISTRICT: SE LOCATION: S 2 T 25 R 12 E **AADT TRUCK: 13.6% LATITUDE:** 36 50 3.98 (DMS) MAINTENANCE COUNTY: STODDARD **FUTURE AADT: 1137 LONGITUDE:** 89 43 48.78 (DMS) SUB AREA: 7H11 **FUTURE AADT YEAR: 2043** ***INDEPTH INSPECTION INFORMATION*** ***FRACTURE CRITICAL INSPECTION INFORMATION*** DATE: RESPONSIBILITY: **CATEGORY: CATEGORY:** DATE: **RESPONSIBILITY: FREQUENCY: CALCULATED INTERVAL**: NBI**: **FREQUENCY: CALCULATED INTERVAL**: NBI**: **TEAM LEADER: INSPECTOR 3: METHOD: TEAM LEADER: INSPECTOR 3: METHOD: INSPECTOR 2: INSPECTOR 4: INSPECTOR 2: INSPECTOR 4:** ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. FRACTURE CRITICAL INSPECTION COMMENTS **INDEPTH INSPECTION COMMENTS** ***SPECIAL INSPECTION INFORMATION*** ***UNDERWATER INSPECTION INFORMATION*** **DATE:** 06/27/2022 **CATEGORY:** CHANNEL CROSS SECT **CATEGORY: SHALLOW-WADE RESPONSIBILITY: DISTRICT DATE:** 06/29/2022 **RESPONSIBILITY:** DIVETEAM **NBI:** NO FREOUENCY: 120 CALCULATED INTERVAL**: 119 **NBI:** NO FREOUENCY: 60 CALCULATED INTERVAL**: 59 **TEAM LEADER: INSPECTOR 3: METHOD:** WT TAPE **TEAM LEADER:** TERRY L SHUNAMON **INSPECTOR 3: MATT TALKEN METHOD: INSPECTOR 2:** JERROD JERNIGAN **INSPECTOR 4: INSPECTOR 2:** ADAM ZENTZ **INSPECTOR 4:** * When calculated interval exceeds the frequency, a justification comment per BIRM is required. ** When calculated interval exceeds the frequency, a justification comment per BIRM is required. SPECIAL INSPECTION COMMENTS **UNDERWATER INSPECTION COMMENTS** OTHER SPECIAL INSPECTIONS OTHER UNDERWATER INSPECTIONS DATE **FREQUENCY CATEGORY** CALCULATED INTERVAL RESPONSIBILITY **METHOD** DATE **FREQUENCY CATEGORY** NBI CALCULATED INTERVAL RESPONSIBILITY **METHOD** NO VISUAL 05/09/2017 DAMAGE POST DISTRICT INCIDENT

6:59:05AM

Missouri Department of Transportation State Bridge Inspection Report

COUNTY: STODDARD

DISTRICT: SE

CLASS: STATBR

FED-ID: 4489

BRIDGE: F0565 ***STRUCTURE POSTING*** APPROVED CATEGORY: S-1 NO POSTING REQUIRED **Ton 1: Ton 2: Ton 3: COMMENTS:** FIELD CATEGORY: S-1 NO POSTING REQUIRED **PROBLEM:** PROBLEM DIRECTION: **Ton 1: Ton 2: Ton 3: COMMENTS:** ***GENERAL COMMENTS/MAJOR RATED ITEMS*** GENERAL COMMENTS: (BOWDEJ1, 09/12/2008)--(32'-60'-60'-60'-32') CONT WF GDR SPANS [ITEM 58] DECK: 4-POOR CONDITION COMMENTS: (MADSEJ, 11/16/2017)--APPROXIMATELY 45% SATURATION, SPALLS, PATCHES, AND DELAMINATIONS THROUGHOUT THE SPAN 2 DECK. **RATING:** 11/16/2017 [ITEM 59] SUPER: 6-SATISFACTORY CONDITION COMMENTS: (MADSEJ, 11/16/2017)--MODERATE TO HEAVY PACKRUST THROUGHOUT THE GIRDER TOP FLANGE IS LIFTING THE DECK APPROXIMATELY 1/2". **RATING:** 05/18/2001 [ITEM 60] SUB: 6-SATISFACTORY CONDITION COMMENTS: (PICKEJ1, 11/04/2019)--MINOR SPALLS IN COLUMNS AND CAPS; MULTIPLE EXPOSED PILES @ ABUTMENTS **RATING:** 10/30/2013 [ITEM 61] BANK/CHANNEL: 7-MINOR DAMAGE COMMENTS: (WILSOT2, 07/24/2017)--MINOR BANK EROSION **RATING:** 11/16/2017 [ITEM 113] SCOUR: 8-STABLE FOR CALCULATED **COMMENTS: RATING:** 05/18/2001 **EVALUATION TYPE:** [ITEM 71] WATERWAY ADEQUACY: DECK/APPRCH OVERTOP SLIGT **COMMENTS: RATING:** 05/18/2001 [ITEM 72] APPRRDWY ALIGNMENT: 8-VERYGOOD **COMMENTS: RATING:** 05/18/2001 ***RAILING AND APPROACH PAVEMENT COMPONENTS AND RATINGS*** [ITEM 36A] BRIDGE RAILING RATING: DOESNT MEET CURRNT STND-0 **RATING:** 07/17/2003 **COMMENTS: DIRECTION MATERIAL CONSTRUCTION COMMENTS** REINFORCED CONCRETE **BALUSTER BOTH** REINFORCED CONCRETE **BOTH CURB** [ITEM 36B] TRANSITION RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36C] APPROACH RAILING RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:** [ITEM 36D] RAIL END TREATMENT RATING: NOT PROVIDED-0 **RATING:** 05/18/2001 **COMMENTS:**

MoDOT

Missouri Department of Transportation State Bridge Inspection Report

March 05, 2024 6:59:05AM

COUNTY: STODDARD

DISTRICT: SE

CLASS: STATBR

FED-ID: 4489

BRIDGE: F0565

<u>MATERIAL</u> REINFORCED CONCF	·		ECTION CONDITION* BOTH POOR LOCATION 2	<u>COMMENTS</u> <u>SEVERITY</u> MODERATE	<u>COMMENT</u>		
		DRAINAC	GE, EXPANSION DEVICES, BA	ANK/SLOPE, AND DECK	PROTECTIVE CO	OMPONENTS	
PROTECTIVE COMPONERIES TYPE-# MAIN SERIES-1 COMMENT:	VENTS: COMPONENT WEARING SURFACE	<u>MATERIA</u> ASPHAL			YEAR APPLIED 2014	<u>MANUFACTURE</u>	<u>OVERALL CONDITION</u> GOOD
COMMENT:	DECK PROTECTION	NOTAPPLIC	ABLE NONE				
COMMENT:	MEMBRANE	NOTAPPLICA	ABLE NONE				
NAGE COMPONENTS:	<u>COMPONENT</u> DRAINAGE	<u>MATERIA</u> REINFORCED CO			<u>COMMENTS</u>		
NSION DEVICE COMPO SUB UNIT-# SUB I PIER-5 COMMENT: COND OTH	LABEL COM OPEN EXP.	<u>PONENT</u> ANSION JOINT <u>LOCATION 1</u> DRIVING SURFACE	MATERIAL STEEL LOCATION 2	<u>-</u>	<u>GAP YEA</u> <u>COMMENT</u> GOODMJ1, 10/25/200		FACTURE OVERALL CONDITION FAIR
PACK <u>SLOPE PROTECTION C</u>		THROUGHOUT MATERIA ROCK			N <u>COMMENTS</u>		
	SLOPE PROTECTION	ROCK	BLAINNI	EI BOIH			
			DE	CCK COMPONENTS			
SPAN TYPE-# MAIN SPANS-1 CONDIT SATURA TRANSVERS	ATION	MATERIA REINFORCED CO LOCATION 1 THROUGHOUT THROUGHOUT				<u>ENT</u>	
<i>MAIN SPANS-2</i> CONDI DELAMIN		REINFORCED CO LOCATION 1 THROUGHOUT EDGE	ONCRETE CAST-IN-PA LOCATION 2	<i>LACE</i> <u>Severity</u> <u>Measu</u> Moderate Minor	<u>COMMI</u>	<u>ENT</u>	

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

MODOT

COUNTY: STODDARD DISTRICT: SE CLASS: STATBR FED-ID: 4489 BRIDGE: F0565 THROUGHOUT SATURATION HEAVY **FEW** SPALLS **BOTTOM** THROUGHOUT **MEDIUM SPALLS** FEWTRANSVERSE CRACKS THROUGHOUT MAIN SPANS-3 DECKREINFORCED CONCRETE CAST-IN-PLACE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT** THROUGHOUT MODERATE DELAMINATION **EDGE** MINOR DETERIORATION **PATCHES** RANDOM **FEW THROUGHOUT** MINOR 20 % SATURATION **SPALLS** THROUGHOUT **MEDIUM** TRANSVERSE CRACKS **FEW** THROUGHOUT MAIN SPANS-4 DECK REINFORCED CONCRETE CAST-IN-PLACE **CONDITION LOCATION 1 LOCATION 2 SEVERITY MEASUREMENT COMMENT** DELAMINATION THROUGHOUT **MODERATE EDGE MINOR** DETERIORATION **RANDOM FEW PATCHES** MINOR 20 % SATURATION **THROUGHOUT SPALLS** THROUGHOUT **MEDIUM** TRANSVERSE CRACKS **FEW** THROUGHOUT MAIN SPANS-5 DECKCAST-IN-PLACE REINFORCED CONCRETE **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT** DELAMINATION THROUGHOUT **MODERATE EDGE MINOR DETERIORATION RANDOM FEW PATCHES MINOR** 20 % **SATURATION** THROUGHOUT TRANSVERSE CRACKS THROUGHOUT **FEW** ***SUPERSTRUCTURE COMPONENTS*** **SERIES TYPE-#** SPAN TYPE **MATERIAL CONSTRUCTION LABEL COMMENTS** MAIN SERIES-1 CONTINUOUS SPAN STEELWIDE FLANGE GIRDERS WEATHERING STEEL **SPAN COMPOSITE INDICATOR LENGTH COMMENTS** MAIN SPANS-1 32 FT 11 IN NON-COMPOSITE NO **CONDITION LOCATION** 1 **SEVERITY LOCATION 2 MEASUREMENT COMMENT THROUGHOUT DECK LIFTING MINOR** .25 INCH **ENDS EAST MEDIUM** PACK RUST MAIN SPANS-2 NON-COMPOSITE 60 FT 5 IN NO **CONDITION** LOCATION 2 **SEVERITY** LOCATION 1 MEASUREMENT **COMMENT DECK LIFTING** AT INTERMEDIATE BENT **MODERATE** .5 INCH WEST **MEDIUM** PACK RUST **ENDS** MAIN SPANS-3 NON-COMPOSITE 60 FT 0 IN NO **CONDITION** LOCATION 1 LOCATION 2 **SEVERITY MEASUREMENT COMMENT DECK LIFTING THROUGHOUT MINOR** .25 INCH PACK RUST **EXTERIOR GIRDERS TOP FLANGE MEDIUM** Design_No = F0565

This report contains information that is protected from disclosure by federal law, 23 USC Section 409 and the Missouri Open Records Law (Sunshine Act), Section 610.021 RSMo. Please review MoDOT's policy and procedure manual on the Sunshine Act before releasing any of the information contained herein.

March 05, 2024 6:59:05AM

Missouri Department of Transportation State Bridge Inspection Report

COUNTY: STODDARD DISTRICT: SE CLASS: STATBR FED-ID: 4489 BRIDGE: F0565

MAIN SPANS-4 NON-COMPOSITE 60 FT 5 IN NO

LOCATION 1 SEVERITY CONDITION LOCATION 2 MEASUREMENT COMMENT DECK LIFTING THROUGHOUT MINOR .25 INCH

PACK RUST **EXTERIOR GIRDERS** TOP FLANGE **MEDIUM**

MAIN SPANS-5 NON-COMPOSITE 32 FT 11 IN NO

SEVERITY CONDITION LOCATION 1 LOCATION 2 MEASUREMENT COMMENT

THROUGHOUT DECK LIFTING MINOR .25 INCH

	SUBSTRUCTURE COMPONENTS				
TRUCTURE SKEW	<u>LENGTH</u> <u>MATERIAL</u>	<u>CONSTRUCTION</u>	<u>LABEL</u> <u>COMMENT</u>	<u>S</u>	
UTMENT-1 LA-15 DEGREE	S 41 FT 2 IN REINFORCED CONCRETE	NON-INTEGRAL			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
ASSOCIATED COMPONENT	<u>MATERIAL</u>	<u>CONSTRUCTION</u>			
BACKWALL	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
LEACHING	RANDOM		MINOR		
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
EROSION	BOTTOM	THROUGHOUT	PILE EXPOSED		
PILING	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
EXPOSED	AT BEAM CAP		1 FT		
STRAIGHT WINGS	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
FIXED BEARING	STEEL	FLAT PLATE			
<u>CONDITIO</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
RUSTING	THROUGHOUT		LIGHT		
PIER-2 LA-15 DEGREE <u>CONDITION</u> ASSOCIATED COMPONENT BEAM CAP	<u>LOCATION 1</u> <u>MATERIAL</u> REINFORCED CONCRETE	MULTIPLE COLUMN LOCATION 2 CONSTRUCTION CAST-IN-PLACE	<u>SEVERITY</u>	MEASUREMENT	
<u>CONDITION</u>		<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	THROUGHOUT		FEW		
SPALLS	DEINIEODCED CONCDETE	CAST IN DIACE			
COLUMN	REINFORCED CONCRETE I OCATION 1	CAST-IN-PLACE LOCATION 2	SEVERITY	MFASIIRFMFNT	COMMENT
COLUMN <u>CONDITIO</u> DELAMINATI SPALLS	N LOCATION 1 ON THROUGHOUT THROUGHOUT	<u>LOCATION 2</u>	<u>SEVERITY</u> SMALL SMALL	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE	<u>LOCATION 2</u> CAST IN PLACE PILE	SMALL SMALL		
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1	<u>LOCATION 2</u>	SMALL SMALL	MEASUREMENT MEASUREMENT	
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE N LOCATION 1 REINFORCED CONCRETE	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE	SMALL SMALL SEVERITY	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1	LOCATION 2 CAST IN PLACE PILE LOCATION 2	SMALL SMALL SEVERITY SEVERITY		<u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION SPALLS	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1 RANDOM	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE LOCATION 2	SMALL SMALL SEVERITY	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION SPALLS FIXED BEARING	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE N LOCATION 1 REINFORCED CONCRETE N LOCATION 1 RANDOM STEEL	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE LOCATION 2 FLAT PLATE	SMALL SMALL SEVERITY SEVERITY MINOR	MEASUREMENT MEASUREMENT	<u>COMMENT</u> <u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION SPALLS FIXED BEARING CONDITION CONDITI	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1 RANDOM STEEL LOCATION 1	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE LOCATION 2	SMALL SMALL SEVERITY SEVERITY MINOR SEVERITY	<u>MEASUREMENT</u>	<u>COMMENT</u> <u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION SPALLS FIXED BEARING CONDITION PACK RUST	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1 RANDOM STEEL LOCATION 1 THROUGHOUT	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE LOCATION 2 FLAT PLATE LOCATION 2	SMALL SMALL SEVERITY SEVERITY MINOR	MEASUREMENT MEASUREMENT	<u>COMMENT</u> <u>COMMENT</u>
COLUMN CONDITION DELAMINATI SPALLS FOOTING CONDITION WEB BEAM CONDITION SPALLS FIXED BEARING CONDITION CONDITI	N LOCATION 1 ON THROUGHOUT THROUGHOUT REINFORCED CONCRETE LOCATION 1 REINFORCED CONCRETE LOCATION 1 RANDOM STEEL N LOCATION 1 THROUGHOUT STEEL	LOCATION 2 CAST IN PLACE PILE LOCATION 2 CAST-IN-PLACE LOCATION 2 FLAT PLATE	SMALL SMALL SEVERITY SEVERITY MINOR SEVERITY	MEASUREMENT MEASUREMENT	COMMENT COMMENT COMMENT

 $Design_No = F0565$

MODOT

COUNTY: STODDARD DISTRICT: SE CLASS: STATBR FED-ID: 4489 BRIDGE: F0565

	JOINT I. STODDINKI	DISTRICT: SE	CLASS, STATER	1.50-11	7. 1107	DidDGL. 1 0303
	PACK RUST TIPPED	THROUGHOUT THROUGHOUT		HEAVY MINOR		(RACKEM, 10/13/2010)WEST
PIER-3	LA-15 DEGREES	32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN	CELEBITY	ME ACUREMENT	COMMENT
ASSOCIA	<u>CONDITION</u> TIED COMPONENT	<u>LOCATION 1</u> <u>MATERIAL</u>	<u>LOCATION 2</u> CONSTRUCTION	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
BEAM C.	AP	REINFORCED CONCRETE	CAST-IN-PLACE			
COLUM	<u>CONDITION</u>	<u>LOCATION 1</u> REINFORCED CONCRETE	<u>LOCATION 2</u> CAST-IN-PLACE	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLOWI	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EQ QED I	SCALING	WATERLINE	CACT BURN A GERNA E	LIGHT		
FOOTING	CONDITION	REINFORCED CONCRETE LOCATION 1	CAST IN PLACE PILE <u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	COMMENT
WEB BEA	AM	REINFORCED CONCRETE	CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u> RANDOM	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED B	SPALLS EARING	STEEL RANDOM	PEDESTAL(ROTATING)	MINOR		
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	RUSTING	THROUGHOUT		LIGHT		
PIER-4	LA-15 DEGREES	32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
AGGOGIA	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
ASSOCIA BEAM C	AP	<u>MATERIAL</u> REINFORCED CONCRETE	<u>CONSTRUCTION</u> CAST-IN-PLACE			
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLUMN	N <u>CONDITION</u>	REINFORCED CONCRETE LOCATION 1	CAST-IN-PLACE <i>LOCATION 2</i>	<u>SEVERITY</u>	MEASUREMENT	COMMENT
	HIGH STEEL SPALL		<u> </u>	FEW	WENSCHEMENT	COMMENT
FOOTING	SCALING	WATERLINE REINFORCED CONCRETE	CAST IN PLACE PILE	LIGHT		
FOOTING	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
WEB BEA		REINFORCED CONCRETE	CAST-IN-PLACE	~		
EXPANS	<u>CONDITION</u> ION BEARING	<u>LOCATION 1</u> STEEL	<u>LOCATION 2</u> ROCKER	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
	PACK RUST	THROUGHOUT		LIGHT		
PIER-5	<i>LA-15 DEGREES</i>	32 FT 0 IN REINFORCED CONCRETE	MULTIPLE COLUMN			
	<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
<u>ASSOCIA</u> BEAM C.	ATED COMPONENT	<u>MATERIAL</u> REINFORCED CONCRETE	<u>CONSTRUCTION</u> CAST-IN-PLACE			
BL/AIVI C	<u>CONDITION</u>	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
COLLIMA	SPALLS	THROUGHOUT	CAST IN DI ACE	FEW		
COLUM	<u>CONDITION</u>	REINFORCED CONCRETE <i>LOCATION 1</i>	CAST-IN-PLACE <u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
	PATCHES	THROUGHOUT		FEW		
FOOTING	G <u>CONDITION</u>	REINFORCED CONCRETE <u>LOCATION 1</u>	CAST IN PLACE PILE <u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	COMMENT
WEB BEA		REINFORCED CONCRETE	CAST-IN-PLACE	NET BILLI	WALLEY CHANGE IN THE	
nume e	<u>CONDITION</u>	<u>LOCATION 1</u>	LOCATION 2	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
FIXED B	EAKING	STEEL	FLAT PLATE			

MODOT

March 05, 2024 6:59:05AM

COUNTY: STODDARD	DISTRICT: SE	CLASS: STATBR	FED-II	D: 4489	BRIDGE: F0565
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
PACK RUST	THROUGHOUT		HEAVY		
EXPANSION BEARING	STEEL	ROCKER			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PACK RUST	THROUGHOUT		MEDIUM		
TIPPED	THROUGHOUT		MODERATE		(RACKEM, 10/13/2010)EAST
ABUTMENT-6 LA-15 DEGREES	41 FT 2 IN REINFORCED CONCRETE	NON-INTEGRAL			
CONDITION	LOCATION 1	LOCATION 2	<u>SEVERITY</u>	MEASUREMENT	COMMENT
ASSOCIATED COMPONENT	MATERIAL	<u>CONSTRUCTION</u>			
BACKWALL	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
LEACHING	RANDOM		MODERATE		
BEAM CAP	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	MEASUREMENT	<u>COMMENT</u>
EROSION	BOTTOM		MINOR		
SPALLS	RANDOM		MINOR		
PILING	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
STRAIGHT WINGS	REINFORCED CONCRETE	CAST-IN-PLACE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
EROSION	NW WING		MODERATE		
FIXED BEARING	STEEL	FLAT PLATE			
<u>CONDITION</u>	<u>LOCATION 1</u>	<u>LOCATION 2</u>	<u>SEVERITY</u>	<u>MEASUREMENT</u>	<u>COMMENT</u>
PACK RUST	THROUGHOUT		LIGHT		

OVER/UNDER ROUTES CLEARANCE INFORMATION

**NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

<u>CLEARANCES OVER DECK</u> <u>VERTICAL CLEARANCE TYPE**</u>

VALUE

DIRECTION

DATE

COMMENT

 $Design_No = F0565$

March 05, 2024 6:59:05AM

Missouri Department of Transportation State Bridge Inspection Report

CLASS: STATBR COUNTY: STODDARD DISTRICT: SE

FED-ID: 4489

LEFT LATERAL CLEARANCE

BRIDGE: F0565

UR-ID

CLEARANCES UNDER BRIDGE

ROUTE

MODOT

RECORD #

**NOTE: Vertical clearances for permitting purposes are taken as 2 inches less than the actual field measured clearance.

DIRECTION OF TRAFFIC RIGHT LATERAL CLEARANCE # LANES

VERTICAL CLEARANCE TYPE VALUE DIRECTION DATE COMMENT**

> ***STRUCTURE PAINT INFORMATION*** STEEL TONS: 88

CONDITION: FAIR RUST AMOUNT: 9=.03% OF SURFACE RUSTED

> **ORIGINAL PAINT CONTRACT REPAINT** DEPARTMENT REPAINT

PAINT TYPE: PAINT TYPE: MANUFACTURE: PAINT TYPE: S SYSTEM NAME: NAME: NAME: CAL SULPH/LEAD PAINT **SURFACE PREP: PAINT COLOR: PAINT COLOR: PAINT COLOR:** GRAY

PAINT YEAR: PAINT YEAR: PAINT YEAR: 2001 MILS: MILS: **MILS**: 12

REQUESTED WORK ITEMS

GENERAL WORK COMMENTS: LOCATION CATEGORY PRIORITY DATE RESPONSIBILITY **ITEM WORK ITEM COMMENT**

DISTRICT ROUTINE **NORTH** BACKFILL ABUTMENT-SLOPE SLOPE 07/18/2017 3 3 DISTRICT ROUTINE **BOTH** LEVEL APPROACH ROADWAY **APPROACH** 11/07/2017

UTILITY ATTACHMENTS

UTILITY OWNER METHOD MEASUREMENT TYPE UTILITY ATTACHMENT COMMENT **VALUE NUMBER** STREAM GAUGE STRAP DIAMETER 18 IN (BOWDEJ1, 05/02/2006)--S. SIDE

PROGRAM NOTES INFORMATION

ITEMS PROJECT# MONTH LET YEAR LET **COMMENT YEAR** 9S3725 2025 REPLACE BRIDGE 2025

Design No = F0565



March 05, 2024 6:59:05AM

COUNTY: STODDARD DISTRICT: SE CLASS: STATBR FED-ID: 4489 BRIDGE: F0565

COUNTY: STOD	DAKD DISTRICT: SE	CLASS: STATER	FED-ID: 4409	DKIDGE: FUSUS				
COMPU	UTER GENERATED RATINGS AND I	DEFICIENCY ITEMS		***ADVANCED SIGN INFORMATION***				
NOTE: The items listed in this section are up	odated whenever computer edits are ran on a struct	ure after the inspection updates have been entered in to TMS.	SIGN#	SIGN TYPE	PROBLEM	PROBLEM DIRECTION		
Rated Item	Rating	Rating Date	1	DELINEATOR	MISSING SIGN	ВОТН		
[Item 67] Structure Evaluation Rating:	5-BETTER THAN MINIMUM	4/17/2002						
[Item 68] Deck Geometry Rating:	5-BETTER THAN MINIMUM	1/20/2006						
[Item 69] Underclearance:	N-NOT APPLICABLE	5/18/2001						
Sufficiency Rating:	63.8%	3/8/2022						
Deficiency:	STRUCTURAL	11/29/2017						
Funding Eligibility:	PARTIAL			***OUTFALL INSP	PECTION INFORMATION	1***		
Estimated New Structure Length:	279 FT.				ann aman			
Estimated Structure Cost:	\$1,100,186		# OUTFALLS:	IN	SPECTOR:			
Estimated Total Project Cost:	\$1,650,279		STATUS:		DATE:			
Year of Cost Estimate:	2024		NOTES:					
generalized to use NBI items to come up with	stimates are computer generated using algorithims a new structure length and width to calculate a new may vary significantly from these numbers once s	v area which is taken times a representative cost per						

March 05, 2024 6:59:05AM

DISTRICT: SE

FED-ID: 4489

BRIDGE: F0565





Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

COUNTY: STODDARD F0565 R REVIEW STATUS: APPROVED T **BRIDGE:** NBI STATUS: 1/17/2024 2023 ROUTE CARRIED 'ON' STRUCT **RECORD TYPE: RUN DATE: SUBMITTAL YEAR:** GENERAL STRUCTURE INFORMATION ROUTE DESIGNATION INFORMATION ROUTE CARRIED 'ON' STRUCT State MISSOURI 5A Record Type MO District 5B SE Route Signing Prefix MAINLINE STODDARD County 5C Designated Level of Service 00114 4489 8 Federal ID No. 5D Route Number 1949 NOT APPLICABLE 27 5E Year Built Directional Suffix 106 MO 114 E 0 7 Year Reconstructed Facility Carried NO HIGHWAY Type of Service On 12 Base Hwv. Network STATE HIGHWAY AGENCY Structure Maintenance 13A LRS Inventory Route No. STATE HIGHWAY AGENCY 22 Structure Owner 13B Subroute No. 33 NO MEDIAN Toll Status ON FREE ROAD Br. Median Code 20 07-RURAL MAJOR COLLECTOR 37 Historical Significance NOT ELIGIBLE FOR NR OF HP 26 Functional Classification NONE EXISTS 101 28A Parallel Struc Desg Lanes on Structure NOT TEMPORARY Temporary Structure 103 RTE NOT A DEFENSE HWY 100 STRAHNET Designation NBIS Bridge Length YES NOT ON NHS National Highway System 104 NOT APPLICABLE 105 Federal Lands Highway 110 Designated Nat. Network STRUCTURE LOCATION INFORMATION STRUCTURE TRAFFIC INFORMATION 804 4 RICHLAND Place 29 AADT 61616 2022 Code 30 AADT Year S 2 T 25 N R 12 E 2-WAY TRAFFIC Location 102 Direction of Traffic 11 Milepoint 14.03 miles 14% 109 AADT Truck Percent 16 Latitude 36 D 50 M 4 S 1126 114 Future AADT 17 Longitude 89 D 43 M 49 S 2042 115 Future AADT Year UNDERRECORD INFORMATION STRUCTURE GEOMETRIC INFORMATION LIT RVR DRAIN DTCH 10 99 Ft. 99 In. Features Intersected Inventory Rte. Vert. Clear 42B WATERWAY 19 8.13 miles Type of Service Under By pass Detour Length 00 28B Lanes Under Structure 32 Approach Roadway Width 25 Ft. 11 In. N/A 15.00 Degrees 54A Vert. Clearance Ref. 34 Skew 54B Vert. Clearance 0 Ft. 0 In. 35 Struct. Flared Rt. Lat Clear Ref. N/A Total Horiz. Clear 25 Ft. 11 In. 55A 47 55B Rt. Lat Clearance 0 Ft. 0 In. 48 Maximum Span Length 60 Ft. 4 In. 247 Ft. 1 In. Left Lat Clearance 0 Ft. 0 In. 49 Structure Length PERMIT NOT REQ Navigation Control 50A 0 Ft. 0 In. Left Curb/Sidewalk Width Nav Vertical Clear 0 Ft. 0 In. 39 50B Right Curb/Sidewalk Width 0 Ft. 0 In. 0 Ft. 0 In. Curb to Curb Br. Width 25 Ft. 11 In. 40 Nav Horizontal Clear 51 33 Ft. 2 In. Nav. Pier Protection 52 Deck Width (Out-Out) 111 99 Ft. 99 In. Nav. Cl. Vert. Clear 53 Vert.Clearance Over Deck



Missouri Department of Transportation Bridge Inventory and Inspection System Structural Inventory & Appraisal Sheet

March 5, 2024 7:00:28am

COUNTY: STODDARD BRIDGE: F0565 R REVIEW STATUS: APPROVED NBI STATUS: T
RECORD TYPE: ROUTE CARRIED 'ON' STRUCT RUN DATE: 1/17/2024 SUBMITTAL YEAR: 2023

	ROWDAIE.				
LOAD RATING AND POSTING INFORMATION	MATERIAL/CONSTRUCTION INFORMATION				
31 Design Load	43A Main Struc. Mat type STEEL CONTINUOUS 43B Main struc Constr. Type STRINGER/MULTIBEAM - GRD 45				
Sufficiency Rating 63.8 Percent Deficiency Rating STRUCTURAL	108C Deck Protect Mat/Constr. 0 NONE				
Funding Eligibility PARTIAL 75A Proposed Work REHAB-GENERAL DETERIORAT 75B Work Done By Contract 76 New Struc Length 278 Ft. 10 In. 94 Struc Improve Cost \$ 1,100,000 95 Roadway Improve Cost \$ 110,000	CONDITION RATING INFORMATION 58 Deck Cond. Rating 4 59 Superstructure Cond. Rating 6 60 Substructure Cond. Rating 6 61 Channel /Channel Protection Cond. Rating 7 62 Culvert Cond. Rating N				
96 Total Project Cost \$ 1,650,000					
97 Year of Cost Estimates 2024	INSPECTION INFORMATION				
APPRAISAL RATING INFORMATION 36A Br. Rail App. Rating DOES NOT MEET ACCEPT STND 36B Transition Rail App. Rating DOES NOT MEET ACCEPT STND 36C Approach Rail App. Rating DOES NOT MEET ACCEPT STND 36D Rail End Treat. App. Rating DOES NOT MEET ACCEPT STND 67 Struc Eval App. Rating 5 68 Deck Geometry App. Rating 5 69 Underclearance App. Rating N 71 Waterway Adeq. App. Rating 6 72 Approach Road App. Rating 8	90 Gen. Insp Date 10 / 23 91 Gen. Insp. Frequency 24 Months 92A Frac. Critical Inspection N Months 93A Frac. Critical Insp. Date 92B Underwater Inspection N Months 93B Underwater Insp. Date 92C Special Inspection N Months 93C Special Inspection Date BORDER BRIDGE INFORMATION 98 Neighboring State Code 98B Neighboring State % Respon				
113 Scour Assess App. Rating 8	99 Neighboring State Struc. No.				
APPROVED POSTING INFORMATION	FIELD POSTING INFORMATION				
Approved Posting Category S-1 Ton1 Ton2 Ton3	Field Posting Category S-1 Ton1 Ton2 Ton3				
Tonnage Values for Posting Sign General Text for Posting Sign NO POSTING REQUIRED	Tonnage Values for Posting Sign General Text for Posting Sign NO POSTING REQUIRED				