Purpose and Need of Project: Improve Safety and Traffic Flow in Buffalo & Warsaw



Roundabout Conflict Points



BEFORE & AFTER

Crash Statistics Before & After Construction of a Roundabout

| MO 96 and MO 43 North of Joplin | | | |
|-----------------------------------|-----------------------|-------|--------------------|
| 5 Years Before & 5 Years After | | | CRASHES |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 2 | 0 | 100% |
| Serious Injury | 3 | 0 | 100% |
| Minor Injury | 6 | 1 | 83% |
| | | | |
| US 60 and MO 43 Seneca | | | |
| | fore & 5 Years After | | |
| | | | CRASHES |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 0 | 0 | |
| Serious Injury | 3 | 0 | 100% |
| Minor Injury | 12 | 3 | 75% |
| | | | |
| US 160 and Jackson Street Willard | | | |
| 4 Years B | efore & 2 Years After | | CRASHES |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 0 | 0 | |
| Serious Injury | 1 | 0 | 100% |
| Minor Injury | 5 | 1 | 80% |
| | 5 | | |