

Photo 1: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Looking south



Photo 2: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB 1 expansion joint




Photo 3: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Looking south



Photo 4: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Right barrier curb, missing slide plate
Typical to all corners.



Photo 5: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB 5 expansion joint



Photo 6: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Drainage basin at SW corner



Photo 7: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
SW wing wall, previous
undermining repair



Photo 8: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Left barrier curb at EB 5 expansion joint





Photo 9: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Left wing wall at EB 1



Photo 10: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Left side of bridge deck from EB1



Photo 11: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
EB 1, left wingwall at
expansion device



Photo 12: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB 1, G1, typical surface rust



Photo 13: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
EB1, G1 – Typical
bearing condition




Photo 14: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB1, G1, Top flange



Photo 15: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB1, G1, Bearing device




Photo 16: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB1, vertical crack between G1&2







Photo 21: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Span (1-2)



Photo 22: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
IB 2 Column 2



Photo 23: 12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
IB 2 Column 1



Photo 24: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
Typical spacing between
Columns and Guardrail

Photo 25:
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
South slope
protection at EB 5



Photo 26:
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
IB 3 Column 1
2'x3' delam.





Photo 27: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
Typical deck joint, Rust
on diaphragm



Photo 28:
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
Typical deck joint,
South slope

Photo 29: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
Left barrier curb, horizontal cracking



Photo 30:
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
North slope
protection



Photo 31: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
EB5, G5



Photo 32: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB5, G4 bearing device – Typical
bearing condition





Photo: 33
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
EB5, right wingwall



Photo 34: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB5, G4 bearing device



Photo 35: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB5, G3 bearing device. Cracked beam seat



Photo 36: 12/23/2019
A2942: Rte. 21 NB over Old Rte. 21
EB5, G3 bearing device. Cracked beam seat




Photo 37:
12/23/2019
A2942: Rte. 21 NB
over Old Rte. 21
EB5, Left wingwall



Photo 38: 12/23/2019
A2942: Rte. 21 NB over
Old Rte. 21
Erosion at end of NW
wingwall