





Photo 5:
12/23/2019
A5529: Rte. 21 NB
over Rte. M
Typical slab edge
(Right outside face)



Photo 6: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Damaged Type A curb at end of
right barrier curb at north
approach. Approach slab
undermined.



Photo 7: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Typical overlay condition



Photo 8: 12/23/2019
A5529: Rte. 21 NB over Rte. M
End of slab joint at EB5



Photo 9: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Right barrier curb at south approach



Photo 10: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Looking north at EB5



Photo 11: 12/23/2019
A5529: Rte. 21 NB over Rte. M
End of slab joint at EB5



Photo 12: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Drainage inlet near EB1



Photo 13: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Left outside face, at EB1



Photo 14: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Cracked slope protection at
left wingwall at EB1



Photo 15: 12/23/2019
A5529: Rte. 21 NB over Rte. M
EB1, between G1&2



Photo 16: 12/23/2019
A5529: Rte. 21 NB over Rte. M
EB1, between G1&2

Photo 17: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Rust staining on deck panel



Photo 18: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Looking at IB2, between G1&2

Photo 19: Not Used



Photo 20: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Span 1, saturation at deck panels



Photo 25: Not Used



Photo 26: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Span 4




Photo 27: 12/23/2019
A5529: Rte. 21 NB over Rte. M
Right outside face at EB5



Photo 28: 12/23/2019
A5529: Rte. 21 NB over Rte. M
SE corner of slope protection

Photo 29: 12/23/2019
A5529: Rte. 21 NB over Rte. M
EB5, left outside face

