



Photo 1: 11/19/19
A2945: MO 21 N over Heads
Creek Rd.
North end of slab joint



Photo 2: 11/19/19
A2945: MO 21 N over Heads
Creek Rd.
South end of slab joint



Photo 3: 11/19/19
A2945: MO 21 N over Heads Creek Rd.
Pot-hole at south approach slab.



Photo 4: 11/19/19
A2945: MO 21 N over Heads Creek Rd.
Patch at south end of bridge deck.

Photo 5: 11/19/19

**A2945: MO 21 N over Heads Creek Rd.
Debris in drain basins.**



Photo 6: 11/19/19

**A2945: MO 21 N over Heads Creek Rd.
Left barrier curb, span 2, cracking and delamination.**



Photo 7: 11/19/19

**A2945: MO 21 N over Heads Creek Rd.
Overlay pot hole and typical overlay
deterioration. Consistent throughout.**



Photo 8: 11/19/19

A2945: MO 21 N over Heads Creek Rd.






Photo 9: 11/19/19
A2945: MO 21 N over
Heads Creek Rd.
EB 1, vertical crack
between GRD 1&2.




Photo 10: 11/19/19
A2945: MO 21 N over
Heads Creek Rd:
EB 1, between GRD
2&3, 3' x 4' delam.




Photo 11: 11/19/19
A2945: MO 21 N over
Heads Creek Rd.
EB 1, vertical crack
between GRD 2&3.




Photo 12: 11/19/19
A2945: MO 21 N over
Heads Creek Rd.
EB 1, vertical crack
between GRD 3&4.

Photo 13: 11/19/19
A2945: MO 21 N over
Heads Creek Rd.
EB 1, vertical crack
between GRD 3&4.




Photo 14: 11/19/19
A2945: MO 21 N over
Heads Creek Rd.
EB 5, vertical crack
between GRD 2&3.




Photo 15: 11/19/19
A2945: MO 21 N over Heads Creek Rd.
South side of Heads Creek Rd, guardrail post wash-out.



Photo 16: 11/19/19
A2945: MO 21 N over Heads Creek Rd.








Photo 21:
11/19/19
A2945: MO 21 N
over Heads
Creek Rd.
South slopewall,
B4 column.