



Photo 1: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Gen. view looking South



Photo 2: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Joint at end of north approach
slab.



Photo 3: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Crack in overlay at end of slab
joint at EB1.



Photo 4: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Looking south

Photo 5: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Typical condition of overlay



Photo 6: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Crack in overlay at end of slab
joint at EBS.



Photo 7: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Joint at end of south approach
slab.



Photo 8: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Looking north, left barrier curb



Photo 9: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Looking north



Photo 10: 12/23/2019
A5530: Rte. 21 SB over Rte. M
EB5, minor erosion at end of left
barrier curb



Photo 11: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Drainage basin between A5529 and
A5530



Photo 12: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Typical condition at EB1





Photo 13: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Span (2-3)




Photo 14: 12/23/2019
A5530: Rte. 21 SB over Rte. M
IB2, Column 3, delam.




Photo 15:
12/23/2019
A5530: Rte. 21 SB
over Rte. M



Photo 16: 12/23/2019
A5530: Rte. 21 SB over Rte. M
EB5, west corner of slope protection



Photo 17: 12/23/2019
A5530: Rte. 21 SB over Rte. M
North slope protection



Photo 18: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Span (1-2)




Photo 19: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Right outside face at EB1




Photo 20: 12/23/2019
A5530: Rte. 21 SB over Rte. M
Evidence of erosion at end of wingwall,
southwest corner at EB5.