

Photo 1: 11/19/19
A2944: MO 21 over Heads
Creek Rd.
General view



Photo 2: 11/19/19
A2944: MO 21 over Heads Creek Rd.
Settling approach pavement at EB1



Photo 3: 11/19/19
A2944: MO 21 over Heads Creek Rd.
End of slab joint at EB1



Photo 4: 11/19/19
A2944: MO 21 over
Heads Creek Rd.
End of slab joint at EB5



Photo 5: 11/19/19
A2944: MO 21 over
Heads Creek Rd.
Crack in right barrier
curb




Photo 6: 11/19/19
A2944: MO 21 over
Heads Creek Rd.
12' delam on west
Crack in right barrier



Photo 7: 11/19/19
A2944: MO 21 over Heads Creek Rd.
General overlay condition



Photo 8: 11/19/19
A2944: MO 21 over Heads Creek Rd.
General view






Photo 13: 11/19/19
A2944: MO 21 over Heads Creek Rd.
Crack on northwest side of EB 1.




Photo 14: 11/19/19
A2944: MO 21 over Heads Creek Rd.
Crack on northwest side of EB 1.
(same crack from previous photo cont.)




Photo 15: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 1. Typical epoxy injected crack in
diaphragm.




Photo 16: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 1. Typical epoxy injected crack at
beam end.

Photo 17: 11/19/19
A2944: MO 21 over Heads Creek Rd.
IB4, GRD 2. Typical girders repair near IB2.



Photo 18:
11/19/19
A2944: MO 21 over
Heads Creek Rd.
EB 5, between GRD
3&4. 3' x 4' delam.




Photo 19: 11/19/19
A2944: MO 21 over Heads Creek Rd.
IB2. Typical slopewall failure at columns.



Photo 20: 11/19/19
A2944: MO 21 over Heads Creek Rd.
IB2. Typical slopewall failure at columns.
Crack sealant is failed (typ.)






Photo 21: 11/19/19
A2944: MO 21 over Heads Creek Rd.
IB4. South face of diaphragm. Typical
efflorescence at construction joints.




Photo 22: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 5, between GRD
4&5. Horizontal
cracking.




Photo 23: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 5, between GRD 4&5. Horizontal cracking.




Photo 24: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 5. Crack on outside face of west edge,
continues to inside face.



Photo 25: 11/19/19
A2944: MO 21 over Heads Creek Rd.
Looking east. Typical pop-outs on girders.




Photo 26: 11/19/19
A2944: MO 21 over Heads Creek Rd.
EB 5. Crack on inside face of west edge,
continues to outside face.



Photo 27: 11/19/19
A2944: MO 21 over Heads Creek Rd.

