

From: [Debra M. Butchart](#)
To: [BR](#)
Subject: Bridge Advertisement (DSI 25-019) BSP 712 for Heat Straightening
Date: Wednesday, June 11, 2025 8:46:46 AM

The [Bridge Special Provisions](#) have been updated as described below:

Implementation Statement: effective immediately for projects not yet submitted to Design

(The Implementation Statement is a recommendation by the Development Section. The SPM is responsible for the level of implementation for any particular job.)

Revision Date	Items Revised	Description of Change
June 2025	EPG: NA	Heat Straightening: Section 4.1.1 has been revised to clarify that the steel to be straightened should be inspected for cracks both before and after heat straightening is performed. Also, if cracking is found, the ends of the cracks should be located by one of the detection methods other than visual inspection. The updated document can be found in the Bridge Special Provisions library on Review Section's Sharepoint page, as well as on the website https://www.modot.org/bridge-special-provisions
	Bridge Standard Drawings: NA	
	MicroStation Cells: NA	
	Std. Specifications: NA	
	Standard Plans: NA	
	Bridge Special Provisions: 712-BSP-17	

Follow links above for more information.

Debra (Debbie) Butchart

(formerly Debra Beckwith)

Structural Specialist

Development Section

Bridge Division

MoDOT- 105 West Capitol Ave

573-522-8718