

DECK REPAIR WITH
VOID TUBE REPLACEMENT



SUPERSTRUCTURE REPAIR (UNFORMED)

① 2 1/4" (min.) Low Slump Concrete Wearing Surface ② Existing 2" Low Slump Concrete Wearing Surface



REPAIRING CONCRETE DECK (HALF-SOLING)

Detailed
Checked

Note: This drawing is not to scale. Follow dimensions.

Sheet No. of

"THIS MEDIA SHOULD NOT BE CONSIDERED A CERTIFIED DOCUMENT."

DATE PREPARED 07/28/2008

ROUTE * | STATE MO

DISTRICT BR | SHEET NO. *

COUNTY *

JOB NO. *

CONTRACT ID.

PROJECT NO.

BRIDGE NO. VSR01

DESCRIPTION | DATE

MISSOURI HIGHWAYS AND TRANSPORTION COMMISSION
105 WEST CAPITOL
JEFFERSON CITY, MO 65102
1-888-ASK-MODOT (1-888-275-6636)

IF A SEAL IS PRESENT ON THIS SHEET IT HAS BEEN ELECTRONICALLY SEALED AND DATED.

REV.