



**CONCRETE MASONRY REPAIR
FIELD SECTION 704 TABLE 1
QUALIFIED RAPID SET CONCRETE PATCHING MATERIAL
(HORIZONTAL)
(0704CMRP)**

<u>Brand Name</u>	<u>Manufacturer</u>	<u>Date of Provisional Withdrawal</u>
DOT Patch HD (6/05)	Symons Corporation	
EcoFix*** (11/16)	United States Gypsum Co.	
Fastrac 246 Rapid Setting Concrete (3/13)	Western Material & Design	
Fastrac 300*** Rapid Setting Cement (3/13)	Western Material & Design	
HD-50 (6/05)	Dayton Superior Specialty Chemical	
MasterEmaco T 1060	BASF Corporation Construction Systems	
Mono-Patch**	Bindan Corporation	
Quikrete Com- mercial Grade Fast Set DOT Mix (86/06)	The Quikrete Companies	
Pave Patch 3000	Dayton Superior Corp., KS	
Phoscrete HC* (4/16)	Phoscrete Corp.	April 1, 2019
Rapid Set Concrete Mix (10/07)	CTS Cement Manufacturing Corp.	
Rapid Set DOT Concrete Mix (12/16)	CTS Cement Manufacturing Corp.	



**MASONRY REPAIR
FIELD SECTION 704 TABLE 1
QUALIFIED RAPID SET CONCRETE PATCHING MATERIAL
(HORIZONTAL)
(0704CMRP)**

<u>Brand Name</u>	<u>Manufacturer</u>	<u>Date of Provisional Withdrawal</u>
Rapid Set DOT*** Repair Mix (12/16)	CTS Cement Manufacturing Corp.	
Repcon 928 (6/10)	SpecChem	
Road Patch (3/05)	Degussa Building Systems	
Sika Set Roadway Patch	Sika Chemical Corp.	
SikaTop 122 Plus	Sika Chemical Corp.	
Speedcrete 2028	Tamms Ind.	

Note: The time to obtain minimum strength may vary depending upon actual field conditions.

* These products have provisional approval pending NTPEP testing result submission after the NTPEP testing session for fast setting concrete mortars is completed. Their use will be allowed until the provisional approval is rescinded.

** This product may not be used with extending aggregate.

*** This product must be used with aggregate meeting the requirements of Section 1005 of the Missouri Standard Specifications for Highway Construction.