

St. Charles County Safety Improvements

<i>Location 20 - U.S. Route 61 (NB & SB) from I-70 to Lincoln County Line</i>		<i>Location 28 & 29 - Veterans Memorial Pkwy & Zumbehl Rd</i>	
Intersection/Segment	Countermeasure	Intersection/Segment	Countermeasure
I-70 to Lincoln Co Line	Guardcable	Zumbehl Road	High Friction Surface Treatment
All Segments	Inlaid Pavement Markers	Country Club Rd, Dierbergs Entrance & Zumbehl Rd.	Retroreflective Signal Backplates
<i>Location 21 - MO 370E from Premier Parkway to Truman Road Entrance Ramp</i>		Various Locations	Upgrade Guardrail/Crashworthy End Terminals
Intersection/Segment	Countermeasure	<i>Location 30 - I-64E from MO 94 to Research Park Bridge</i>	
1.855 Log Miles	Inlaid Pavement Markers	Intersection/Segment	Countermeasure
1.855 Log Miles	Wet Reflective Pavement Markings	1 Curve	High Friction Surface Treatment
<i>Location 22 - MO 370W from Truman Road Exit Ramp to I-70</i>		0.750 Log Miles	Inlaid Pavement Markers
Intersection/Segment	Countermeasure	0.750 Log Miles	Wet Reflective Pavement Markings
3.000 Log Miles	Inlaid Pavement Markers	<i>Location 31 & 32 - Route 94 (EB&WB) from Sidentop Rd to Ramp MO 364E to MO 94</i>	
3.000 Log Miles	Wet Reflective Pavement Markings	Intersection/Segment	Countermeasure
<i>Location 23 & 24 - Route H</i>		3.00 Log Miles	Guardcable
Intersection/Segment	Countermeasure	3.00 Log Miles	Inlaid Pavement Markers
5 Curves	High Friction Surface Treatment	South Breeze Rd	LED Stop Signs
7.706 Log Miles	Centerline and Edgeline Rumbles	Sidentop Rd, Cedar Glen Dr, Weldon Springs Rd, Wolfrum Rd & Westwood Dr	Retroreflective Signal Backplates
8 Curves	Fluorescent Curve Signs	Weldon Springs Rd & Wolfrum Dr	Dynamic Signal Warning Flashers
7.706 Log Miles	Install 2ft Turf Shoulder	Weldon Springs Rd & Wolfrum Dr	Improve Channelized Right Turn Angle
<i>Location 25 - I-70E from Ramp to Wentzville Pkwy to Route Z Entrance Ramp</i>		Various Locations	Upgrade Guardrail/Crashworthy End Terminals
Intersection/Segment	Countermeasure	<i>Location 33 - MO 364W from Ramp MO 364W to MO 94E to Heritage Crossing</i>	
1 Curve	High Friction Surface Treatment	Intersection/Segment	Countermeasure
0.803 Log Miles	Inlaid Pavement Markers	0.973 Log Miles	Diamond Grinding
0.803 Log Miles	Wet Reflective Pavement Markings	0.973 Log Miles	Wet Reflective Pavement Markings
Various Locations	Upgrade Guardrail/Crashworthy End Terminals	0.973 Log Miles	Inlaid Pavement Markers
<i>Location 26 - I-70W from U.S. Route 61 to Wentzville Pkwy</i>		Various Locations	Upgrade Guardrail/Crashworthy End Terminals
Intersection/Segment	Countermeasure	<i>Location 34 - MO 364/94 EB</i>	
0.379 Log Miles	Inlaid Pavement Markers	Intersection/Segment	Countermeasure
0.379 Log Miles	Wet Reflective Pavement Markings	0.904 Log Miles - MO 364	Diamond Grinding
<i>Location 27 - I-70E from Lake St. Louis Blvd to Bryan Road</i>		0.904 Log Miles - MO 364	Wet Reflective Pavement Markings
Intersection/Segment	Countermeasure	0.904 Log Miles - MO 364	Inlaid Pavement Markers
2.000 Log Miles	Inlaid Pavement Markers		
2.000 Log Miles	Wet Reflective Pavement Markings		