RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Carroll	D	2T0024	2005	Upgrade active warning devices at Rte. D/Pine Street (DOT# 005 322F) BNSF in Norborne. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Carroll	65	2T0026	2005	Upgrade active warning devices at Bus. 65/Main Street (DOT# 005 308K) BNSF in Carrollton. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$56	No
Carroll	Var	2T0023	2005	Upgrade active warning devices at Oak Street (DOT# 005 323M) BNSF in Norborne. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$16	No
Carroll	Var	2T0025	2005	Upgrade active warning devices at County Road 613 (DOT# 005 320S) BNSF near Norborne. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Carroll	Var	2T0027	2005	Close highway/rail crossing at County Road 276 (DOT# 005 305P) BNSF near Carrollton and build a roadway from County Road 276 to Highway 24. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$144	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Carroll	Var	2T0028	2005	Upgrade the active warning devices at County Road 303 (DOT# 005 304H) BNSF near Carrollton. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Carroll	Var	2T0029	2005	Close highway/rail crossing located at County Road 270 (DOT #005 303B) BNSF near Carrollton. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$5	No
Linn	Var	2T0030	2006	Close the highway/rail crossing located at East Fifth Street (DOT #005 129U) BNSF in Bucklin. Project No. RRP-000S(195). Reason(s): The project was added due to additional funding made available.	\$5	No
Randolph	3	2T0022	2005	Upgrade active warning devices at Missouri Rte. 3/McLean Street (DOT# 483 728F) NS in Clifton Hill. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$42	No
Randolph	Р	2T0015	2005	Upgrade active warning devices at Rte. P/Main Street (DOT# 483 678E) NS in Clark. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$102	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Randolph	Var	2T0016	2005	Upgrade active warning devices at Business 24/Coates Street (DOT# 483 697J) NS in Moberly. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$184	No
Randolph	Var	2T0017	2005	Close highway/rail crossing located at County Road 1220/Wayside (DOT# 483 704S) NS near Moberly. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$31	No
Randolph	Var	2T0018	2005	Upgrade active warning devices at Huntsville Avenue (DOT# 483 714X) NS in Huntsville. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$27	No
Randolph	Var	2T0019	2005	Upgrade active warning devices at Taylor Street (DOT# 483 718A) NS in Huntsville. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$42	No
Randolph	Var	2T0020	2005	Upgrade active warning devices at Depot Street (DOT# 483-719G) NS in Huntsville. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$149	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Randolph	Var	2T0021	2005	Install active warning devices at County Road 1120 (DOT# 483 724D) NS near Huntsville. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$102	No
Audrain	Var	3T0012	2005	Close highway/rail crossing at County Road 724 (DOT # 483 627U) Norfolk Southern Railway Co. and build a connecting highway from County Road 724 to County Road 725 near Benton City. Project No. RRP-000S(174). Reason(s): The project was added due to additional funding made available.	\$56	No
Cass	Р	4T0044	2005	Upgrade active warning devices at Rte. P (DOT# 442 998S) MNA near Pleasant Hill. Project No. RRP-000S(201). Reason(s): The project was added due to additional funding made available.	\$153	No
Cass	Var	4T0028	2005	Install active warning devices at 259th Street (DOT# 329 837P) KCS near West Line. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$180	No
Cass	Var	4T0029	2005	Install active warning devices at 307 Street (DOT #443 025U) MNA near Archie. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$175	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Cass	Var	4T0045	2005	Install active warning devices at Orr Road (DOT # 443 002M) MNA near Pleasant Hill. Project No. RRP-000S(201). Reason(s): The project was added due to additional funding made available.	\$153	No
Cass	Var	4T0049	2005	Upgrade active warning devices at 187th Street (DOT# 329 821T) KCS near Belton. Project No. RRP-000S(200). Reason(s): The project was added due to additional funding made available.	\$60	No
Cass	Var	4T0050	2005	Upgrade active warning devices at Lone Pine Road (DOT # 329 836H) KCS in Cleveland. Project No. RRP-000S(200). Reason(s): The project was added due to additional funding made available.	\$144	No
Cass	Var	4T0051	2005	Install active warning devices at 299th Street (DOT# 329 845G) KCS near West Line. Project No. RRP-000S(200). Reason(s): The project was added due to additional funding made available.	\$144	No
Cass	Var	4T0052	2005	Install active warning devices at County Road 315 (DOT# 329 850D) KCS near Drexel. Project No. RRP-000S(200). Reason(s): The project was added due to additional funding made available.	\$144	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Cass	Var	4T0053	2005	Install active warning devices at Industrial Drive (DOT# 329 860J) KCS near Drexel. Project No. RRP-000S(200). Reason(s): The project was added due to additional funding made available.	\$144	No
Clay	Var	4T0010	2004	Upgrading active warning devices at Italian Way (DOT # 375 400C) Iowa Chicago & Eastern Railroad Co. in Excelsior Springs. Project No. RRP-000S(185). Reason(s): The project was added due to additional funding made available.	\$184	No
Clay	Var	4T0011	2004	Upgrading active warning devices at Salem Road (DOT # 375 442R) Iowa Chicago & Eastern Railroad Co. near Excelsior Springs. Project No. RRP-000S(185). Reason(s): The project was added due to additional funding made available.	\$178	No
Clay	Var	4T0012	2004	Install active warning devices at 174th Street (DOT # 375 445L) near Lawson. Project No. RRP-000S(179). Reason(s): The project was added due to additional funding made available.	\$160	No
Jackson	Var	4T0019	2005	Upgrading active warning devices at Genessee Street (DOT # 663 541H / 411 877J) Terminal Railroad Association of St. Louis in Kansas City. Project No. RRP-000S(173). Reason(s): The project was added due to additional funding made available.	\$200	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Jackson	Var	4T0030	2005	Close highway/rail crossing located at Courtney Road (DOT# 005 378A) BNSF near Sugar Creek. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$24	No
Jackson	Var	4T0031	2005	Upgrade active warning devices at Courtney Atherton (DOT# 005 373R) BNSF near Atherton. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$160	No
Jackson	Var	4T0032	2005	Upgrade active warning devices at Mabel Street (DOT# 005 372J) BNSF in Atherton. Project RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$160	No
Jackson	Var	4T0033	2005	Upgrade active warning devices at Atherton-Sibley (DOT# 005 368U) BNSF near Sibley. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Ray	J	4T0040	2005	Upgrade active warning devices at Rte. J/First Street (DOT# 005 334A) BNSF in Hardin. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Ray	Z	4T0035	2005	Upgrade active warning devices at Rte. Z (DOT # 005 358N) BNSF near Floyd. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Ray	Var	4T0024	2004	Upgrading active warning devices at Moss Street (DOT # 375 446T) lowa Chicago & Eastern Railroad Co. in Lawson. Project No. RRP-000S(185). Reason(s): The project was added due to additional funding made available.	\$203	No
Ray	Var	4T0034	2005	Upgrade active warning devices at Sibley Road (DOT # 005 359V) BNSF near Orrick. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Ray	Var	4T0036	2005	Close highway/rail crossing located at Pig Lane (DOT# 005 357G) BNSF near Floyd. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$5	No
Ray	Var	4T0037	2005	Upgrade active warning devices at County Road 336 (DOT# 005 354L) BNSF near Camden. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$160	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Ray	Var	4T0038	2005	Upgrade active warning devices at County Road 307 (DOT# 005 340D) BNSF near Henrietta. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$4	No
Ray	Var	4T0039	2005	Install active warning devices at 92nd Street (DOT# 005 337V) BNSF near Hardin. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$160	No
Ray	Var	4T0041	2005	Close highway/rail crossing located at 2nd Street (DOT# 005 332L) BNSF in Hardin. Project No. RRP-000S(198). Reason(s): The project was added due to additional funding made available.	\$5	No
Boone	Var	5T0008	2005	Install active warning devices at Rogers Street (DOT #480 808N) CT in Columbia. Project No. RRP-000S(191). Reason(s): The project was added due to additional funding made available.	\$130	No
Boone	Var	5T0032	2005	Install active warning devices at Dinwiddie School Road (DOT# 483 669F) NS near Centralia. Project No. RRP-000S(197). Reason(s): The project was added due to additional funding made available.	\$102	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Cole	Т	5T0014	2005	Upgrade active warning devices at Rte. T (DOT# 442 253D) UP near Elston. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$8	No
Cole	Z	5T0017	2005	Upgrade active warning devices at Rte. Z (DOT# 442 250H) UP near Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$180	No
Cole	NN	5T0019	2005	Upgrade active warning devices at Rte. NN/Monroe Street (DOT# 442 247A) UP in Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Cole	179	5T0013	2005	Upgrade active warning devices at Missouri Rte. 179 (DOT# 442 259U) UP near Jefferson City. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$8	No
Cole	Var	5T0015	2005	Install active warning devices at Old Stage Road (DOT# 442 252W) UP near Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$144	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Cole	Var	5T0016	2005	Install active warning devices at Nilges Road (DOT# 442 251P) UP near Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$144	No
Cole	Var	5T0018	2005	Close highway/rail crossing located at Oak Street (DOT# 442 249N) UP in Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$30	No
Cole	Var	5T0020	2005	Upgrade active warning devices at Marion Street (DOT# 442 246T) UP in Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Moniteau	В	5T0031	2005	Upgrade active warning devices at Rte. B/Moreau Avenue (DOT# 442 188A) UP in Tipton. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Moniteau	Н	5T0028	2005	Upgrade active warning devices at Rte. H (DOT# 442 200E) UP in Clarksburg. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Moniteau	PP	5T0023	2005	Upgrade active warning devices at Rte. PP (DOT# 442 240C) UP near McGirk. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$48	No
Moniteau	Var	5T0012	2004	Install active warning devices at Whippoorwill Road (DOT # 442 236M) UP near McGirk. Project No. RRP-000S(193). Reason(s): The project was added due to additional funding made available.	\$200	No
Moniteau	Var	5T0021	2005	Install active warning devices at Hughs Road (DOT# 442 244E) UP near Centertown. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$144	No
Moniteau	Var	5T0022	2005	Upgrade active warning devices at East Railroad (DOT# 442 243X) UP near McGirk. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$144	No
Moniteau	Var	5T0024	2005	Upgrade active warning devices at East Street (DOT# 442 215U) UP in California. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Moniteau	Var	5T0025	2005	Upgrade active warning devices at Rte. 87/South Oak Street (DOT# 442 212Y) UP in California. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$8	No
Moniteau	Var	5T0026	2005	Upgrade active warning devices at Williams Street (DOT# 442 211S) UP in California. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Moniteau	Var	5T0027	2005	Upgrade active warning devices at Locust Street (DOT# 442 202T) UP in Clarksburg. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Moniteau	Var	5T0029	2005	Upgrade active warning devices at Round Hill Road (DOT# 442 192P) UP near Tipton. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No
Moniteau	Var	5T0030	2005	Upgrade active warning devices at Auglaize Avenue (DOT# 442 191H) UP in Tipton. Project No. RRP-000S(199). Reason(s): The project was added due to additional funding made available.	\$4	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Franklin	Var	6T0015	2005	Install active warning devices at Kingsland Avenue (DOT# 922 527D) UP and close highway/rail crossings at Simmonds Avenue (DOT# 442 752U) UP, Front Street (DOT# 442 754H) UP, and Tiemann Road (DOT# 442 757D) UP in Washington. Reason(s): The project was added due to additional funding made available.	\$219	No
Jefferson	Var	6T0016	2005	Upgrade active warning devices at Mill Street (DOT# 663 884P) BNSF in Festus. Project No. RRP-000S(195). Reason(s): The project was added due to additional funding made available.	\$200	No
St Louis	Var	6T0014	2005	Install active warning devices at Schuetz Street (DOT # 596 304M) CMR near Maryland Heights. Project No. RRP-000S(191). Reason(s): The project was added due to additional funding made available.	\$200	No
Barry	Var	7T0021	2005	Close BNSF highway/rail crossings at Central Avenue (DOT # 676 367D) and Eisenhower Street (DOT #668 316H) and build grade separation at Eisenhower Street in Monett. Project No. RRP-000S(190) Reason(s): The project was added due to additional funding made available.	\$750	No
Barton	EE	7T0040	2005	Install active warning devices at Rte. EE (DOT# 443 204K) MNA near Lamar. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$175	No

RSMo 21.795.3(2)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Barton	Var	7T0041	2005	Install active warning devices at County Road (DOT# 443 219A) MNA near Lamar. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$175	No
Bates	18	7T0036	2005	Upgrade active warning devices and install concrete crossing surface at Rte. 18 /Main Street (DOT#443 047U)MNA and close the MNA highway/rail crossing locations at 3rd Street (DOT# 443 048B), 6th Street DOT #443 045F), and 7th Street (DOT# 443 044Y in Adrian. Reason(s): The project was added due to additional funding made available.	\$202	No
Bates	Var	7T0037	2005	Install active warning devices and concrete crossing surface at 5th Street (DOT# 443 046M)MNA in Adrian. Project No. RRP-000S(171). Reason(s): The project was added due to additional funding made available.	\$144	No
Bates	Var	7T0038	2005	Install active warning devices and concrete crossing surface at 8th Street (DOT# 443 043S) MNA in Adrian. Project No. RRP-000S(171). Reason(s): The project was added due to additional funding made available.	\$200	No
Bates	Var	7T0042	2005	Install active warning devices at NW 16002 (DOT# 329 866A) KCS near Drexel Project No. RRP-000S(200) Reason(s): The project was added due to additional funding made available.	\$144	No

RSMo 21.795.3(2)

(Dollars in Thousands)

County	Route	Job Number	Current SFY	Description of Improvement / Location	Estimate	'92 Plan
Lawrence	Var	7T0039	2005	Install active warning devices at County Road 2185 (DOT # 435 117) MNA near Aurora. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$175	No
Taney	Var	8T0012	2005	Upgrade active warning devices at Main Street (DOT# 435 028U) MNA in Branson. Project No. RRP-000S(196). Reason(s): The project was added due to additional funding made available.	\$300	No
Texas	Var	9T0013	2005	Install active warning devices at County Road 593/Cannady (DOT# 667 722B) BNSF near Cabool. Project No RRP-000S(195). Reason(s): The project was added due to additional funding made available.	\$175	No

Count of Projects: 78 \$8,274

Estimate: This field contains the current estimate for the project consisting of CN-EST + CN_ENGTOT (CONTIG+ENG) +RW_EST + PRE_ENG+ UTILITIES + NONCONTR.

T:\Planning\OTPM\Reports\Accountabiliy\2004\Projects Added to 2005-2009 STIP.mdb

Query: qry Projects Added 2005-2009 STIP - 7-2004; Report: Rpt Projects added to 2005-2009

Tables: Alljobtn.dbf (parent); 2004prog.dbf; reasons.dbf

Criteria: Adv_Const <>'P' (Payback); AlljobtnSFY = Between SFY 2004 and 2008 and is null or >2008 in 2004PROG SFY