



From: [Debra M. Beckwith](#)
To: [BR](#)
Subject: Bridge Advertisement (DSI 22-024) Misc Field Welding Updates
Date: Monday, April 25, 2022 9:26:26 AM
Attachments: [image001.png](#)
[image002.png](#)

The EPG has been updated as described below:

Revision Date	Items Revised	Description of Change
 Apr. 2022	EPG:  712.1.4	EPG 712.1.4.1.1 - Removed MoDOT field welder cards information. Not done since 2013.
	Bridge Standard Drawings: NA	EPG 712.1.4.1.3 - Added language to match Sec 712.6.3 of the Spec Book. Also added clarification of thud sound for checking weld on a shear stud.
	MicroStation Cells: NA	
	Std. Specifications: NA	EPG 712.1.4.2 - Deleted last sentence. Welder certifications not maintained since 2013.
	Standard Plans: NA	
	Bridge Special Provisions: NA	

Follow links above for more information, or to view more details about this (or any) revision, use the [Revision Index Database](#), located under Completed Revisions on Development's Sharepoint page.

Instructions:

Under Tables (left-hand side) double-click on RevisionRecords.

Click on the link under the Effective Date to access documentation for the completed revision.

Debra M. (Debbie) Beckwith

Structural Specialist – Development Section

Missouri Department of Transportation

Central Office – Bridge Division

105 W. Capitol Ave., P.O. Box 270, Jefferson City, MO 65102

573-522-8718

www.modot.org