

From: [Debra M. Beckwith](#)
To: [BR](#)
Subject: Bridge Advertisement (DSI 21-011) Galvanizing sole plate
Date: Thursday, February 25, 2021 9:21:29 AM

The [EPG & Bridge Standard Drawings](#) have been updated as described below:

Implementation Statement: *Effective immediately for all plans not yet submitted to Design.*

(The Implementation Statement is a recommendation by the Development Section. The SPM is responsible for the level of implementation for any particular job.)

Revision Date	Items Revised	Description of Change
Feb. 2021	EPG: 751.50	Clarified sole plate and anchor bolt coating requirements when superstructure is galvanized. Added notes H3.29.2 & H3.49.2 and modified other H3 notes.
	Bridge Standard Drawings: BRG	
	MicroStation Cells: NA	
	Std. Specifications: NA	
	Standard Plans: NA	
	Bridge Special Provisions: NA	

Follow links above for more information, or to view more details about this (or any) revision, use the [Revision Index Database](#).

Instructions:

1. Select the Revision Index Database.
2. Select "Read Only" and Click "O.K."
3. Under Tables (left-hand side) double-click on Table1.
4. Scroll down to the bottom of the list to find the latest Revision.
5. Click on the link under the Effective Date to open the storage location for the Completed Revision.

DEBRA (DEBBIE) M. BECKWITH

Structural Specialist

Missouri Department of Transportation

Central Office – Bridge Division

105 W. Capitol Ave., P.O. Box 270, Jefferson City, MO 65102

573-522-8718

Mon. & Fri. 7:00 a.m. to 3:30 p.m.; Tues, Wed, Thur 6:30 a.m. to 3:00 p.m.

www.modot.org