

RFQ 9-160303KH-Q Generator Maintenance at 601 W Main and Lab

	Fabick	Cummins Mid-South
Lump Sum for testin, inspection and maintenance	\$ 7,985.00	\$ 6,528.28
Oil/Filter Change 601 W. Main	\$ 736.76	\$ 988.04
Oil/Filter Change at Lab	\$ 736.76	\$ 988.04
Air Filter Replacement 601 W. Main	\$ 174.34	\$ 439.96
Air Filter Replacement at Lab	\$ 174.34	\$ 439.96
Total	\$ 9,807.20	\$ 9,384.28

Award