

Missouri  
Department  
of Transportation



Ed Hassinger, District Engineer

St. Louis Metro District  
2309 Barrett Station Road  
Ballwin, Mo. 63021  
(314) 301-1439  
Fax (314) 301-1437  
or (573) 526-0016  
[www.modot.mo.gov](http://www.modot.mo.gov)  
Toll Free 1-888 ASK MoDOT

# QUOTATION TABULATION

General Services

Thank you for your response to our Request for Quotation **SL14-051-RW Pavement Marker Repair**

For your information, the following is a tabulation of all responses which were received.

If you have any questions, please contact me at the address/phone number shown above.

**Buyer:** Terri Mount Sr. Procurement Agent Posted 010/24/13 7:00 a.m.

QTY	U/M	DESCRIPTION (including size and/or part #'s)	TraMar Contracting	
			Unit cost	Extended Cost
560	Ea	Groove pavement and place 2 inlaid pavement makre bases with lenses	34.00	\$19,040.00
560	Ea	Remove and replace inlaid pavement marker bases with lenses	27.00	\$15,120.00
1	Lump sum	Temporary Traffic Control		\$37,020.00
		Total Extended Cost		\$71,180.00