

Bridges on I-44 ramps at Route 366 (Watson)



Water seeps through cracks and crevices, breaking down the concrete. In winter, chemicals placed on the road further deteriorates bridges.



Concrete along the bridges are cracking and crumbling.



Water seeps through cracks in the roadway above and deteriorates the foundations.



Concrete foundations are cracking and crumbling.



A picture of a rusty bridge support from the side.



The same bridge support as at the left, but head on.