Purpose and Need of Project: Improve Safety and Traffic Flow



Total Crashes in the last 5 Year Period

- 1 SERIOUS INJURY
- 7 MINOR INJURIES

BEFORE & AFTER

Crash Statistics Before & After Construction of a Roundabout

| MO 96 and N | | lorth d | of Joplin |
|---|--------------------|---------|--------------------|
| 5 Years Beto | re & 5 Years After | | CRASHES |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 2 | 0 | 100% |
| Serious Injury | 3 | 0 | 100% |
| Minor Injury | 6 | 1 | 83% |
| US 60 and MO 43 Seneca 5 Years Before & 5 Years After CRASHES | | | |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 0 | 0 | |
| Serious Injury | 3 | 0 | 100% |
| Minor Injury | 12 | 3 | 75% |
| US 160 and Jackson Street Willard 4 Years Before & 2 Years After CRASHES | | | |
| CRASH SEVERITY | BEFORE | AFTER | REDUCED BY: |
| Fatal | 0 | 0 | |
| Serious Injury | 1 | 0 | 100% |
| Minor Injury | 5 | 1 | 80% |